



YOUR HOME INSPECTION REPORT

521 E Rosebud Dr
San Tan Valley, AZ 85143

Chris Jumonville
JANUARY 13, 2020



Inspector

Joe Vallone

AZBTR #67612

(602) 999-5850

Office@homeinspectaz.com



Agent

Christina Cullen

My Home Group Real Estate

(602) 614-5770

chrisc@laughtonteam.com

TABLE OF CONTENTS

1: Inspection Details	6
2: Exterior	7
3: Foundation and Structure	17
4: Attic	19
5: Roof	24
6: Garage	28
7: Laundry	34
8: Fireplace	39
9: Kitchen	42
10: Indoor Environmental Issues	49
11: Hallways	50
12: Home Interior / Living Areas	52
13: Plumbing	58
14: Main Electrical Panel	66
15: HVAC / Heating & Cooling Systems	71
16: Bedrooms	79
17: Master or Main Bathroom	84
18: Hallway Bathroom	90
19: Stairs	95
20: Setting Reasonable Expectations	97
21: Report Conclusion	100
22: Pool/Spa - FSHI Evaluated	101
23: Half Bathroom	112
Standards of Practice	115

Home Inspection Full Report by First Step Home Inspectors.

The "First Step to buying or selling your home!"

SUMMARY



UNSATISFACTORY ITEM

Home Inspection Summary Report by First Step Home Inspectors.

The "First Step to buying or selling your home!"

- ⚠ 2.4.1 Exterior - Walkways: Offsets Noted
- ⚠ 2.10.1 Exterior - Exterior Windows: Loose Swiggle Seals
- ⚠ 2.11.1 Exterior - Screens: Screen Door / Missing
- ⚠ 2.15.1 Exterior - Fences & Gates: Fence / Cracking & Separation, Damaged and Leaning
- ⚠ 2.16.1 Exterior - Fascia / Trim / Soffits / Eaves: Moisture Staining Noted
- ⚠ 2.17.1 Exterior - Patio Floor / Patio Cover(s): Patio Floor
- ⚠ 4.6.1 Attic - Insulation: Attic Floor Insulation Minimal / Cellulose
- ⚠ 5.7.1 Roof - With Flat Roofed Sections: Roof Bubbles Noted
- ⚠ 5.8.1 Roof - Concrete Tile Roof: Cracked / Damaged Mortar Caps
- ⚠ 5.8.2 Roof - Concrete Tile Roof: Loose or Displaced Roof Tiles
- ⚠ 6.6.1 Garage - Garage Side Door: Rubs or Catches
- ⚠ 6.6.2 Garage - Garage Side Door: Damaged Door Sweep
- ⚠ 6.7.1 Garage - Garage Doors & Hardware: Vehicle Door Damage
- ⚠ 6.14.1 Garage - Lights / Wall Switches: Opener Light / No Response
- ⚠ 8.2.1 Fireplace - General Comments: Fireplace
- ⚠ 8.9.1 Fireplace - Log Starter: Pilot Light / Not Lit / Not Tested
- ⚠ 8.12.1 Fireplace - Screen / Glass Doors: Fireplace Glass / Fixed / Cloudy
- ⚠ 9.6.1 Kitchen - Range with Cooktop: Oven Element
- ⚠ 9.8.1 Kitchen - Sink and Faucet: Faucet / Hot And Cold Reverse
- ⚠ 11.10.1 Hallways - Smoke Detectors / CO: Missing
- ⚠ 12.6.1 Home Interior / Living Areas - Windows: Locks Need Adjustment

- ⚠ 13.2.1 Plumbing - City Water Meter: Buried Handle
- ⚠ 13.6.1 Plumbing - Gas Hot Water Heater: Insufficient Capacity
- ⚠ 13.8.1 Plumbing - Hose Bibs: Leaks During Use
- ⚠ 13.10.1 Plumbing - Irrigation: Leaking Valve/Fitting
- ⚠ 14.6.1 Main Electrical Panel - Wiring Observations: Double Tapped Wires / Noted
- ⚠ 16.5.1 Bedrooms - Windows: Window Frame Damage
- ⚠ 17.7.1 Master or Main Bathroom - Doors: Striker Plate Needs Adjustment
- ⚠ 17.8.1 Master or Main Bathroom - Flooring: Hollow Sounding Tiles
- ⚠ 17.8.2 Master or Main Bathroom - Flooring: Cracks / Floor Tiles or Grout Lines
- ⚠ 17.14.1 Master or Main Bathroom - Lights / Wall Switches: Ceiling Light / No Response
- ⚠ 17.16.1 Master or Main Bathroom - Exhaust Fan: Noisy
- ⚠ 18.4.1 Hallway Bathroom - Trap and Drain: Slow Drain
- ⚠ 18.8.1 Hallway Bathroom - Flooring: Cracked Floor Tiles
- ⚠ 18.8.2 Hallway Bathroom - Flooring: Hollow Sounding Tiles
- ⚠ 22.3.1 Pool/Spa - FSHI Evaluated - Pool Observations: Spa
- ⚠ 22.3.2 Pool/Spa - FSHI Evaluated - Pool Observations: Pool
- ⚠ 22.4.1 Pool/Spa - FSHI Evaluated - Enclosure Safety Observations: No Self Closing Feature
- ⚠ 22.5.1 Pool/Spa - FSHI Evaluated - Interior Finish: Cracks on Pool Steps
- ⚠ 22.5.2 Pool/Spa - FSHI Evaluated - Interior Finish: Cracks on Pool Interior
- ⚠ 22.6.1 Pool/Spa - FSHI Evaluated - Deck & Steps & Coping: Cracking Noted / Steps
- ⚠ 22.6.2 Pool/Spa - FSHI Evaluated - Deck & Steps & Coping: Deck Cracks Noted
- ⚠ 22.7.1 Pool/Spa - FSHI Evaluated - Tiles: Tiles Missing
- ⚠ 22.11.1 Pool/Spa - FSHI Evaluated - Spa/Hot Tub Filter: Pressure Gauge / Broken
- ⚠ 22.12.1 Pool/Spa - FSHI Evaluated - Skimmer & Cleaning System: Missing Diverter
- ⚠ 22.12.2 Pool/Spa - FSHI Evaluated - Skimmer & Cleaning System: Pop Ups Not Retracting
- ⚠ 22.12.3 Pool/Spa - FSHI Evaluated - Skimmer & Cleaning System: Missing Pool Floor Heads
- ⚠ 22.12.4 Pool/Spa - FSHI Evaluated - Skimmer & Cleaning System: Gears Not Rotating
- ⚠ 22.12.5 Pool/Spa - FSHI Evaluated - Skimmer & Cleaning System: Floor Sweep and Pop Ups Noted
- ⚠ 22.13.1 Pool/Spa - FSHI Evaluated - Supply & Return Lines Etc: Aerator Valve Handle / Damaged
- ⚠ 22.13.2 Pool/Spa - FSHI Evaluated - Supply & Return Lines Etc: Paint & Label PVC Pipes
- ⚠ 22.13.3 Pool/Spa - FSHI Evaluated - Supply & Return Lines Etc: Valve Handle Damaged
- ⚠ 22.13.4 Pool/Spa - FSHI Evaluated - Supply & Return Lines Etc: Valve
- ⚠ 22.15.1 Pool/Spa - FSHI Evaluated - Pool Pump and Motor: Motor or Pump / Does Not Respond
- ⚠ 22.15.2 Pool/Spa - FSHI Evaluated - Pool Pump and Motor: Pump/Motor Leaking
- ⚠ 22.15.3 Pool/Spa - FSHI Evaluated - Pool Pump and Motor: Noisy
- ⚠ 22.16.1 Pool/Spa - FSHI Evaluated - Electrical: Exposed Wire / Needs Conduit
- ⚠ 22.16.2 Pool/Spa - FSHI Evaluated - Electrical: Spa Display
- ⚠ 22.17.1 Pool/Spa - FSHI Evaluated - Pool Light: Pool Light / No Response
- ⚠ 22.17.2 Pool/Spa - FSHI Evaluated - Pool Light: Spa Light / No Response
- ⚠ 22.18.1 Pool/Spa - FSHI Evaluated - Heater: No TPR Valve on Heater
- ⚠ 23.4.1 Half Bathroom - Valves and Connectors: Half Bathroom

1: INSPECTION DETAILS

Information

Inspection Start Time (Approx) 8:00am	Inspection Finish Time (Approx) 11:30 am	Home Inspection Fee \$375.00
Budget Brothers Termite Inspection Fee \$55.00	Size of Property (Square Feet) 2347 Approximate square foot size of this property.	Year Built 2005 Approximate year of build for this property.
House / Building Faces North	Type of Building Single Family	Style Two Story
Utilities All Utilities Are On	Occupancy & Furnishings Occupied, Furnished	In Attendance Buyers Agent, Homeowner/Seller
Approx Temperature (Fahrenheit) 50-55	Weather Conditions Clear & Dry	

Occupied
The owners were at the residence upon arrival and were not aware of a Home Inspection.The Wife was sick and in the Master Bedroom during the inspection.The Master Bedroom and Bathroom inspection was limited.

2: EXTERIOR

Information

Exterior Lot Pictures: Front Yard Lot Pictures
Yard
Front Yard




Driveways: Type
Concrete

Exterior Lot Pictures: Courtyard
No Courtyard

Driveways: Satisfactory
The driveway is in satisfactory condition.



Walkways: Satisfactory
The walkway(s) are in satisfactory condition.



Walkways: Type
Concrete, Flagstone



House Wall Finish: Cladding Type
Stucco, Brick or Stone Veneer

Doorbell: Satisfactory
The doorbell is functional and works on demand.

Exterior Windows: Type
Double or Dual Pane

Lights: Exterior Lights
Exterior
Wall Lights
Exterior property lights.

Outlets / Electrical: Outlets / Type
Three Prong
Type of outlets noted.

Outlets / Electrical: GFCI / Reset Locations
Garage

Ceiling Fans: None Noted
There are not any exterior ceiling fans currently installed.


Fences & Gates: Fence / Satisfactory
The exterior yard fences are satisfactory.

Fences & Gates: Gates / Satisfactory
The property yard gates are functional and in satisfactory condition.

Fences & Gates: Fence Type
Concrete Block
Type of yard fencing in place on the property.

Fences & Gates: Gate Type
Steel Rail/Wood
Gate types on the property.

Patio Floor / Patio Cover(s): Patio Floors Satisfactory
The patio floor areas are in satisfactory condition.



Patio Floor / Patio Cover(s): Patio Cover(s) / Type
Front Patio Cover, Rear Patio Cover

General Info

This report is the exclusive property of First Step Home Inspectors and the client whose name appears herewith, and its use by any unauthorized persons is strictly prohibited.

The observations and opinions expressed in this report are those of First Step Home Inspectors and supersede any alleged verbal comments. We inspect all of the systems, components, and conditions described in accordance with the standards set forth and regulated by the Arizona Board of Technical Registratiion. Items we do not inspect are clearly disclaimed in the contract and/or in the aforementioned standards. However, some components that are inspected and found to be functional may not necessarily appear in the report, simply because we do not wish to waste our client's time by having them read an unnecessarily lengthy report about components that do not need to be serviced.

In accordance with the terms of the contract, the service recommendations made in this report should be completed by qualified specialists or contractors, well before you take possession of this property and within any specified contingency or inspection period. Qualified contractors may well identify additional defects or recommend some upgrades that could affect your evaluation of the property.

This report has been produced in accordance with our signed contract and is subject to the terms and conditions agreed upon therein. All printed comments and the opinions expressed herein are those of First Step Home Inspectors.

Scope of Work

You have contracted with First Step Home Inspectors to perform a generalist inspection in accordance with the standards of practice established by the Arizona Board of Technical registration. Generalist inspections are essentially visual, and distinct from those of specialists, inasmuch as they do not include the use of specialized instruments, the dismantling of equipment, or the sampling of air and inert materials. Consequently, a generalist inspection and the subsequent report will not be as comprehensive, nor as technically exhaustive, as that generated by specialists, and it is not intended to be. The purpose of a generalist inspection is to identify significant defects or adverse conditions that would warrant a specialist evaluation. Therefore, you should be aware of the limitations of this type of inspection, which is clearly indicated in the standards. However, the inspection is not intended to document the type of cosmetic deficiencies that would be apparent to the average person, and certainly not intended to identify insignificant deficiencies. Similarly, we do not inspect for vermin infestation, which is the responsibility of a licensed exterminator.

Most homes built after 1978, are generally assumed to be free of asbestos and many other common environmental contaminants. However, as a courtesy to our clients, we are including some well documented, and therefore public, information about several environmental contaminants that could be of concern to you and your family, all of which we do not have the expertise or the authority to evaluate, such as asbestos, radon, methane, formaldehyde, termites and other wood-destroying organisms, pests and rodents, molds, microbes, bacterial organisms, and electromagnetic radiation, to name some of the more commonplace ones. Nevertheless, we will attempt to alert you to any suspicious substances that would warrant evaluation by a specialist. However, health and safety, and environmental hygiene are deeply personal responsibilities, and you should make sure that you are familiar with any contaminant that could affect your home environment. You can learn more about contaminants that can affect your home from a booklet published by The Environmental Protection Agency, which you can read online at www.epa.gov/iaq/pubs/insidest.htm.

MOLD is one such contaminant. It is a microorganism that has tiny seeds, or spores, that are spread in the air then land and feed on organic matter. It has been in existence throughout human history and actually contributes to the life process. It takes many different forms, many of them benign, like mildew. Some characterized as allergens are relatively benign but can provoke allergic reactions among sensitive people, and others characterized as pathogens can have adverse health effects on large segments of the population, such as the very young, the elderly, and people with suppressed immune systems. However, there are less common molds that are called toxins that represent a serious health threat. All molds flourish in the presence of moisture, and we make a concerted effort to look for any evidence of it wherever there could be a water source, including that from condensation. Interestingly, the molds that commonly appear on ceramic tiles in bathrooms do not usually constitute a health threat, but they should be removed. However, some visibly similar molds that form on cellulose materials, such as on drywall, plaster, and wood, are potentially toxigenic. If mold is to be found anywhere within a home, it will likely be in the area of tubs, showers, toilets, sinks, water heaters, evaporator coils, inside attics with unvented bathroom exhaust fans, and return-air compartments that draw outside air, all of which are areas that we inspect very conscientiously. Nevertheless, mold can appear as though spontaneously at any time, so you should be prepared to monitor your home, and particularly those areas that we identified. Naturally, it is equally important to maintain clean air-supply ducts and to change filters as soon as they become soiled because contaminated ducts are a common breeding ground for dust mites, rust, and other contaminants. Regardless, although some mold-like substances may be visually identified, the specific identification of molds can only be determined by specialists and laboratory analysis and is absolutely beyond the scope of our inspection. Nonetheless, as a prudent investment in environmental hygiene, we categorically recommend that you have your home tested for the presence of any such contaminants, and particularly if you or any member of your family suffers from allergies or asthma. Also, you can learn more about mold from an Environmental Protection Agency document entitled "A Brief Guide to Mold, Moisture, and Your Home," by visiting their website at: <http://www.epa.gov/iaq/molds/moldguide.html/>, from which it can be downloaded.

ASBESTOS is a notorious contaminant that could be present in any home built before 1978. It is a naturally occurring mineral fiber that was first used by the Greek and Romans in the first century, and it has been widely used throughout the modern world in a variety of thermal insulators, including those in the form of paper wraps, bats, blocks, and blankets. However, it can also be found in a wide variety of other products too numerous to mention, including duct insulation and acoustical materials, plasters, siding, floor tiles, heat vents, and roofing products. Although perhaps recognized as being present in some documented forms, asbestos can only be specifically identified by laboratory analysis. The most common asbestos fiber that exists in residential products is chrysotile, which belongs to the serpentine or white-asbestos group, and was used in the clutches and brake shoes of automobiles for many years. However, a single asbestos fiber is said to be able to cause cancer and is, therefore, a potential health threat and a litigious issue. Significantly, asbestos fibers are only dangerous when they are released into the air and inhaled, and for this reason authorities such as the Environmental Protection Agency [EPA] and the Consumer Product Safety Commission [CPSC] distinguish between asbestos that is in good condition, or non-friable, and that which is in poor condition, or friable, which means that its fibers could be easily crumbled and become airborne. However, we are not specialists and, regardless of the condition of any real or suspected asbestos-containing material [ACM], we would not endorse it and recommend having it evaluated by a specialist.

POPCORN CEILING - In early formulations, it often contained white asbestos fibers. When asbestos was banned in ceiling treatments by the Clean Air Act of 1978 in the United States,[1] popcorn ceilings fell out of favor in much of the country. However, in order to minimize economic hardship to suppliers and installers, existing inventories of asbestos-

bearing texturing materials were exempt from the ban, so it is possible to find asbestos in popcorn ceilings that were applied through the 1980s. According to the EPA, the use of asbestos in textured ceiling paint was banned in 1977. Inhaled in large quantities, asbestos fibers can cause lung disease, scarring of the lungs and lung cancer. However, not all popcorn ceilings contain asbestos. Moreover, if left undisturbed or contained, asbestos is not dangerous.

RADON is a gas that results from the natural decay of radioactive materials in the soil and is purported to be the second leading cause of lung cancer in the United States. The gas is able to enter homes through the voids around pipes in concrete floors or through the floorboards of poorly ventilated crawlspaces, and particularly when the ground is wet and the gas cannot easily escape through the soil and be dispersed into the atmosphere. However, it cannot be detected by the senses, and its existence can only be determined by sophisticated instruments and laboratory analysis, which is completely beyond the scope of our service. However, you can learn more about radon and other environmental contaminants and their effects on health, by contacting the Environmental Protection Agency (EPA), at www.epa.gov/radon/images/hmbuygud.pdf, and it would be prudent for you to inquire about any high radon readings that might be prevalent in the general area surrounding your home.

LEAD poses an equally serious health threat. In the 1920's, it was commonly found in many plumbing systems. In fact, the word "plumbing" is derived from the Latin word "plumbum," which means lead. When in use as a component of a waste system, it is not an immediate health threat, but as a component of potable water pipes, it is a definite health hazard. Although rarely found in modern use, the lead could be present in any home build as recently as the nineteen forties. For instance, lead was an active ingredient in many household paints, which can be released in the process of sanding, and even be ingested by small children and animals chewing on painted surfaces. Fortunately, the lead in painted surfaces can be detected by industrial hygienists using sophisticated instruments, but testing for it is not cheap. There are other environmental contaminants, some of which we have already mentioned, and others that may be relatively benign. However, we are not environmental hygienists, and as we stated earlier we disclaim any responsibility for testing or establishing the presence of any environmental contaminant, and recommend that you schedule whatever specialist inspections that may deem prudent within the contingency period.

CRACKS AND WINDOWS - Unsealed cracks around windows, doors, and thresholds can permit moisture intrusion, which is the principal cause of the deterioration of any surface. Unfortunately, the evidence of such intrusion may only be obvious when it is raining. We have discovered leaking windows while it was raining that may not have been apparent otherwise. Regardless, there are many styles of windows but only two basic types, single and dual-glazed. Dual-glazed windows are superior because they provide a thermal as well as an acoustical barrier. However, the hermetic seals on these windows can fail at any time, and cause condensation to form between the panes. Many environmental factors come into play when and if hermetic seals have failed and Unfortunately, it is not always apparent, which is why we disclaim an evaluation of hermetic seals or unnoticed fogging glass. Nevertheless, in accordance with industry standards, we test a representative number of unobstructed windows and ensure that at least one window in every bedroom is operable and facilitates an emergency exit.

FURTHERMORE, you are advised to seek two professional opinions and acquire estimates of repair as to any defects, comments, improvements or recommendations mentioned in this report. We recommend that the professional making any repairs inspect the property further in order to discover and repair related problems that were not identified in the report. We recommend that all repairs, corrections, and cost estimates be completed and documented prior to closing or purchasing the property. Feel free to hire other professionals to inspect the property prior to closing. Including HVAC professionals, electricians, engineers, window professionals roofers etc.

All conditions are reported as they existed at the time of the inspection. The information contained in this report may be unreliable beyond the date of the inspection due to changing conditions.

General Site Comments: General Property Comments

It is important to maintain a property, including painting or sealing walkways, decks, and other hard surfaces, and it is particularly important to keep the house walls sealed, which provide the only barrier against deterioration. Unsealed cracks around windows, doors, and thresholds can permit moisture intrusion, which is the principle cause of the deterioration of any surface. Unfortunately, the evidence of such intrusion may only be obvious when it is raining. We have discovered leaking windows while it was raining that may not have been apparent otherwise. Regardless, there are many styles of windows but only two basic types, single and dual-glazed. Dual-glazed windows are superior, because they provide a thermal as well as an acoustical barrier. However, the hermetic seals on these windows can fail at any time, and cause condensation to form between the panes. Unfortunately, this is not always apparent, which is why we disclaim an evaluation of hermetic seals. Nevertheless, in accordance with industry standards, we test a representative number of unobstructed windows, and ensure that at least one window in every bedroom is operable and facilitates an emergency exit.

Exterior Lot Pictures: Backyard Lot Pictures

Yard

Backyard



Driveways: Common Cracking Noted

There are a few cracks in the driveway which appear to be cosmetic but you may want to view for yourself and repair as you feel necessary.

Landscaping: Satisfactory

The property landscaping appears to be in satisfactory condition. However, you may wish to have it evaluated by a qualified landscape contractor for more information.

Landscaping: Not Evaluated

I do not fully evaluate landscaping, but some of the trees, plants, bushes or shrubs may need to be trimmed or pruned. Regular maintenance and watering of them is recommended and assumed as part of healthy and normal yard landscaping.

House Wall Finish: Typical Stucco Shrinkage Cracks

There are typical shrinkage type cracks observed in the stucco, which you should view for yourself. All cracks result from movement, and are structural in that respect, but the vast majority of them have only a cosmetic significance. Most people do not realize that structures move, but they do and sometimes more or less continuously. Therefore, stress, settlement or shrinkage type fractures can reappear after they have been repaired, and particularly if they have not been repaired correctly. I recommend that all exterior cracks and gaps, if present, are properly covered or sealed to help prevent possible moisture or pest intrusion. However, you may wish to have this confirmed by an appropriate specialist. Most stucco homes are recommended to be repainted about every 10 years or so.

Grading & Drainage: Grading Comments

Water can be destructive and foster conditions that are deleterious to health. For this reason, the ideal property will have soils that slope away from the residence and the interior floors will be several inches higher than the exterior grade. Also, the residence will have roof gutters and downspouts that discharge into area drains with catch basins that carry water away to hard surfaces. However, we cannot guarantee the condition of any subterranean drainage system, but if a property does not meet this ideal, or if any portion of the interior floor is below the exterior grade, we cannot endorse it and recommend that you consult with a grading and drainage contractor, even though there may not be any evidence of moisture intrusion. The sellers or occupants will obviously have a more intimate knowledge of the site than we could possibly hope to have during our limited visit, however we have confirmed moisture intrusion in residences when it was raining that would not have been apparent otherwise. Also, in conjunction with the cellulose material found in most modern homes, moisture can facilitate the growth of biological organisms that can compromise building materials and produce mold-like substances that can have an adverse affect on health.

Grading & Drainage: Moisture & Related Issues

Moisture intrusion is a perennial problem, with which you should be aware. It involves a host of interrelated factors, and can be unpredictable, intermittent, or constant. When moisture intrusion is not self evident, it can be inferred by musty odors, peeling paint or plaster, efflorescence, or salt crystal formations, rust on metal components, and wood rot. However, condensation and humidity can produce similar conditions if the temperature in an area is not maintained above the dew point. Regardless, if the interior floors of a residence are at the same elevation or lower than the exterior grade we could not rule out the potential for moisture intrusion and would not endorse any such areas. Nevertheless, if such conditions do exist, or if you or any member of your family suffers from allergies or asthma, you should schedule a specialist inspection as soon as possible.

Grading & Drainage: Interior-Exterior Elevations

There is an acceptable difference in elevation between the exterior grade and the interior floors that should ensure that moisture intrusion would not threaten the living space, but of course I cannot guarantee that.

Grading & Drainage: Flat & Level Pad

The residence is situated on a flat level pad, which would typically not need a geological evaluation. However, because we do not have the authority of a geologist you may wish to have a site evaluation, as you feel necessary.

Grading & Drainage: Drainage Swales Clear

The drainage swales are clear and clean and should be kept clean for the general maintenance of the property.


Exterior Doors: Door Locks / Satisfactory

The residence door locks were verified as satisfactory or functional. They work as intended, unless otherwise noted .

Exterior Doors: Front Door(s) / Satisfactory


Steel Panel

The front entrance door(s) are solid, security type doors. Also noted adequate weather stripping, thresholds, door sweeps and deadbolts. They function properly and are in acceptable condition, unless otherwise noted.

**Exterior Doors: Rear Door(s) / Satisfactory**

Sliding Glass Door(s)

The rear entrance door(s) are solid, security type doors. Also noted adequate weather stripping, thresholds, door sweeps and deadbolts as necessary. They function properly and are in acceptable condition, unless otherwise noted.



Exterior Windows: General Comments

Exterior Windows

The house or residence windows are in satisfactory condition from the exterior and from within the interior living areas, unless otherwise noted. This includes areas such as but is not limited to: bedrooms, bathrooms, living areas, kitchen, garage, guest quarters, hallways etc. In accordance with industry standards, I am not required to test every window in the house and particularly if the house is furnished. However, I do make a realistic attempt to do so in the best interest of my clients. Sometimes window location, window screens, furniture and other factors restrict window accessibility. I do test every unobstructed and accessible window in the living areas and in every bedroom or sleeping quarters to ensure at least one facilitates and emergency exit. Common window problems can include, but are not limited to: cracked or damaged glass, windows that do not operate as intended and broken hermetic seals. Any windows with broken hermetic seals can be very difficult to locate if the atmospheric conditions are not just right. The height of an emergency escape and rescue window opening should not be more than 44" inches above the floor and accessible by approximately 5.7 square feet of space or 20" x 24". If you desire more information about the windows in this property, I recommend asking the seller and/or consulting a qualified window professional.

NOTE: Provision 11.2 B of the Standards of Professional Practice for Arizona Home Inspectors does not apply to the area between panes of glass in multi-pane glazing assemblies as it relates to the presence or absence of moisture or condensation.

Exhaustive evaluation of the interior of multi-pane window assemblies is determined to be cosmetic and outside of the scope of a home inspection. Detection of problems related to the hermetic seal, interior coatings and gases that may or may not be present requires specific expertise. Additionally, the ability to determine the condition of the hermetic seal, interior coatings, and gases present within is highly dependent on climactic conditions, cleanliness of glazing, window screen and window covering obstructions.

Any comments we make regarding the integrity of the window seals in multi-pane windows is being made only as a courtesy to our clients based on the windows at the time of the inspection.

Exterior Windows: Tested / Functional

In accordance with industry standards, we are required to test a representative sample of windows. The windows tested were functional and worked properly, unless otherwise noted or specifically stated. However, we do test every unobstructed and accessible window in every living area and bedroom to determine if at least one facilitates an emergency exit or egress.

Exterior Windows: Seal Around Exterior Windows

I recommend monitoring the areas around your exterior windows and sealing as needed to help prevent possible moisture intrusion issues. Over time, small cracks and exposed areas will occur. For example, stucco can shrink and pull away from windows as it dries. Further evaluation is recommended from a qualified contractor for more detailed information and service is determined necessary.

Exterior Windows: Dual Pane Windows Comment

Multi-pane windows with broken hermetic seals can be very difficult to locate or identify at all times and weather conditions. Most commonly noted by slight fogging, moisture or discoloration between the panes of glass.

Sometimes the atmospheric conditions, temperature and daylight will prevent these broken seals from standing out or being noticeable. Due to this difficulty, I recommend you should have a qualified contractor further evaluate all the windows in this residence for more detailed information and before you take possession of this property.

Screens: Present

The window screens in place on the window exterior areas, during the inspection, appear to be in satisfactory condition overall. Minor or relatively insignificant screen damage was not noted or documented. Also, window screens are not entirely or thoroughly evaluated because they are often removed for aesthetic or staging reasons.

They are easily damaged and can be removed after our inspection, so I choose to disclaim them. We do not test any automatic or powered window shades, screens or shade systems.

Note: The window screens located on the exterior of the residence windows have made a clear evaluation of the window condition difficult. I recommend viewing these windows again for yourself, once the screens are removed. These screens can restrict findings such as broken hermetic seals, cracks and other window damage.

Lights: Exterior Lights / Satisfactory

Exterior

The exterior lights outside the doors of the residence and on the property were functional when tested. Any sensor or light sensitive fixture lights were not tested. All lights may not have been located and/or tested. Any service items needed will be noted.

Outlets / Electrical: GFCI Satisfactory

The ground fault circuit interrupter or GFCI outlets present were noted as functional at the time of inspection. Their approximate locations are noted. All GFCI reset locations may not have been located at the time of the inspection.

Fascia / Trim / Soffits / Eaves: Fascia/Trim/Soffit Etc

Exterior

Fascia, Soffit, Eaves, Trim

The exterior areas are in satisfactory condition as viewed during the inspection. Only minor and typical exterior weathering was viewed, unless otherwise specifically noted.

Patio Floor / Patio Cover(s): Patio Covers / Satisfactory

The exterior patio covers are in satisfactory condition, unless otherwise specifically noted.



Limitations

Exterior Windows

DIRTY

The residence windows are dirty or dusty on the interior and exterior glass panes. This makes evaluating the windows for broken hermetic seals more difficult. I recommend having the windows properly cleaned and further evaluated as you feel necessary.

Exterior Windows

UPPER WALL WINDOWS / HARD TO VIEW

The upper wall or higher wall residence windows are difficult to fully evaluate due to their location. I recommend further evaluation of these windows, from a qualified professional, as you feel necessary. Any obvious visible issues will be noted in this report.

Lights

PHOTO SENSOR LIGHTS / NOT TESTED

Any photocell sensor lights were not tested. You should ask the sellers to have these lights demonstrated as you feel necessary.

Lights


SOLAR YARD LIGHTS / NOT TESTED

Any solar yard lights were not tested as part of this inspection service.

Fences & Gates

GATE / PADLOCKED CLOSED

The yard gate(s) were padlocked closed during the inspection and could not be opened. I recommend you should view them once the locks are removed.



Observations

2.4.1 Walkways



Unsatisfactory Item

OFFSETS NOTED

There is an offset in a walkway that could prove to be a trip-hazard. I recommend using caution when walking in this area.

Recommendation

Contact a qualified professional.



2.10.1 Exterior Windows



Unsatisfactory Item

LOOSE SWIGGLE SEALS

There are windows within this residence with loose or "drooping" interior swiggle seals that need further evaluation. All windows with seal issues are not pictured. This issue is an indication that the window either has failed or may fail soon. I recommend at least monitoring these windows and/or requesting further evaluation of all residence windows from a qualified contractor for more detailed information and to determine if service is necessary.

Recommendation

Contact a qualified window repair/installation contractor.



2.11.1 Screens




Unsatisfactory Item

SCREEN DOOR / MISSING

A sliding screen door is missing on a sliding glass door. I recommend replacing as you feel necessary.

Recommendation

Contact a qualified professional.



2.15.1 Fences & Gates

FENCE / CRACKING & SEPARATION,DAMAGED AND LEANING

YARD

There are areas of obvious cracking or separation/lifting on the concrete block fence. The Pilaster is damaged and the fence appears to be leaning. This should be further evaluated by a qualified contractor and serviced if determined necessary.

Recommendation

Contact a qualified professional.



Unsatisfactory Item

2.16.1 Fascia / Trim / Soffits / Eaves

MOISTURE STAINING NOTED

EXTERIOR BACK PATIO SOFFITS

These are moisture stained areas that should all be identified and further evaluated by a qualified contractor for service as determined necessary. Service is important to help prevent further wear or deterioration. I recommend asking the seller for more information and/or having additional evaluation from a qualified contractor for more details.

Recommendation

Contact a qualified professional.



Unsatisfactory Item



2.17.1 Patio Floor / Patio Cover(s)

PATIO FLOOR

There is areas where the stucco is peeling off the patio floor. Recommend Service as you feel necessary by a qualified

Recommendation

Contact a qualified professional.



Unsatisfactory Item

3: FOUNDATION AND STRUCTURE

Information

Slab Foundation: Material/Type Concrete Slab-On-Grade, Stem Wall	Columns / Supports: Columns and Supports / Type Stucco & Wood	Wall Structure: Identification / Type The walls are conventionally framed with wooden studs
Floor Structure: Identification / Type Poured Concrete Slab, The upper residence floors likely include conventional / engineered lumber sheathed in plywood or oriented strand board (OSB) Upper residence floors likely contain this material.	Roof / Ceiling Structure: Identification / Type Prefabricated truss system	

Various Hard Surfaces: Satisfactory

The visible portions of the hard surfaces are in acceptable condition, unless otherwise specifically noted.

Various Hard Surfaces: Common Settlement Cracking Noted

There are common settling, or curing, cracks in the hard surfaces. This is somewhat predictable, and is typically not regarded as being structurally significant, but I am not a specialist and you may wish to have this confirmed by one.

Slab Foundation: General Comments

This residence has a slab foundation. Such foundations vary considerably from older ones that have no moisture barrier under them and no reinforcing steel within them to newer ones that have both. Our inspection of slab foundations conforms to industry standards, which is that of a generalist and not a specialist. We check the visible portion of the stem walls on the outside for any evidence of significant cracks or structural deformation, but we do not move furniture or lift carpeting and padding to look for cracks or moisture penetration, and we do not use any of the specialized devices that are used to establish relative elevations and confirm differential movement. Significantly, many slabs are built or move out of level, but the average person may not become aware of this until there is a difference of more than one inch in twenty feet, which most authorities regard as being tolerable. Many slabs are found to contain cracks when the carpet and padding are removed, including some that contour the edge and can be quite wide. They typically result from shrinkage and usually have little structural significance. However, there is no absolute standard for evaluating cracks, and those that are less than 1/4" and which exhibit no significant vertical or horizontal displacement are generally not regarded as being significant. Although they typically do result from common shrinkage, they can also be caused by a deficient mixture of concrete, deterioration through time, seismic activity, adverse soil conditions, and poor drainage, and if they are not sealed they can allow moisture to enter a residence, and particularly if the residence is surcharged by a hill or even a slope, or if downspouts discharge adjacent to the slab. However, in the absence of any major defects, we may not recommend that you consult with a foundation contractor, a structural engineer, or a geologist, but this should not deter you from seeking the opinion of any such expert.

Slab Foundation: Satisfactory

The visible foundation areas show only the normal signs of weathering and/or cracking at the time of the inspection. These are considered satisfactory conditions. No significant damage was noted at this time, unless otherwise specifically noted.

Slab Foundation: Method of Evaluation

The slab foundation was evaluated on the exterior, by examining the stem walls that project above the footing at the base of the house walls. The interior portions of the slab, which is also known as the slab floor, have little structural significance and, inasmuch as they are covered and not visually accessible, it is beyond the scope of our inspection.

Slab Foundation: Bolted Slab / Acceptable

The residence appears to have a bolted slab foundation with no visible or significant abnormalities.

Columns / Supports: Satisfactory

The property columns and/or supports were noted to be in satisfactory condition at the time of the inspection. Unless otherwise specified.

**Wall Structure: Satisfactory**

The wall structure of this residence is in satisfactory condition, unless otherwise noted.

Floor Structure: Satisfactory

The floor structure is in satisfactory condition where visible, unless otherwise noted.

Roof / Ceiling Structure: Satisfactory

The roof and ceiling structure appears to be in satisfactory condition, unless otherwise noted.

4: ATTIC

Information

Attic Entry: Location Hallway	Roof Decking/Sheathing: Attic Decking / Sheathing Type Attic OSB - Oriented Strand Board Type of visible wood roof decking.	Insulation: Type Blown Loose Cellulose Type of attic insulation noted at the time of inspection.
Insulation: Installed Location Attic Floor The attic insulation is installed at the noted location(s).	Insulation: Insulation Depth 5-6 Inches Insulation depth noted during the inspection.	Ventilation: Type Noted Gable Vents, Soffit Vents The installed attic ventilation type is noted here.



Vapor Barrier: Vapor Barrier As Noted Visible Comments regarding the vapor barrier or vapor retarder.	Electrical: Attic Lights / Satisfactory The attic lights work on demand at the attic switch.
---	--



Attic Entry: General Comments

In accordance with our standards, we do not attempt to enter attics that have less than thirty-six inches of headroom, are restricted by ducts, or in which the insulation obscures the joists and thereby makes mobility hazardous, in which case we would inspect them as best we can from the access point. In regard to evaluating the type and amount of insulation on the attic floor, we use only generic terms and approximate measurements, and do not sample or test the material for specific identification. Also, we do not disturb or move any portion of it, and it may well and often does obscure water pipes, electrical conduits, junction boxes, exhaust fans, heating and cooling ducts and other components.

Method of Evaluation: Direct Access

The attic was evaluated by direct access to easily accessible areas, and viewed from easy vantage points.

Method of Evaluation: Limited Access / Framing Etc Restricts View

Insulation, HVAC ductwork/components and framing position within the attic obscures some of the framework and other items such as the vapor barrier/vapor retarder. Therefore, the attic inspection and its related components within is limited to what is visible.

Method of Evaluation: Limited Access / Vaulted Ceilings

Vaulted ceilings, framing position, insulation placement and HVAC ductwork within the attic obscures some of the framework. Therefore, the inspection of it and its components is limited to what is visible.

Common Observations: Limited Attic Access

The evaluation of the attic areas at this residence is limited to visible and readily or easily accessible locations only.

Framing: Framework Pictures**Framing: Factory Wood Truss / Satisfactory**

The wood roof framing is in satisfactory condition. The roof framing consists of a factory- built wood truss system, comprised of components called chords, webs, and struts that are connected by metal gussets nailed in place. Each component of the truss is designed for a specific purpose, and cannot be removed or modified without compromising the integrity of the entire truss. The lowest component, which is called the chord and to which the ceiling is attached, can move by thermal expansion and contraction and cause creaking sounds, which are more pronounced in the mornings and evenings along with temperature changes. Such movement has no structural significance, but can result in small cracks or divots in the drywall or plaster.

Roof Decking/Sheathing: Decking / Sheathing Pictures



Roof Decking/Sheathing: Satisfactory

The visible portions of the wood roof decking are in acceptable condition, unless otherwise specifically noted, and should conform to the standards of the year in which they were installed.

Insulation: Insulation Pictures



Ventilation: Satisfactory

The residence attic ventilation appears satisfactory. Contacting a qualified insulation contractor about having your attic ventilation upgraded could help lower energy costs by cooling down your attic during the warmer summer months.

Vapor Barrier: Visible

As Noted

There is black tar paper or other paper/material visible at the gable ends. It appears to be in good condition where viewed. Most of the building paper is covered and is not clearly visible, which limits a full evaluation.

Water Pipes: Visible Attic Water Supply Pipes

Attic

None Visible

Visible type of water supply plumbing visible in the attic during the inspection.

Water Pipes: None Visible

Any attic water pipes were not visible during the inspection. They may be obscured or hidden from view behind insulation, framework, ductwork etc.

Heat Vents: Satisfactory

The visible heat vents that pass through the attic are functional and appear satisfactory, unless otherwise specifically noted.



Plumbing Vents: Drainpipe Vents / Satisfactory

The visible plumbing drainpipe vents appear to be in satisfactory condition, unless otherwise specifically noted.



Exhaust Ducts: Satisfactory

The visible portions of the exhaust ducts appear to be functional, unless otherwise noted.



Observations

4.6.1 Insulation

ATTIC FLOOR INSULATION MINIMAL / CELLULOSE

ATTIC

The attic floor insulation was measured at only about 5-6 inches depth in various attic locations. The current recommended minimum for this type of floor insulation is 8-9 inches depth. I recommend adding more floor insulation to conserve energy and prevent heating and cooling loss. Further review and consultation from a qualified insulation contractor is recommended for service as necessary.



Unsatisfactory Item



Recommendation

Contact a qualified professional.

5: ROOF

Information

Method of Evaluation: Method Used Walking on its surface The residence roof and its components were evaluated in this manner.	Flashings: Type Metal Type of roof flashings noted during the inspection.	Drainage & Gutters: Gutter Type None Noted Type of gutters on this property.
With Flat Roofed Sections: Flat Roof Locations Flat Roof Rear Location(s) of flat roof areas.	With Flat Roofed Sections: Normal Wearing The flat patio composition rolled roof has signs of normal wearing.	
General Observations: Underlayment Comment Felt underlayment lasts approximately 15 to 30 years. If the home is more than 15 years old, or if there was any exposed underlayment, I recommend you should consult a qualified roofing contractor for more detailed information and to determine if service is necessary. I do not lift or move any roof tiles to view the underlayment.		
General Observations: No Guarantee Against Leaks This roof inspection is not a guarantee against leaks. For a guarantee, you would need to have a roofing company perform a water-test and issue a roof certification. Further evaluation from a qualified roofer is recommended as you feel necessary.		
Roof Age (approximate): Estimated Roof Age Original Roof Estimated roof age only. Please ask the seller for more detailed information or contact a qualified roofing contractor for evaluation.		

Roof Pictures: Main Roof Covering**Flashings: Satisfactory**

The roof flashings are in acceptable condition where viewed, unless otherwise specifically noted. They appear to consist of metal flashing around roof penetrations and in valleys.

Drainage & Gutters: Roof Drainage / Satisfactory

Roof drainage on this residence appears to be satisfactory, unless otherwise noted.

With Flat Roofed Sections: Roof Covering Type

Composition Rolled Roof

Type of covered patio roof(s) on the property.



Concrete Tile Roof: General Comments

Concrete tile roofs are among the most expensive and durable of all roofs, and are warranted by the manufacturer to last for forty years or more, but are usually only guaranteed against leaks by the installer from three to five years. Like other pitched roofs, they are not designed to be waterproof, only water resistant, and are dependant on the integrity of the waterproof membrane beneath them, which cannot be seen without removing the tiles, but which can be split by movement, deteriorated through time, or by ultra-violet contamination. Significantly, although there is some leeway in installation specifications, the type and quality of membranes that are installed can vary from one installer to another, and leaks do occur. The majority of leaks result when a roof has not been well maintained or kept clean, and we recommend servicing them annually.

Observations

5.7.1 With Flat Roofed Sections

ROOF BUBBLES NOTED

There are a few roof bubbles on the house flat roof and some soft decking. This could indicate moisture has gotten underneath the roof membrane. I recommend further evaluation from a qualified contractor for more detailed information and to determine the level of service necessary.

Recommendation

Contact a qualified professional.



Unsatisfactory Item



5.8.1 Concrete Tile Roof

CRACKED / DAMAGED MORTAR CAPS

I recommended having any cracked, separated, damaged, exposed or missing roof mortar caps evaluated and serviced as necessary, by a qualified contractor, or the roof could leak if moisture passes through these affected areas.

Recommendation

Contact a qualified roofing professional.



Unsatisfactory Item



5.8.2 Concrete Tile Roof

LOOSE OR DISPLACED ROOF TILES

Viewed out of place, loose or displaced roof tiles that should be evaluated and repaired or replaced as necessary by a qualified contractor. These issues should be repaired to help prevent wearing of the protective layer beneath the roof covering or possible moisture intrusion within the residence.

Recommendation


Contact a qualified roofing professional.

 Unsatisfactory Item



6: GARAGE

Information

<div>Walls and Ceiling: Type</div> <div>Drywall</div>	<div>Garage Side Door: Type</div> <div>Steel Panel</div>	<div>Garage Doors & Hardware: Type of Door</div> <div>Garage Sectional Type of garage door(s).</div>
		
<div>Garage Doors & Hardware: Seals</div> <div>Garage Satisfactory The garage door seals are in acceptable condition.</div>	<div>Garage Doors & Hardware: Hinges</div> <div>Garage Satisfactory The garage door(s) hinges are in acceptable condition.</div>	<div>Garage Doors & Hardware: Rollers</div> <div>Garage Satisfactory The garage rollers appear to be in acceptable condition.</div>
<div>Automatic Openers: Number of Openers</div> <div>Two Number of automatic garage door openers present during the inspection.</div>	<div>Windows: Type</div> <div>Garage None</div>	

Ventilation Ports: Satisfactory

The garage exterior wall ventilation ports are functional.



Outlets / Electrical: Outlets / Type

Three Prong
Type of outlets noted.

Outlets / Electrical: GFCI / Reset

Location
Garage
Location of GFCI reset.

Lights / Wall Switches: Wall Switches / Functional

The garage wall switches are functional and respond on demand.

Lights / Wall Switches: Type / Lights

Ceiling Lights
Type of lighting installed.

Lights / Wall Switches: Lights Satisfactory

The lights are in satisfactory condition, unless otherwise noted.

Picture Of Garage / Size: View

Three Car Garage
The garage and its components were evaluated.



Parking Space: Satisfactory

The parking space within the garage appears to be an adequate and typical size. However, I recommend you should check to be sure this garage size fits your vehicles and needs before you take possession of the property.



Parking Space: Cabinet or Shelves Restriction

Cabinets or shelves located in the garage will restrict the interior garage parking space somewhat. I recommend you should view this for yourself and determine if service is needed.

Slab Floor: Satisfactory

The visible garage slab floor areas are in satisfactory condition. Small floor cracks are common and often result as a consequence of the curing process or common settling, but are not considered to be structurally threatening.

Walls and Ceiling: Satisfactory

The visible garage walls and ceilings are in acceptable condition, unless otherwise noted.

Walls and Ceiling: Cosmetic Issues Noted

The walls and/or ceilings have typical and minor cosmetic damage such as: (scuffs, scrapes, nail holes etc) that you should view yourself and correct as desired.

Walls and Ceiling: Typical Settlement Cracking Noted

There are typical and minor settlement type cracking noted on some walls and ceilings.

Entry Door Into the House: Satisfactory

The garage to house entry door is a solid core door, or fire-rated type that self-closes in conformance with fire-safety regulations.



Garage Side Door: Satisfactory

The garage side door is a solid, security type door. Also noted adequate weather stripping, thresholds, door sweeps and deadbolts. It functions properly and is in acceptable condition, unless otherwise noted.

Garage Doors & Hardware: Vehicle Door(s)

Garage

Needs Service

The sectional garage door(s) and its hardware are functional and worked properly at the time of the inspection.

Automatic Openers: Picture



Automatic Openers: Satisfactory / Two

The automatic garage door openers are functional and will reverse when obstructed at the safety lights and when met with reasonable resistance during closing.

Cabinets/Drawers/Shelves: Type Noted

Garage

Cabinets

Type of cabinets, drawers, shelves etc as noted.



Cabinets/Drawers/Shelves: Satisfactory Comment

The installed and accessible cabinets, drawers, shelves and countertop etc are in satisfactory condition; as applicable.

Firewall Separation: Satisfactory


The entire garage firewall separating the garage from the residence appears functional and in good condition.

Limitations

Slab Floor

OBSTRUCTED VIEW / STORAGE

The storage on the garage floor prevents a clear view of the entire slab. I recommend evaluating the floor yourself once the storage is removed.



Observations

6.6.1 Garage Side Door

RUBS OR CATCHES

GARAGE

The side garage door rubs or catches on the door frame or threshold. I recommend further evaluation from a qualified contractor for service as determined necessary.

Recommendation

Contact a qualified professional.



Unsatisfactory Item



6.6.2 Garage Side Door

DAMAGED DOOR SWEEP

The side garage door sweep is damaged or loose and needs to be serviced or replaced as necessary.

Recommendation

Contact a qualified handyman.



Unsatisfactory Item



6.7.1 Garage Doors & Hardware

VEHICLE DOOR DAMAGE

The single car garage vehicle door has an area of damage. The door exterior is creased or buckled on the bottom panel. Further evaluation is recommended from a garage door contractor for service as determined necessary.

Recommendation

Contact a qualified garage door contractor.



Unsatisfactory Item



6.14.1 Lights / Wall Switches

OPENER LIGHT / NO RESPONSE

GARAGE

The garage ceiling light(s), at the automatic garage door opener, do not respond and should be demonstrated or serviced as necessary. Maybe bad bulb(s)?

Recommendation

Contact a qualified professional.



Unsatisfactory Item



7: LAUNDRY

Information

Laundry Room / View: Location & Picture

Stand Alone Room
Location of laundry room.



Valves & Connectors: Type / Washing Machine Valves

Laundry Area
Ball Valves
Type of washing machine water supply valves.



Windows: Type

None

Lights / Wall Switches: Wall Switches / Functional

The wall switches are functional and respond on demand.

Lights / Wall Switches: Type / Lights

Ceiling Lights
Type of lighting installed.

Lights / Wall Switches: Lights / Satisfactory

The lights are in satisfactory condition, unless otherwise noted.

Outlets / Electrical: GFI Outlet Resets In

Garage
GFCI reset location.

Cabinets/Drawers/Shelves: Cabinets/Drawers/Shelves etc

Cabinets



Exhaust Fan: Functional

The laundry exhaust fan was functional and responds on demand.

Gas Valve & Connector: Gas Supply Line

Visible

**Dryer Vent: Dryer Vent Discharges**

Vents Up and Out

Location the dryer vent discharges to.

Washer & Dryer: Picture / Not Evaluated

Washing Machine, Dryer

Any washing machines and/or dryers present were not evaluated as part of this inspection service. We do not turn them on or test any cycles. We do not disconnect washing machines supply lines to check for leaking. We recommend evaluating these appliances yourself and/or having a qualified contractor further evaluate them as you feel necessary.

**Valves & Connectors: Washer / Connected / Satisfactory**

The washing machine valves and connectors appear functional but were not tested. No leaking was noted. However, because they are not in daily use they typically become stiff or frozen.

Valves & Connectors: Metal Braided Hose Recommendation

The water supply to washing machines is commonly left on, and the rubber hoses that are commonly used to supply water to them often become stressed and can leak or burst. For this reason we recommend replacing all washing machine rubber supply hoses with metal-braided ones that are more resilient.

Trap & Drain: Washing Machine Drain Line / Not Visible

The washing machine drain line appears satisfactory but is not visible because it's behind or within the wall. I was unable to evaluate it as part of this inspection.

Doors: Satisfactory

The door(s) in the laundry room are functional and in satisfactory condition, unless otherwise specifically noted.

Flooring: Satisfactory

The visible floor in the laundry room is in satisfactory condition unless otherwise specifically noted.

Walls and Ceiling: Satisfactory

The visible walls and ceilings in the laundry room are in acceptable condition, unless otherwise noted.

Walls and Ceiling: Cosmetic Issues Noted

The walls and/or ceilings have typical and minor cosmetic damage such as: (scuffs, scrapes, nail holes etc) that you should view yourself and correct as desired.

Outlets / Electrical: Outlets / Satisfactory

The outlets in the laundry are functional and grounded, unless otherwise noted.

220 Volt Receptacle: In Use / Power Verified

The 220 volt receptacle for the dryer is in use and power supply was verified at the outlet. I recommend you should evaluate this outlet style to be sure the dryer you plan on using here is compatible with it.

**Cabinets/Drawers/Shelves: Satisfactory Comment**


The installed cabinets, drawers, shelves, countertop etc are in satisfactory condition; as applicable.

Closet: Satisfactory

The laundry closet and interior closet space appear to be in satisfactory condition.


Gas Valve & Connector: Satisfactory / Capped

The laundry room gas supply connection is currently capped off. This line will need service before it can be used with a gas dryer. You should be aware of this.



Dryer Vent: Dryer Vent / Satisfactory

The visible dryer vent connection appears correct. NOTE: Faulty dryer vents have been responsible for thousands of fires, hundreds of injuries, and even deaths. The best vents are a smooth-walled metal type that travels a short distance; all other types should be regarded as suspect, and should be inspected bi-annually to ensure that they do not contain trapped lint or moisture. We do not evaluate the interior condition of dryer exhaust vents.



Limitations

Sink & Faucet

NONE NOTED

There is not a laundry sink.

Closet

STORAGE NOTED

The storage noted in the laundry room closet limits a clear view of all wall and floor areas. I recommend evaluating these areas once the storage is removed and before you take possession of the property.



Ceiling Fan

NONE NOTED

There is not a ceiling fan.

8: FIREPLACE

Information

Fireplace / Type: Pictures



Fireplace / Type: Fuel Type
Natural Gas

Fireplace / Type: Location
Living Room

Fireplace: Satisfactory

The fireplace interior area appears to be in satisfactory condition.

Chimney Walls: Satisfactory

The chimney walls appear to be in satisfactory condition.

Chimney Flashings: Satisfactory

The chimney flashings appear to be in acceptable condition.

Weather Cap-Spark Arrestor: Satisfactory

The chimney(s) have a functional weather cap/spark arrestor.

Ornamental Gas Log: Appears Functional

The ornamental gas fire log appears functional.

Damper: Gas / No Damper Needed

There is not a damper needed because this is a gas fireplace.



Screen / Glass Doors: Fireplace Screen or Door
Fixed Glass

Mantle: Satisfactory

The fireplace mantle is in satisfactory condition.

Hearth: Satisfactory

The hearth is in satisfactory condition.

Ash Box: None Noted

There is not an ash box located on the fireplace exterior.

Fireblock: Not Visible

I was unable to view or see a fireblock in the attic.

General Comments: Prefabricated Chimney Comments

There are a wide variety of pre-fabricated chimneys, which are generally constructed on-site with approved components. I perform a competent, generalist inspection of them, but I'm not a specialist. This inspection is limited to those areas that can be easily viewed without dismantling any components. I am not able to guarantee that the installed components are the ones made or designed for use with this fireplace. I recommend further evaluation of this fireplace, by a qualified contractor, for more detailed information and information as you feel necessary.

Crown or Termination Cap: Satisfactory

The crown appears to be in satisfactory condition. It is designed to seal the chimney wall and shed rainwater to prevent moisture from deteriorating the chimney.



Chimney Flue: Interior / Not Visible

A complete view of the chimney flue, specifically interior areas, is not possible. You should consider having it evaluated further by a qualified contractor for more detailed information before the fireplace is used.

Hearth: Not Necessary

A fire resistant hearth is not required because this is an enclosed natural gas fireplace. I recommend further evaluation from a qualified contractor for more detailed information or as you feel necessary.

Observations

8.2.1 General Comments

FIREPLACE




Unsatisfactory Item

The fireplace has some open grout joints and slight movement which is causing this that you may want to view to determine service as necessary.

Recommendation

Contact a qualified professional.



8.9.1 Log Starter


PILOT LIGHT / NOT LIT / NOT TESTED

Unsatisfactory Item

The fireplace is turned off and any pilot light is not lit. This fireplace could not be tested during the inspection. There is also an exposed switch within the control area. I recommend asking the sellers to have it lit and/or checked/demonstrated by a qualified contractor as you feel necessary.

Recommendation

Contact a qualified professional.



8.12.1 Screen / Glass Doors

FIREPLACE GLASS / FIXED / CLOUDY

Unsatisfactory Item

The fixed fireplace glass is cloudy, which makes it difficult to view the fireplace interior areas. I recommend further evaluation from a qualified contractor for service.

Recommendation

Contact a qualified professional.



9: KITCHEN

Information

Refrigerator: Picture



Refrigerator: Water Dispenser
Works on Demand

Refrigerator: Ice Maker
Works on Demand

Dishwasher: Picture



Garbage Disposal: Picture



Built in Microwave: Picture



Range with Cooktop: Picture



Exhaust Fan or Downdraft:
Picture



Exhaust Fan or Downdraft: Type
Exhaust Hood to Exterior,
Exhaust Hood Internal
Type of exhaust system.


Sink and Faucet: Picture / Water Flow

Picture of the functional water flow at the kitchen sink.



Valves and Connectors: Type

Pull Valve
Type of valve(s) visible.



Windows: Type

Double pane

Outlets / Electrical: GFI Outlet Reset Location

Kitchen

Sink and Faucet: Kitchen Sink And Faucet / Functional

The kitchen sink and faucet are functional.

Valves and Connectors: Refrigerator Water Line

Not Visible

Lights / Wall Switches: Wall Switches

The kitchen wall switches are satisfactory and work on demand.

Ceiling Fan: None Noted

There is not a kitchen ceiling fan installed.

Sink and Faucet: Hand Sprayer Satisfactory

The kitchen sink hand sprayer is functional and works on demand.




Flooring: Satisfactory

The kitchen floor is in satisfactory condition.

Lights / Wall Switches: Lights / Type

Ceiling Lights
Type of lights noted.

Picture of Kitchen: View**Refrigerator: Satisfactory / Temps Ok**

The refrigerator was functional and achieved acceptable temperatures. This is a limited courtesy inspection and you should ask the seller about its full operation. You should make sure to set your fridge at appropriate temperatures as needed. I do not know if this appliance is staying with the property or not. I recommend you should plug the refrigerator into its own dedicated outlet and not into a GFCI protected outlet.

**Refrigerator: Water Dispenser / Functional**

The refrigerator water supply dispenser was functional when tested during inspection.

Refrigerator: Ice Maker / Functional

The refrigerator ice maker was functional when tested during the inspection. Ice is visible in the freezer.

Dishwasher: Satisfactory

The dishwasher is functional, completes an entire cycle, drains properly and no leaking was noted during the inspection.

**Garbage Disposal: Satisfactory**

The garbage disposal was functional during the inspection. No leaking noted, unless otherwise indicated.

Built in Microwave: Satisfactory

The built in microwave was functional during the inspection, but I did not test it for leakage, which would require a specialized instrument. However, their power diminishes over time, and the specific measurement of the microwaves, as well as their containment within the unit, requires specialized instruments, which is beyond the scope of our service.

Range with Cooktop: Type

Gas Cooktop, Electric Range

**Range with Cooktop: Satisfactory**

The range and cooktop are functional and both bake and broil work on demand.

Sink and Faucet: Cosmetic Issues In Sink

There are minor cosmetic marks (scuffs, scrapes etc) in the kitchen sink that you should be aware of and fix if desired.

**Trap and Drain: Satisfactory**

The kitchen sink traps and drains are functional. No leaking was seen during the inspection, unless otherwise noted.

**Valves and Connectors: Valves / Satisfactory**

The kitchen valves and connectors below the sink appear functional. Valves were not turned, however no leaking was noted at the time of inspection. Valves are not in daily use and will inevitably become stiff or frozen/stuck and need service or replacement.

Valves and Connectors: Refrigerator Water Line / Satisfactory

The refrigerator water line appears to be in good condition and was not leaking during the inspection. I did not test it or try to run water through it.

RO System/Filtration System: Faucet / Functional

The reverse osmosis or filter water supply faucet at the sink was activated and water came out. This is a very limited courtesy check and not a full inspection of the reverse osmosis system which is beyond the scope of this home inspection. I recommended you should consult with a specialist on maintenance and water quality as these systems can fail at any time. Especially when they are not being used.



Countertop: Satisfactory

The visible areas of the kitchen countertop(s) are in satisfactory condition.

Countertop: Typical Wearing Noted

Kitchen

The kitchen countertop showed typical wear and tear that you should view for yourself and correct if desired.

Walls and Ceiling: Satisfactory

The kitchen walls and ceiling are textured drywall and in acceptable condition.

Walls and Ceiling: Cosmetic Issues Noted

The kitchen walls or ceiling have minor cosmetic damage (scuffs, scrapes, nail holes etc) that you should view yourself and correct as desired.

Flooring: Cosmetic Issues Noted

The kitchen floor has typical wear and tear or cosmetic issues. I recommend viewing them and servicing as you feel necessary.

Windows: Satisfactory

The kitchen window(s) are in satisfactory condition. Unless otherwise specifically noted.

Lights / Wall Switches: Lights / Satisfactory

The lighting in the kitchen area is satisfactory, unless specifically noted otherwise.

Outlets / Electrical: Outlets / GFCI Protection Noted

The kitchen has modern three prong, GFCI protected outlets that were functional during the home inspection.

Limitations

Doors

NONE NOTED

There is not a kitchen pantry closet.

Observations

9.6.1 Range with Cooktop



Unsatisfactory Item

OVEN ELEMENT

Part of the element on the lower oven does not Appear to Glow.Both elements on the upper oven appear to glow even when only Bake is selected.Recommend Service as you feel necessary.

Recommendation

Contact a qualified professional.



9.8.1 Sink and Faucet



Unsatisfactory Item

FAUCET / HOT AND COLD REVERSE

KITCHEN

The hot and cold water lines to the kitchen sink faucet are reversed and should be serviced as necessary. Hot water is on the right side and cold water is on the left side; this is opposite of the usual setup. I recommend correcting this issue to help prevent the possibility of a scalding type injury.

Recommendation

Contact a qualified professional.

10: INDOOR ENVIRONMENTAL ISSUES

Information

Environmental Observations: Air Quality Not Evaluated

I do not test for mold or measure indoor air quality, which the Consumer Product Safety Commission ranks fifth among potential contaminants. A person's health is a truly personal responsibility, and because I do not inspect for mold or test for other environmental contaminants I recommend that you should schedule an appropriate inspection by an environmental hygienist before you take possession of this property. This would be imperative if you or any member of your family suffers from allergies or asthma, and could require the sanitizing of air ducts and other concealed areas. Note: Mold cannot exist without moisture. Therefore, any moisture whatsoever, whether it be from inadequate grading and drainage, a leaking roof, window, or door, or moisture from a faulty exhaust vent, a condensate pipe, an evaporator coil, or a component of a plumbing system etc should be serviced immediately, or the potential for mold infestation will remain.

Environmental Observations: Insects and Other Pests

Vermin, insects and other pests such as: crickets, spiders, scorpions, pigeons, termites, mice/rats etc. are part of the natural habitat and they often invade homes. Many of these pests can get into a home through the smallest of areas that are likely not visible or very difficult to locate. Rats and mice have collapsible rib-cages and many pests can enter even the tiniest crevices. And it is not uncommon for pests to establish colonies within crawlspaces, attic, closets, and even inside walls, where they can breed and become a health threat. Therefore, it would be prudent to make sure that a home is rodent, insect and pest proof, and to monitor those areas that are not readily accessible. This inspection does not include an evaluation of any in wall, in ground or onsite pest control or prevention systems. You should also consult a qualified pest control service for an evaluation of the property if you are concerned or for more information. This is recommended to be completed before the close of escrow and before the residence is occupied, especially if you are concerned or desire more information

Environmental Observations: Domestic Animals

Domestic animals living within a residence can have an adverse affect on air quality etc. Their presence may require extensive cleaning of walls, floors, air ducts etc. You should evaluate this property regarding previous or current domestic animals and service as you feel necessary.

11: HALLWAYS

Information

Hallway Picture: View



Doors: None Noted

There are not any hallway doors.

Windows: Type

None

Windows: None Noted

There are not any windows located in the hallway areas.

Lights / Wall Switches: Wall Switches / Functional

The hallway wall switches are functional and respond on demand.

Lights / Wall Switches: Type / Lights

Ceiling Lights
Type of lighting installed.

Lights / Wall Switches: Lights / Satisfactory

The lighting is in satisfactory condition, unless otherwise noted.

Smoke Detectors / CO: Type

Smoke Detector
Type of smoke detector and/or carbon monoxide detector.

Flooring: Satisfactory

The floor in the hallway is in satisfactory condition unless otherwise specifically noted.

Walls and Ceiling: Satisfactory

The walls and ceilings in the hallway are in acceptable condition, unless otherwise noted.

Walls and Ceiling: Cosmetic Issues Noted

The walls and/or ceilings have typical and minor cosmetic damage such as: (scuffs, scrapes, nail holes etc) that you should view yourself and correct as desired.

Cabinets/Drawers/Shelves: Cabinets/Drawers/Shelves etc

Cabinets, Drawers

**Outlets / Electrical: Three Prong / Satisfactory**

The outlets in the hallway were functional and grounded, unless otherwise noted.

Smoke Detectors / CO: Smoke Detectors / In Place

There are smoke detectors in place within the hallways of the residence. They responded when tested, unless otherwise noted. NOTE: Smoke detectors should be tested monthly and can fail at any time. They should be replaced at least every ten years or if they fail to respond.

Limitations

Closet

NONE NOTED

There were not closets.

Smoke Detectors / CO

TOO HIGH

The hallway smoke detectors were not tested because they are too high on the the wall or ceiling and could not be easily reached.

Observations

11.10.1 Smoke Detectors / CO


MISSING

HALLWAY

A smoke detector is missing and should be replaced as a fire safety feature.



Recommendation

Contact a qualified handyman.



12: HOME INTERIOR / LIVING AREAS

Information

Living Space Room Pictures: Main Entry View	Windows: Windows / Type Double pane	Cabinets/Drawers/Shelves: Cabinets/Drawers/Shelves etc Cabinets, Countertop, Drawers
		
Lights / Wall Switches: Lights / Type Ceiling Lights Type of room lighting noted.	Outlets / Electrical: Outlets / Type Three Prong Type of outlets noted.	Smoke Detectors: Type Smoke Detector Type of smoke detector and/or carbon monoxide detector.

General Interior Comments: Furnished Residence

The residence is furnished which limits or restricts a thorough evaluation of all wall and floor areas, windows, electrical outlets etc. In accordance with industry standards, I only inspect those surfaces that are exposed and readily accessible. I do not move furniture, lift carpets, nor remove or rearrange items within closets and cabinets. I strongly suggest you should come back to look over the property, once everything is moved out and all personal items have been removed. This will help give you a better evaluation of the overall property condition.

General Interior Comments: Living Areas Disclaimer


Our inspection of living spaces includes the visually accessible areas of walls, floors, cabinets and closets, and includes the testing of a representative number of windows and doors, switches and outlets. However, we do not evaluate window treatments, or move furniture, lift carpets or rugs, empty closets or cabinets, and we do not comment on cosmetic deficiencies. We may not comment on the cracks that appear around windows and doors, or which follow the lines of framing members and the seams of drywall and plasterboard. These cracks are a consequence of movement, such as wood shrinkage, common settling and will often reappear if they are not correctly repaired. Such cracks can become the subject of disputes, and are therefore best evaluated by a specialist. Similarly, there are a number of environmental pollutants that we have already elaborated upon, the specific identification of which is beyond the scope of our service but which can become equally contentious. In addition, there are a host of lesser contaminants, such as that from moisture penetrating carpet-covered cracks in floor slabs, as well as odors from household pets and cigarette smoke that can permeate walls, carpets, heating and air conditioning ducts, and other porous surfaces, and which can be difficult to eradicate. However, the sense of smell adjusts rapidly, and the sensitivity to such odors is certainly not uniform. We recommend you should make this determination for yourself, and particularly if you or any member of your family suffers from allergies or asthma, and then schedule whatever remedial services may be deemed necessary before the close of escrow or before you take possession of this property.

General Interior Comments: Door Stops-General


Any missing door stops throughout the home should be repaired or installed as you feel necessary.

General Interior Comments: Smoke & CO Detectors Comment

I recommend monitoring, replacing or adding smoke and carbon monoxide detectors as necessary, throughout this property, for safety reasons. Especially is gas appliances are present. Many times these units become worn, damaged or simply too old an may not work as intended.

Living Space Room Pictures: Family Room View**Living Space Room Pictures: Living Room View**

Living Space Room Pictures: Dining Room View



Doors: Satisfactory

The interior door(s) in the living areas are functional and in satisfactory condition, unless otherwise specifically noted.

Flooring: Satisfactory

The visible floors in the living areas are in satisfactory condition, unless otherwise specifically noted.

Walls and Ceiling: Satisfactory

The walls and ceilings in the livable areas are in acceptable condition, unless otherwise noted.

Walls and Ceiling: Cosmetic Issues Noted

The walls and/or ceilings have typical and minor cosmetic damage such as: (scuffs, scrapes, nail holes etc) that you should view yourself and correct as desired.

Walls and Ceiling: Settlement Cracking Noted

There are typical and minor settlement type cracking noted on some walls and ceilings in the livable spaces.



Windows: Satisfactory

The windows in the livable rooms are in satisfactory and functional condition, unless otherwise noted.

Screens / Shutters / Blinds: Screens Present

The window screens in place on the window exterior areas, during the inspection, appear to be in satisfactory condition overall. Minor or relatively insignificant screen damage was not noted or documented. Also, window screens are not entirely or thoroughly evaluated because they are often removed for aesthetic or staging reasons. They are easily damaged and can be removed after our inspection, so I choose to disclaim them.

Cabinets/Drawers/Shelves: Satisfactory Comment

The cabinets, drawers, shelves and countertop etc are in satisfactory condition; as applicable.

Closets: Satisfactory

The closets and interior closet space, in the livable areas of this property, appear to be in satisfactory condition.

Lights / Wall Switches: Wall Switches / Satisfactory

The wall switches in the livable areas are functional and respond on demand.

Lights / Wall Switches: Lights / Satisfactory


The lights in the livable rooms and areas are satisfactory, unless specifically noted otherwise.

Outlets / Electrical: Wall Outlets / Grounded / Satisfactory

The wall outlets in the livable areas were functional and grounded, unless otherwise noted.

Ceiling Fan: Satisfactory

The ceiling fan(s) within the livable areas work or respond properly on demand, unless otherwise noted.



Smoke Detectors: Older

The smoke detectors in this residence appear older and may be ready for replacement as a fire safety upgrade. The recommended life span for smoke detectors is approximately ten years. They are generally recommended to be replaced once they reach ten years old.

Limitations

Windows

ACCESS BLOCKED OR RESTRICTED

Some windows were blocked and could not be opened or properly evaluated from within the residence. I recommend you should evaluate these windows once access is possible.



Screens / Shutters / Blinds

BLINDS AND SHUTTERS COMMENT

NOTE: We do not test or evaluate blinds, shutters or any other similar type window or door treatments, throughout this property. They were not evaluated as part of this inspection service. They are only briefly viewed for access to evaluate windows behind them, regardless if they are temporary or permanent. They also can restrict a clear view of window areas and are only operated so I can access any related windows or doors. I recommend you should view them and determine if you want them serviced as you feel necessary.



Screens / Shutters / Blinds


SCREENS RESTRICT VIEWING

The window screens located on the exterior of the residence windows have made a clear evaluation of the window condition difficult. I recommend viewing these windows again for yourself, once the screens are removed. These screens can restrict findings such as broken hermetic seals, cracks and other window damage.

Closets

STORAGE NOTED

There is storage noted in the closets. This restricts a clear view of the interior areas.



Smoke Detectors

TOO HIGH TO TEST

Some of the smoke detectors in the livable areas of this residence are too high up on the wall or ceiling to test. I recommend you should have them tested as you feel necessary.

Observations

12.6.1 Windows

LOCKS NEED ADJUSTMENT



Some window locks need service to latch closed or work properly to hold the window securely closed. They barely contact the window frame. I recommend further evaluation from the builder to determine the level of service necessary.

Recommendation

Contact a qualified professional.



13: PLUMBING

Information

City Water Meter: City Water Meter-Picture




City Water Meter: City Water Meter Location

Front

Location of the city water meter.

House Water Shut-Off Valve / Supply: Picture

Picture of the main house water shut-off valve.



House Water Shut-Off Valve / Supply: Valve Type

Ball Valve

Type of main water supply shut-off valve located at the property.

Water Supply Pressure: Water Supply Pressure / Picture

70 psi



Water Supply Pressure: Water Pressure Regulator / As Noted

NONE / No Water Pressure Regulator Noted

General Gas Components: Picture

Picture of gas main/meter.



General Gas Components: Main Observations

Gas was on

The gas main/meter supply is either on or off as noted.

General Gas Components: Main Shut-off Location

Front Yard

Gas Hot Water Heater: Location Garage Garage	Gas Hot Water Heater: Year Built 2005	Gas Hot Water Heater: Capacity / Gallons 40
Gas Hot Water Heater: Fuel Source Type Natural Gas	Gas Hot Water Heater: Thermal Expansion Tank None	Supply Plumbing Type Polyethylene Supply plumbing type as noted.
Pipe Insulation / Supports: Water Supply Line Supports Not Visible Water supply piping supports viewed as noted.	Hose Bibs: Type NONE / Anti-Siphon Valves Not Noted	Waste and Drainage Systems: Clean Out Location / Picture Front Yard Location of the plumbing drain clean outs.
Waste and Drainage Systems: Type Of Material ABS / Acrylonitrile Butadiene Styrene	Irrigation: Type / Pictures Drip System, Not Tested - Occupied House Pictures of irrigation valves and related components.	



Standard Plumbing Comments: Drain Line Comment

NOTE: The underground sewer and/or drain lines were NOT video scanned or otherwise visually evaluated as part of this home inspection service. Underground pipes and pipes within walls, floors and ceilings are considered outside the scope of a home inspection. These drain lines were only tested for functional drainage by running water in sinks, tubs, showers and toilets etc. It is very common and typical for property drain lines to have tree and plant roots in them or to become cracked, settled or otherwise damaged over time. They can also be previously damaged but not noticed as part of a typical home inspection. These drain pipes can also consist of older material that is no longer in use (cast iron, Orangeburg, clay etc). Further evaluation of these drain lines is highly recommended by contacting a qualified contractor or plumber who can complete this for you, within the inspection period or at least before you close or take possession of the property.

City Water Meter: City Water Meter / Satisfactory

The street or city water meter was observed for a short while, while no water was running on the property. The meter or dial was not spinning or moving, or the digital display reads 0.00. This is a good indication of no water leaking underground between the water meter and residence. However, this is not an exact determination and further evaluation may be necessary if you desire more detailed information or are concerned about the possibility of an underground water leak. Following up with the water company is a good idea so you are aware of potential normal water usage at this residence. I recommend getting an emergency water or plumbers key from a hardware store in case of emergency so you can easy shut off this meter if needed.

House Water Shut-Off Valve / Supply: Valve Location

Front Wall

These valves appear to be in satisfactory and functional condition, unless noted otherwise.

Water Supply Pressure: Water Pressure / Satisfactory

The water pressure to the residence, and from the street, was within industry standards; usually between 40 and 80 psi and a water pressure regulator is not required on the water supply plumbing system at this pressure.

General Gas Components: Disclaimer

The inspector does not pressure test the gas pipe system. We recommend having the gas system evaluated and pressure tested if it is older than 20 years. Additionally, it is recommended to have the Gas Company inspect the gas system for any issues which are not normally part of a home inspection such as gas leaks. The gas company does a "code inspection" and this inspection focuses on functionality and obvious safety issues.

General Gas Components: Supply Pipes and Supports / Satisfactory

The visible portions of the gas pipes and their supports appear to be in acceptable condition.

Gas Hot Water Heater: Picture of Unit & Data Plate



Gas Hot Water Heater: Hot Water Temperature Noted

121 - 125

The residence hot water heater water temperature was noted as satisfactory during the home inspection. Hot water temperature supply was verified at all sinks, tubs, showers etc; unless otherwise noted. The hot water temperature is recommended to be set at a minimum of 110 degrees Fahrenheit to kill microbes and a maximum of 140 degrees Fahrenheit to prevent scalding. Hot water temperature can also be raised or lowered as desired at the water heater.



Gas Hot Water Heater: Manufacturer

Bradford White

I recommend flushing and servicing your water heater tank annually for optimal performance. Contacting a qualified contractor for more detailed information is also recommended, as you feel necessary.

Gas Hot Water Heater: Water Shut-Off Valve Condition

Satisfactory

The shut-off valve on a water heater should be functional and move freely and easily to turn off water supply if necessary.

**Gas Hot Water Heater: Water Connectors Condition**


Satisfactory

The water supply connectors on a water heater should be free of any mineral build up and have no signs of leaking.

**Gas Hot Water Heater: TPR Relief Valve & Discharge Pipe Condition**

Satisfactory

The water heater should be equipped with a mandated pressure-temperature relief valve and acceptable discharge pipe to the exterior.

**Gas Hot Water Heater: Drain Valve Condition**

Satisfactory

The drain valve is in place and presumed to be functional. I did not test it as part of this inspection service.

Gas Hot Water Heater: Gas Shut-Off Valve/Connector Condition

Satisfactory

The water heater gas control valve and its connector at the water heater were not moved but appear functional, unless noted otherwise.

**Gas Hot Water Heater: Gas Exhaust Vent Condition**

Satisfactory

The gas water heater vent/flue appears to be in good condition and is securely fastened in place. It meets proper clearances at the time of the inspection. Unless otherwise noted.

**Gas Hot Water Heater: Gas Water Heater Combustion Ventilation**

Satisfactory

Is there adequate combustion air ventilation for the gas water heater? Supply air vents in the garage, storage closet, etc.

Gas Hot Water Heater: Drain Pan & Discharge Pipe

Drain Pan Only

Water heaters are recommended to be equipped with a drain pan and discharge pipe to the exterior, which is designed to prevent water damage from a leak. Nevertheless, the water heater should be periodically monitored for any signs of a leak.

Satisfactory / Functional Flow

The water supply plumbing lines for this residence appear to be in satisfactory condition, where visible. Functional water flow was verified. Unless otherwise indicated.

Pipe Insulation / Supports: Attic Pipe Insulation

Attic

None Noted

The visible sections of the residence water supply piping in the attic appear to be insulated as noted.

Waste and Drainage Systems: General Comments / Sewer Lines & Drain Lines

I attempt to evaluate drain pipes by flushing every drain that has an active fixture while observing its draw and watching for blockages or slow drains, but this is not a conclusive test and only a video-scan of the main line by a qualified contractor would confirm its actual condition: (Note, we DO NOT provide this service). However, you can be sure that blockages will occur, usually relative in severity to the age of the system, and will range from minor ones in the branch lines, or at the traps beneath sinks, tubs, and showers, to major blockages in the main line. The minor ones are easily cleared, either by chemical means or by removing and cleaning the traps. However, if tree roots grow into the main drain that connects the house to the public sewer, repairs could become expensive and might include replacing the entire main line. For these reasons, we recommend that you ask the sellers if they have ever experienced any drainage problems, or you may wish to have the main waste line video-scanned before the close of escrow. Failing this, you should obtain an insurance policy that covers blockages and damage to the main line. However, most policies only cover plumbing repairs within the house, or the cost of roofer service, most of which are relatively inexpensive.

NOTE: The underground sewer or drain lines were not video scanned or otherwise visually evaluated as part of this home inspection service. They are considered outside the scope of a home inspection. These drain lines were tested for functional drainage by running water in sinks, tubs, showers and toilets only. If you require further evaluation of these drain lines, I recommend contacting a qualified contractor or plumber who can complete this for you.

Waste and Drainage Systems: Drainpipes / Functional Drainage Noted

Yard

Based on industry recommended water tests, the drainpipes are functional and acceptable at this time and functional drainage was noted. Bathtubs, showers sinks etc were drained during the inspection to check for drainage issues.

Waste and Drainage Systems: City Sewer System

This residence appears to be on the city sewer system. However, this was not verified as part of the inspection service. Only a video-scan of the main drainpipe, by a qualified contractor, could confirm its actual condition and if this is a sewer or septic system. This service is recommended within the inspection period and before you take possession of the property.

Irrigation: General Comments

Irrigation systems and their components are considered outside the scope of home inspections per the Arizona Standards of Professional Practice for Home Inspectors. However, we believe it is in the best interest of our clients to provide a brief overview of them and to test them as we feel necessary for basic operation. Please contact a qualified contractor for more detailed information before you take possession of the property and if you have any concerns with the irrigation system.

There are a wide variety of irrigation components, such as pipes that could include old galvanized ones, more dependable copper ones, and modern polyvinyl ones that are commonly referred to as PVC. The quality can range and it is not uncommon to find a mixture of them. To complicate matters, significant portions of these pipes cannot be examined because they are buried. Therefore, we identify a system based on what type of pipe that can be seen. This inspection only includes the visible portions of the system, and we do not test each component, nor search below vegetation for any concealed hose bibs, actuators, risers, or drip heads. Because the actuators are under pressure, we look for any evidence of damage or leakage, but recommend that you have the sellers demonstrate any automatic sprinkler system before the close of escrow and indicate any seasonal changes that they may make to the program. Further review from a qualified landscape professional may be required and is recommended for further review before the close of escrow.



Polyethylene Water Pipes: Satisfactory

The water supply plumbing visible within the residence appears to be in satisfactory condition, unless otherwise noted.

Polyethylene Water Pipes: Plumbing / Visible At

Sinks

This residence is served with Polyethylene plumbing, also known as PEX, potable water supply pipes. Functional water supply and flow was noted.

Observations

13.2.1 City Water Meter

BURIED HANDLE

Unsatisfactory Item

The main city water supply shut-off valve handle is currently buried and was not accessible during the inspection. I recommend having it located and properly uncovered so it can be evaluated before you take possession of the property. Service as necessary is recommended.

Recommendation

Contact a qualified professional.

13.6.1 Gas Hot Water Heater

INSUFFICIENT CAPACITY

Unsatisfactory Item

The water heater may not have the adequate capacity necessary to supply sufficient water to the home as needed. I recommend evaluating options to replace the water heater with a larger capacity tank as you feel necessary.

Recommendation

Contact a qualified plumbing contractor.

13.8.1 Hose Bibs

LEAKS DURING USE

Unsatisfactory Item

EXTERIOR FRONT

A hose bib slowly leaks at the handle while in use. I recommend having it evaluated by a qualified contractor and serviced as determined necessary.

Recommendation

Contact a qualified professional.

13.10.1 Irrigation

LEAKING VALVE/FITTING

Unsatisfactory Item

YARD

There are valves or fittings that are wet and leaking. They should be further evaluated and repaired or replaced as determined necessary by a qualified contractor.

Recommendation

Contact a qualified professional.



14: MAIN ELECTRICAL PANEL

Information

Panel Size & Location: Location on House
Left Side

Circuit Breakers: Type Noted
Main Panel
Breakers



Wiring Observations: Aluminum Wiring / Larger Circuits
Electrical Breaker Panel
None

Breakers with larger or thicker aluminum wiring noted.


Panel Cover Observations: Interior Cover / Acceptable
The interior panel cover is in acceptable condition.

Panel Size & Location: Picture / Manufacturer Label



Panel Size & Location: Manufacturer
General Electric (GE)

Service Conductor: Type
Copper Wire, Bus Bar
Type of service conductor material.




Panel Cover Observations: Panel Cover Type
Main Panel
Exterior Cover, Interior Cover

Main Panel Observations: Condition
Main Panel
Satisfactory

Service Conductor: Satisfactory Comment
The service conductor appears to be in satisfactory condition.

Panel Cover Observations: Exterior Cover / Acceptable
The exterior panel cover is in acceptable condition.



Panel Size & Location: Amperage

200 Amp; 120/240 Volt

Service size as noted per manufacturer label if visible. Specialized testing equipment was not used to verify this.

Main Panel Observations: Satisfactory Comment

The main electrical breaker panel and its components have no visible deficiencies.

Main Panel Observations: Low Voltage Components / Not Evaluated

Any low voltage components in this residence were not evaluated as part of the inspection. Such as low voltage components, wall jacks, wiring for speakers, cable, alarm systems, internet etc. I recommend contacting a qualified contractor for more detailed evaluation as you feel necessary.

Service Entrance: Service Entrance Type

Underground/Lateral

There are a wide variety of electrical systems with an even greater variety of components, and any one particular system may not conform to current standards or provide the same degree of service and safety. What is most significant about electrical systems however is that the national electrical code [NEC] is not retroactive, and therefore many residential systems do not comply with the latest safety standards. For example, many homes built during and before the 1970's may have aluminum wiring including in the house electrical system. Aluminum wiring during this time has been known to cause problems. Regardless, we are not electricians and in compliance with our standards of practice we only test a representative number of switches and outlets and do not perform load-calculations to determine if the supply meets the demand. It would be prudent to have a qualified electrician evaluate the entire electrical system in your home if it was built in or before the 1970's. However, in the interests of safety, we regard every electrical deficiency and recommended upgrade as a latent hazard that should be serviced as soon as possible, and that the entire system be evaluated and certified as safe by an electrician. Therefore, it is essential that any recommendations that we may make for service or upgrades should be completed before the close of escrow, because an electrician could reveal additional deficiencies or recommend some upgrades for which we would disclaim any further responsibility. However, we typically recommend upgrading outlets to have ground fault protection, which is a relatively inexpensive but essential safety feature. These outlets are often referred to as GFCI's, or ground fault circuit interrupters and, generally speaking, have been required in specific locations for more than thirty years, beginning with swimming pools and exterior outlets in 1971, and the list has been added to ever since: bathrooms in 1975, garages in 1978, spas and hot tubs in 1981, hydro tubs, massage equipment, boat houses, kitchens, and unfinished basements in 1987, crawlspaces in 1990, wet bars in 1993, and all kitchen countertop outlets with the exception of refrigerator and freezer outlets since 1996. Similarly, AFCI's or arc fault circuit interrupters, represent the very latest in circuit breaker technology, and have been required in all bedroom circuits since 2002. However, inasmuch as arc faults cause thousands of electrical fires and hundreds of deaths each year, we categorically recommend installing them at every circuit as a prudent safety feature.

**Service Entrance: Underground / Satisfactory**

The main conductor lines are underground or lateral service and in satisfactory condition. This is a characteristic of modern electrical services, but because the service lines are underground, and cannot be seen, they are not evaluated as part of this inspection service. I recommend contacting a qualified contractor for more detailed information or as you feel necessary.

Circuit Breakers: Breakers Satisfactory Comment

There are no visible deficiencies with the circuit breakers. Unless otherwise noted.

Circuit Breakers: System Includes Arc-Fault Breakers

This electrical system does include arc-fault circuit interrupters (AFCI) that are mandated by current standards. An AFCI is an electrical safety device installed in new home bedroom circuits, in many jurisdictions, for construction generally permitted after January 1, 2002. The AFCI breakers in place tested and reset on demand at the time of the inspection, however they can fail at anytime without warning. The AFCI's purpose is to prevent fires, which may occur due to faulty electrical appliances connected to a bedroom circuit. They are considered an essential safety feature of modern homes.




Circuit Breakers: Main Disconnect / Satisfactory

The main electrical breaker disconnect appears to be in satisfactory condition.



Wiring Observations: Visible Branch Wiring / Type / Picture

Copper

**Wiring Observations: Satisfactory Comment**

The visible electrical wiring appears to be in satisfactory condition, unless otherwise noted.

Grounding: Satisfactory Comment

The main panel grounding connection was observed and appears to be in satisfactory condition at the time of the inspection.

Grounding: Grounding Location

Main Hose Bib, Gas Main Meter

**Observations**

14.6.1 Wiring Observations

DOUBLE TAPPED WIRES / NOTED

ELECTRICAL BREAKER PANEL


There are double tapped wires (two wires in one connection) inside the breaker panel box. This makes it possible to overload the wires. This should be further evaluated by a qualified contractor for service as determined necessary.

Recommendation

Contact a qualified professional.





Unsatisfactory Item



15: HVAC / HEATING & COOLING SYSTEMS

Information

HVAC System Info: HVAC System / Type Gas Split System(s) Type of HVAC system(s) located onsite.	HVAC System Info: Number of HVAC Systems Onsite 1 Number of HVAC systems onsite during the inspection.	HVAC System Info: HVAC Component(s) Location Condensing Coil(s) Outside On Ground, Air Handler/Furnace(s) In Attic
HVAC System Info: HVAC System Locations Main Residence	Condensing Coils Age/Data: Satisfactory The condensing coil(s) respond to the thermostat and are functional.	Condensing Coils Age/Data: Year Built 2019
Condensing Coils Age/Data: Total Combined HVAC Tons Onsite 5.0 Tons	Condensing Coils Age/Data: HVAC Manufacturer / Brand York	Air Handler or Furnace / Age & Data: Picture and Data Plates (ALL)
		
Air Handler or Furnace / Age & Data: Year Built Unknown	Air Handler or Furnace / Age & Data: HVAC Manufacturer / Brand York	Fuel Source: Type Gas/Electric
Return-Air Compartment / Filter: Location Hallway Ceiling Location of the return air vents.	Heating Differential Temperature Readings: Air Return Temperatures - Acceptable Air return temperatures for this residence were noted as acceptable.	Heating Differential Temperature Readings: Air Supply Temperatures - Acceptable Air supply temperatures for this residence were noted as acceptable.
		

Thermostats: Location Hallway Thermostats were noted in these locations.	Condensing Coil Disconnect: Disconnect / Type Pull Out Type of disconnect noted.	Condensate Drainpipe: Drainpipes / Satisfactory The condensate drainpipes discharge correctly, as noted.
---	---	--



Condensate Drainpipe: Drains To: Outside Residence The condensate drain pipe(s) properly discharge at the noted location.	Registers: Satisfactory The air supply registers are functional and reasonably clean.	Registers: Location Wall, Ceiling HVAC air supply register locations.
---	---	--

HVAC Comments: General Comment

The components of most heating and air-conditioning systems have a design-life ranging from ten to twenty years, but can fail prematurely with poor maintenance, which is why we apprise you of their age whenever possible. We test and evaluate them in accordance with the standards of practice, which means that we do not dismantle and inspect the concealed portions of evaporator and condensing coils, the heat exchanger, which is also known as the firebox, electronic air-cleaners, humidifiers, ducts and in-line duct-motors or dampers. We perform a conscientious evaluation of both systems, but we are not specialists. However, even the most modern heating systems can produce carbon monoxide, which in a sealed or poorly ventilated room can result in sickness, debilitating injury, and even death. Therefore, in accordance with the terms of our contract, it is essential that any recommendations that we make for service or a second opinion be scheduled before the close of escrow, or within the inspection period if possible, because a specialist could reveal additional defects or recommend further upgrades that could affect your evaluation of the property, and our service does not include any form of warranty or guarantee. Having the heating and cooling system fully evaluated by a qualified HVAC contractor, especially before you take possession of this property, and at least annually is recommended, regardless of its condition, because we rely heavily on these systems during the warmer months and summer months in Arizona.



HVAC Comments: Cooling and Heating Verified in Each Room

Cooling and heating presence was verified as noted in each room of this residence, unless otherwise noted.

HVAC Comments: Further HVAC Review Is Recommended

Further review of the heating and cooling system is recommended from a qualified HVAC contractor for more detailed information, regardless of the HVAC system condition during the inspection. This further review is important because we rely on these units almost non-stop in the hot summer months and very often in the warmer months before and after the summer. It is also critical to have the entire HVAC system evaluated, before you take possession of the property, if it has not been used for an extended period of time (such as an unoccupied or vacant property) or if they appear to be in disrepair and in need of service. Review from a qualified HVAC contractor or HVAC specialist is recommended to overview the system and check it for possible repairs, service or upgrades that are beyond the scope of this generalist home inspection.

Condensing Coils Age/Data: Picture and Data Plates (ALL)



Air Handler or Furnace / Age & Data: Heat Exchanger (Gas Only) / Not Visible

The heat exchanger, which is often located in the combustion chamber of the gas furnace, was not visible given its location and due to the visible limitations of a home inspection. However, I recommend the combustion chamber and heat exchanger should be evaluated by a qualified HVAC contractor before you take possession of this property. If it is cracked, the furnace will have to be replaced for safety reasons.

Air Handler or Furnace / Age & Data: Satisfactory

The furnace(s)/air handler(s) were functional and respond when prompted at it's thermostat. I recommend further review from a qualified HVAC contractor for more information or a detailed evaluation, at least before you take possession of the property or as you feel necessary.

Fuel Source: Gas Heat / Electric Cooling

The fuel supply source onsite for the HVAC system(s) includes gas heat and electric cooling.

Refrigerant Type: Refrigerant Type

HVAC

R-410A

Type of refrigerant type as visible or as noted on the HVAC manufacturer label. Further evaluation may be necessary from a qualified contractor to accurately determine or verify this.

Age Observations: HVAC / Newer and Functional

The HVAC system(s) are newer. Such systems are designed to last approximately twenty years, but they should be serviced bi-annually and have their filters changed every two to three months.

Cooling Differential Temperature Readings: Air Return Temperatures / As Noted

Air Return

See Below, See Limitations

Air return temperatures in degrees Fahrenheit for this residence were as noted.

Cooling Differential Temperature Readings: Air Supply Temperatures / As Noted

Air Supply Registers

See Limitations, See Below

Air supply temperatures in degrees Fahrenheit for this residence were as noted.

Cooling Differential Temperature Readings: Cooling System Not Temp Tested

The HVAC cooling system(s) was not temperature tested as part of this inspection service. However, it does respond to its controls on demand. I recommend having it further evaluated by a qualified contractor HVAC contractor as you feel necessary or for more detailed information.

Heating Differential Temperature Readings: HVAC / Satisfactory Heating Comment

NOTE: The heating unit(s) respond on demand and achieve a satisfactory temperature split between the supply and return air. However, it would be prudent to have the unit serviced by a qualified HVAC contractor soon and preferably within the inspection period or at least before you take possession of the property. Especially if it hasn't been evaluated or serviced in the past twelve months. Requesting prior service history from the seller could help you determine this.

Heating Differential Temperature Readings: Air Return Temperatures / As Noted

Air Return

75

Air return temperatures in degrees Fahrenheit for this residence were as noted.



Heating Differential Temperature Readings: Air Supply Temperatures / As Noted

Air Supply Registers
116-120, 121-125

Air supply temperatures in degrees Fahrenheit for this residence were as noted.




Thermostats: Satisfactory

The thermostat(s) were functional and respond to their controls at the time of the inspection.

**Refrigerant Lines: Satisfactory**

The refrigerant lines are in acceptable condition and foam wrapped where viewed.

**Gas Automatic Safety Controls: Gas Safety Control Comments**

A thermocouple is a safety device on gas furnaces that shuts off the gas supply if the pilot light goes out or if the electric igniter fails.

A limit switch is a safety control located on the furnace. If specific components get too hot, the limit switch shuts off the burner. It also shuts off the blower when the temperature drops to a certain level after the burner has shut off.

Gas Automatic Safety Controls: Thermocouple and Limit Switch

The thermocouple and limit switch appear to be present and in satisfactory condition.

Gas Valve & Connector: Satisfactory

The gas valve(s) and connector(s) are in acceptable, visible condition. However the valves itself were not turned or operated.

**Gas Valve & Connector: No Drip Loop or Leg**

The flexible gas feed line(s) to the furnace(s) do not have a drip loop or drip leg installed to catch debris in the gas line. I recommend further evaluation from a qualified contractor for service as you feel necessary.

Gas Vent Pipe and Cap: Satisfactory

The gas furnace vent pipes and caps are in acceptable condition and should work as intended. As a reminder, I do not test for gas leaks or combustion by-product fume leaks such as carbon monoxide.

**Gas Combustion-Air Vents: Satisfactory**

The combustion-air vents appear to be adequate to support complete combustion.

Drip Pan: Satisfactory / One

The drip pan is acceptable. There was no moisture noted in the pan at the time of inspection.

**Condensate Drainpipe: Drainpipe / Satisfactory**

The condensate drainpipe discharges correctly, as noted.



Ducting: Type / Satisfactory**Flexible Ducting**

The visible HVAC ductwork appears to be in satisfactory condition, unless otherwise noted.



Limitations**HVAC Comments****AMBIENT TEMP BELOW 65 / DID NOT TEST AC**

The ambient temps were below 65 degrees. Testing the air conditioning could damage the unit, therefore I did not temperature test in the air conditioning system as part of this inspection. I did turn it on briefly to be sure it responds to its controls. Further detailed evaluation is recommended from a qualified HVAC contractor if you are concerned or desire more information.

Cooling Differential Temperature Readings**AC NOT TEMPERATURE TESTED**

The residence HVAC air conditioning systems were not temperature tested as part of this inspection; ambient temperature is too low. However the unit(s) do respond to their thermostats when prompted. I recommend further evaluation from a qualified contractor as you feel necessary.

Registers**PROFESSIONALLY CLEAN DUCTWORK**

You should consider having the ductwork professionally cleaned. As a reminder, we do not test the air quality as part of this inspection process.

16: BEDROOMS

Information

Windows: Type
Double pane

Windows: Emergency Egress
Bedrooms
Yes

Status of the
bedroom(s) emergency egress.

Lights / Wall Switches: Lights / Type
Ceiling Lights
Type of lights noted.


Outlets / Electrical: Type
Three Prong
Type of outlets noted.

View of Bedrooms: Master Bedroom View / Photos
View of the master bedroom.




View of Bedrooms: Guest Bedroom #1 View / Photos

View of a guest bedroom.


**View of Bedrooms: Guest Bedroom #2 View / Photos**

View of a guest bedroom.



View of Bedrooms: Guest Bedroom #3 View / Photos

View of a guest bedroom.



Doors: Satisfactory

The door(s) in the bedrooms are functional and in satisfactory condition, unless otherwise specifically noted.

Flooring: Satisfactory

The visible floors in the bedrooms are in satisfactory condition unless otherwise specifically noted.

Flooring: Squeaky Floors Noted

There are squeaky floor areas in some of the bedrooms. I recommend service as you feel necessary.

Walls and Ceiling: Satisfactory

The walls and ceilings in the bedrooms are in acceptable condition, unless otherwise noted.

Walls and Ceiling: Cosmetic Issues Noted

The walls and/or ceilings have typical and minor cosmetic damage such as: (scuffs, scrapes, nail holes etc) that you should view yourself and correct as desired.

Windows: Satisfactory

The windows in the bedrooms are in satisfactory and functional condition, unless otherwise noted.

Screens / Shutters / Blinds: Screens Present

The window screens in place on the window exterior areas, during the inspection, appear to be in satisfactory condition overall. Minor or relatively insignificant screen damage was not noted or documented. Also, window screens are not entirely or thoroughly evaluated because they are often removed for aesthetic or staging reasons. They are easily damaged and can be removed after our inspection, so I choose to disclaim them.

Closet: Satisfactory

The closets and interior closet space, in the bedrooms of this property, appear to be in satisfactory condition.

Ceiling Fans: Satisfactory

The ceiling fan(s) within the bedrooms work or respond properly on demand, unless otherwise noted.

Lights / Wall Switches: Wall Switches / Functional

The wall switches in the bedroom areas are functional and respond on demand.

Lights / Wall Switches: Lights / Satisfactory

The lights in the bedrooms are satisfactory and functional, unless noted otherwise.

Outlets / Electrical: Outlets / Satisfactory

The outlets in the bedrooms were functional and grounded, unless otherwise noted.

Smoke Detectors: In Place As Noted

There are smoke detectors in place within the bedrooms of the residence. They responded when tested, unless otherwise noted. NOTE: Smoke detectors should be tested monthly and can fail at any time. They should be replaced at least every ten years or if they fail to respond.

Limitations**Windows****ACCESS BLOCKED OR RESTRICTED**

Some windows were blocked and could not be opened or properly evaluated during the inspection. I recommend you should evaluate the windows as you feel necessary.



Screens / Shutters / Blinds**BLINDS AND SHUTTERS COMMENT**

NOTE: We do not test or evaluate blinds, shutters or any other similar type window treatments, throughout this property. They were not evaluated as part of this inspection service. They are only briefly viewed for access to evaluate windows behind them, regardless if they are temporary or permanent. They also can restrict a clear view of window areas and are only operated so I can access any related windows or doors. I recommend you should view them and determine if you want them serviced as you feel necessary.

Screens / Shutters / Blinds**WINDOW SCREENS RESTRICT VIEWING**

The window screens located on the exterior of the residence windows have made a clear evaluation of the window condition difficult. I recommend viewing these windows again for yourself, once the screens are removed. These screens can restrict findings such as broken hermetic seals, cracks and other window damage.

Smoke Detectors**NOT TESTED / TOO HIGH**

The bedroom smoke detectors are installed very high up on the wall or ceiling and could not be tested during the inspection. I recommend testing them before you move in or as you feel necessary.

Observations

16.5.1 Windows

WINDOW FRAME DAMAGE

BEDROOM

A bedroom window has a damaged frame. I recommend service as necessary from a qualified contractor to help prevent further damage.


Recommendation

Contact a qualified professional.




17: MASTER OR MAIN BATHROOM

Information

Bathroom: Size Full Bath	Toilet: Condition Flushes on Demand	Flooring: Type Tile
		
Windows: Type Dual Pane	Cabinets/Drawers/Shelves: Type Cabinets, Drawers	Lights / Wall Switches: Wall Switches / Functional The wall switches are functional and respond on demand.
Lights / Wall Switches: Type / Lights Ceiling Lights, Wall Lights Type of lighting installed.	Outlets / Electrical: GFI Outlets / Reset Location Hallway Bathroom	Exhaust Fan: Condition Works on Demand
Exhaust Fan: Functional The bathroom exhaust fan(s) are functional and respond on demand.		

Bathroom: Location & Picture
2nd Floor



Bathroom: Checking Water Supply/Flow
The water supply and water flow was tested in this bathroom for a minimum of five (5) minutes. This includes sinks, the tub and/or shower. We do this to try and simulate conditions that may show leaking or other related water issues. Please be aware that conditions and components will change over time.

Sink and Faucet: Water Flow Pictures

Works On Demand

Pictures of functional water flow at the residence bathroom sinks.

**Sink and Faucet: Satisfactory Comment**

The sink and faucet were functional and in good condition, unless otherwise noted.

Sink and Faucet: Cosmetic Issues Noted

There is cosmetic staining noted in the master bathroom sinks. I recommend service as you feel necessary.

Tub/Shower: Satisfactory Comment

The tub/shower is functional. Water supply was verified and no leaking noted, unless otherwise indicated.


**Tub/Shower: Tub/Shower Type & Water Flow Pictures**

Separate Stall Shower, Separate Tub

Type of tub and/or shower noted in this bathroom. Water flow pictures.

Tub/Shower: Cosmetic Damage Noted

There is some cosmetic type damage on the shower floor. I recommend service as you feel necessary.



Trap and Drain: Condition


Functional Drainage Noted

**Trap and Drain: Satisfactory Comment**

The bathroom sink traps and drains are functional. No leaking was noted unless specifically indicated.

Valves and Connectors: Type

Pull Valve

**Valves and Connectors: Satisfactory Comment**

The valves and connectors below the bathroom sinks and toilet appear functional. Valves were not turned or tested, however no leaking was noted at the time of inspection, unless otherwise noted. Valves are not in daily use and will inevitably become stiff or frozen and need service or replacement.

Toilet: Satisfactory Comment

The toilets were functional, flush properly and no leaking noted, unless otherwise specified.

Flooring: Worn Or Cosmetically Damaged

The flooring is worn or cosmetically damaged, which you should view for yourself and correct as desired.

Windows: Satisfactory

The windows in the bathroom are in satisfactory and functional condition, unless otherwise noted.

Walls and Ceiling: Satisfactory Comment

The walls and ceilings in the bathroom are in acceptable condition, unless otherwise noted.

Walls and Ceiling: Cosmetic Issues Noted

The walls and/or ceilings have typical and minor cosmetic damage such as: (scuffs, scrapes, nail holes etc) that you should view yourself and correct as desired.

Countertop: Satisfactory Comment

The visible areas of the bathroom countertops are in satisfactory condition.

Countertop: Typical Wearing Noted

The bathroom countertop showed typical wear and tear that you should view for yourself and correct if desired.

Cabinets/Drawers/Shelves: Satisfactory / As Noted


The bathroom cabinets, drawers and shelves, as applicable, are in satisfactory condition, unless otherwise specifically noted.

Cabinets/Drawers/Shelves: Cosmetic Issues Noted

The cabinets have typical and minor cosmetic damage, often consistent with time and use. I recommend you should view these areas for yourself and correct as desired.

Closet: Satisfactory Comment

The closets and interior closet space, in the bathroom, appear to be in satisfactory condition.



Outlets / Electrical: GFI Satisfactory

Master Bathroom

The bathroom outlets are functional and include ground fault protection (GFI) that resets in the noted location(s),

Limitations

Cabinets/Drawers/Shelves

STORAGE RESTRICTS VIEWING

Storage in the bathroom cabinets restricts viewing the entire cabinet and any components with them. I recommend checking the cabinets and components again once the storage is removed. It is possible for storage to hide damage, defects or moisture stains/damage that would have otherwise been visible during the inspection.



Observations

17.7.1 Doors

STRIKER PLATE NEEDS ADJUSTMENT

MASTER BATHROOM

The door striker plate needs to be adjusted for installed for the striker pin to engage.

Recommendation

Contact a qualified handyman.



Unsatisfactory Item



17.8.1 Flooring

HOLLOW SOUNDING TILES

MASTER BATHROOM

There are hollow sounding master bathroom floor tiles which you should view for yourself. Also noted obvious cracked and missing grout between the tiles. This is likely to have been caused by normal movement/settlement or poor craftsmanship. Further evaluation is recommended from a qualified contractor for service as you feel necessary.

Recommendation

Contact a qualified professional.



Unsatisfactory Item

17.8.2 Flooring

CRACKS / FLOOR TILES OR GROUT LINES


There are minor and typical cracks in the master bathroom floor tiles or grout lines, which you should view for yourself. They are likely to have been caused by normal settlement, but you may wish to seek the opinion of a specialist; especially if you are concerned or desire more information.

Recommendation

Contact a qualified professional.



Unsatisfactory Item



17.14.1 Lights / Wall Switches

CEILING LIGHT / NO RESPONSE

MASTER BATHROOM

A master bathroom ceiling light does not respond and should be demonstrated or serviced as necessary. Maybe a bad bulb?

Recommendation

Contact a qualified professional.



Unsatisfactory Item



17.16.1 Exhaust Fan

NOISY

MASTER BATHROOM

The master bathroom exhaust fan is functional, but noisy, and you should consider replacing it for a quieter one or have it serviced as you feel necessary.



Unsatisfactory Item

Recommendation

Contact a qualified professional.



18: HALLWAY BATHROOM

Information

Bathroom: Size
Full Bath

Sink and Faucet: Water Flow / Pictures
Hallway Bathroom
Works on Demand

Pictures of water flow during the inspection.

Trap and Drain: Condition
Functional Drainage Noted



Valves and Connectors: Type
Guest Bathroom
Pull Valve

Toilet: Condition
Flushes on Demand

Doors: Condition
Functional



Flooring: Type
Tile

Windows: Type
None

Walls and Ceiling: Condition
Satisfactory

Cabinets/Drawers/Shelves: Type
Cabinets

Lights / Wall Switches: Wall Switches / Functional

The wall switches are functional and respond on demand.

Lights / Wall Switches: Type / Lights
Wall Lights
Type of lighting installed.

Outlets / Electrical: GFI Outlets / Reset Location
This Bathroom

Exhaust Fan: Condition
Functional

Exhaust Fan: Functional

The bathroom exhaust fan(s) are functional and respond on demand.

Bathroom: Location & Picture

2nd Floor

**Bathroom: Checking Water Supply/Flow**

The water supply and water flow was tested in this bathroom for a minimum of five (5) minutes. This includes sinks, the tub and/or shower. We do this to try and simulate conditions that may show leaking or other related water issues. Please be aware that conditions and components will change over time.

Sink and Faucet: Satisfactory Comment

The sink and faucet were functional and in good condition, unless otherwise noted.

**Tub-Shower: Tub/Shower Type & Water Flow Pictures**

Tub & Shower in One

Type of tub and/or shower noted in this bathroom. Water flow pictures.

**Tub-Shower: Satisfactory Comment**

The tub and/or shower is functional. Water supply was verified and no leaking noted, unless otherwise indicated.

Tub-Shower: Caulk Shower Valves on Wall

There are open gaps or separations at the shower valves on the wall in the bathroom. I recommend servicing these areas as necessary to help prevent moisture intrusion into the wall

Tub-Shower: Cosmetic Damage Noted

There is minor cosmetic type damage in the tub that you should be aware of.

**Trap and Drain: Satisfactory Comment**

The bathroom sink traps and drains are functional. No leaking was noted unless specifically indicated.

Valves and Connectors: Satisfactory Comment

The valves and connectors below the bathroom sinks and toilet appear functional. Valves were not turned or tested, however no leaking was noted at the time of inspection, unless specifically noted otherwise. Valves are not in daily use and will inevitably become stiff or frozen and need service or replacement.

Toilet: Satisfactory Comment

The toilet is functional, flushes properly and no leaking was noted, unless otherwise specified.

Doors: Satisfactory Comment

The doors in this bathroom are functional and in satisfactory condition, unless otherwise specifically noted.

Flooring: Satisfactory Comment

The floors in the bathrooms are in satisfactory condition unless otherwise specifically noted.

Flooring: Cracks / Floor Tile And Grout

There are minor and typical cracks in the floor tiles or grout lines, which you should view for yourself. They are likely to have been caused by normal settlement, but you may wish to seek the opinion of a specialist; especially if you are concerned or desire more information.



Walls and Ceiling: Satisfactory Comment

The walls and ceiling in the hallway bathroom are in acceptable condition, unless otherwise noted.

Countertop: Satisfactory Comment

The visible areas of the bathroom countertops are in satisfactory condition.

Countertop: Typical Wearing Noted

The bathroom countertop showed typical wear and tear that you should view for yourself and correct if desired.

Cabinets/Drawers/Shelves: Satisfactory / As Noted

The bathroom cabinets, drawers and shelves, as applicable, are in satisfactory condition, unless otherwise specifically noted.

Cabinets/Drawers/Shelves: Cosmetic Issues Noted

The cabinets have typical and minor cosmetic damage, often consistent with time and use. I recommend you should view these areas for yourself and correct as desired.

Lights / Wall Switches: Lights / Satisfactory

The lightning in this bathroom is satisfactory, unless specifically noted otherwise.

Outlets / Electrical: GFI / Satisfactory

Hallway Bathroom

The bathroom outlets are functional and include ground fault protection (GFI) that resets in the noted location(s),

Limitations

Closet

NONE NOTED

There were no bathroom closets during this inspection.

Observations

18.4.1 Trap and Drain

SLOW DRAIN

HALLWAY BATHROOM

The hallway bathroom sink drain is slow or partially blocked and should be evaluated for service as necessary by a qualified contractor. Service is important to ensure any blockage has not progressed beyond the drain trap and involved the main waste line. Maybe only a build up of hair and soap from normal usage?

Recommendation

Contact a qualified professional.

 Unsatisfactory Item

18.8.1 Flooring

CRACKED FLOOR TILES

HALLWAY BATHROOM

 Unsatisfactory Item

There are cracks in the hallway bathroom floor tiles or grout lines, which you should view for yourself. They are likely to have been caused by normal settlement, but you may wish to seek the opinion of a specialist; especially if you are concerned or desire more information.

Recommendation

Contact a qualified professional.



18.8.2 Flooring

HOLLOW SOUNDING TILES

HALLWAY BATHROOM

There are hollow sounding hallway bathroom floor tiles which you should view for yourself. Also noted obvious cracked and missing grout between the tiles. This is likely to have been caused by normal movement/settlement or poor craftsmanship. Further evaluation is recommended from a qualified contractor for service as you feel necessary.

Recommendation

Contact a qualified professional.



Unsatisfactory Item

19: STAIRS

Information

View of Stairs / Photo



Lights / Wall Switches: Wall Switches / Functional

The wall switches are functional and respond on demand.

Outlets / Electrical: None Noted

There are not any outlets in the stairwell area.

Floor Treads & Risers: Satisfactory

The stair treads and risers appear satisfactory. The rise should not be less than 4 inches, nor greater than 7 inches, and the treads should not be less than 11 inches. In addition, the dimensions of the treads and the risers should not exceed 3/8 of an inch from the smallest dimension on the entire run of the stairs.

Handrails & Guardrails: Satisfactory

The handrail and/or guardrail on the stairs is satisfactory and in good condition. If children occupy or visit this residence, suitable safety precautions should be taken to safeguard them.

Flooring: Satisfactory
Stairs

The stairwell floor is in satisfactory condition, unless otherwise specifically noted.

Walls and Ceiling: Satisfactory

The walls and ceilings in the stairwell area are in acceptable condition, unless otherwise noted.

Walls and Ceiling: Cosmetic Issues Noted

The walls and/or ceilings have typical and minor cosmetic damage such as: (scuffs, scrapes, nail holes etc) that you should view yourself and correct as desired.

Walls and Ceiling: Typical Settlement Cracking Noted

There are typical and minor settlement type cracking noted on some walls and ceilings in the livable spaces.

Standard Clearances: Head Height Windows: Type
Clearance / Satisfactory None

The head height clearance at the stairs appears satisfactory.

Lights / Wall Switches: Type / Lights **Lights / Wall Switches: Lights / Satisfactory**

Ceiling Lights The lighting is in satisfactory condition, unless otherwise noted.

Type of lighting installed.

Smoke Detectors: Smoke Detectors / In Place / Functional

There are smoke detectors in place within the bedrooms of the residence. They responded when tested, unless otherwise noted. NOTE: Smoke detectors should be tested monthly and can fail at any time. They should be replaced at least every ten years or if they fail to respond.

Limitations

Smoke Detectors

TOO HIGH TO TEST

The smoke detector in the stairwell area is too high up on the wall or ceiling to test. I recommend further evaluation as you feel necessary.

20: SETTING REASONABLE EXPECTATIONS

Information

Setting Reasonable Expectations

Setting Reasonable Expectations When Things Go Wrong

There may come a time that you discover something wrong with your house, and you may be upset or disappointed with your home inspection.

Intermittent Or Concealed Problems

Some problems can only be discovered by living in a house. They cannot be discovered during the few hours of a home inspection. For example, some shower stalls leak when people are in the shower, but do not leak when you simply turn on the water supply. Some roofs and basements only leak when specific conditions exist. Some problems will only be discovered when carpets are lifted, furniture is moved or finishes are removed.

No Clues

These problems may have existed at the time of the inspection but there were no clues as to their existence. Our inspections are based on the past performance of the house. If there are no clues of a past problem, it is unfair to assume we should foresee a future problem or failure.

We May Miss Some Minor Things

Some say we are inconsistent because our reports identify some minor problems but not others. The minor problems that are identified were discovered while looking for more significant problems. We note them simply as a courtesy. The intent of the inspection is not to find the \$200 problems; it is to find the \$2,000 problems. These are the things that affect peoples decisions to purchase.

Contractors Advice

The main source of dissatisfaction with home inspectors comes from comments made by contractors. Contractors opinions often differ from ours. Don't be surprised when three roofers all say the roof needs replacement when we said that, with some minor repairs, the roof will last a few more years.

Last Man In Theory

While our advice represents the most prudent thing to do, many contractors are reluctant to undertake these repairs. This is because of the Last Man In Theory. The contractor fears that if he is the last person to work on the roof, he will get blamed if the roof leaks, regardless of whether the roof leak is his fault or not. Consequently, he won't want to do a minor repair with high liability when he could re-roof the entire house for more money and reduce the likelihood of a callback. This is understandable.

Most Recent Advice Is Best

There is more to the Last Man In Theory. It suggests that it is human nature for homeowners to believe the last bit of expert advice they receive, even if it is contrary to previous advice. As home inspectors, we unfortunately find ourselves in the position of First Man In and consequently it is our advice that is often disbelieved.

Why Didnt We See It

Contractors may say, "I cant believe you had this house inspected, and they didn't find this problem". There are several reasons for apparent oversights:

1. Conditions During Inspection

It is difficult for homeowners to remember the circumstances in the house, at the time of the inspection. Homeowners seldom remember that it was raining, there was storage everywhere in the basement or that the furnace could not be turned on because it was too hot out, etc. Its impossible for contractors to know what the circumstances were when the inspection was performed.

2. The Wisdom Of Hindsight

When the problem manifests itself, it is very easy to have 20/20 hindsight. Anybody can say that the basement is wet when there is 2 inches of water on the floor. Predicting the problem is a different story.

3. A Long Look

If we spent 1/2 an hour under the kitchen sink or 45 minutes disassembling the furnace, we would probably find more problems too. Unfortunately, the inspection would take several days and would cost considerably more.

4. We are Generalists

We are generalists; we are not specialists. Example: An HVAC contractor is a specialist and will indeed have more knowledge and expertise on heating and cooling systems than we do.

5. An Invasive Look

Problems often become apparent when carpets or drywall/plaster are removed, when fixtures or cabinets are pulled out, and so on. A home inspection is a visual examination. We don't perform any invasive or destructive tests.

Not Insurance

In conclusion, a home inspection is designed to better your odds. It is not designed to eliminate all risk. For that reason, a home inspection should not be considered an insurance policy. The premium that an insurance company would have to charge for a policy with no deductible, no limit and an indefinite policy period would be considerably more than the fee we charge. It would also not include the value added by the inspection.

Home Inspections are NOT...

- A protection against future failures.
- An appraisal that determines the value of a home.
- A code inspection, which verifies local building code compliance or the existence of permits for any improvements on the property.

We hope this is good food for thought. Please feel free to contact us with questions or concerns.

21: REPORT CONCLUSION

Information

Report Conclusion

Congratulations on the purchase of your new property! Since we never know who will be occupying or visiting a property, whether it be children or the elderly, we ask you to consider following these general safety recommendations: install and monitor smoke and carbon monoxide detectors; identify all escape and rescue ports; rehearse an emergency evacuation of the home; upgrade older electrical systems (if present) by at least adding ground-fault outlets; never service any electrical equipment without first disconnecting its power source; safety-film all non-tempered glass; ensure that every elevated window and the railings of stairs, landings, balconies, and decks are child-safe, meaning that barriers are in place or that the distance between the rails is not wider than three inches; regulate the temperature of water heaters to prevent scalding; make sure that goods that contain caustic or poisonous compounds, such as bleach, drain cleaners, and nail polish removers be stored where small children cannot reach them; ensure that all garage doors are well balanced and have a safety device, particularly if they are the heavy wooden type; remove any double-cylinder deadbolts from exterior doors; and consider installing child-safe locks and alarms on the exterior doors of all pool and spa properties.

We are proud of our service and trust that you will be completely satisfied with the quality of our report. We have made every effort to provide you with an accurate assessment of the condition of the property and its components and to alert you to any significant defects or adverse conditions. However, we may not have tested every outlet, and opened every window and door, or identified every minor defect. Also because we are not specialists or because our inspection is essentially visual, latent defects could exist. Therefore, you should not regard our inspection as conferring a guarantee or warranty. It does not. It is simply a report on the general condition of a particular property at a given point in time. Furthermore, as a homeowner, you should expect problems to occur. Roofs will leak, drain lines will become blocked, and components and systems will fail without warning. For these reasons, you should take into consideration the age of the house and its components and keep a comprehensive insurance policy current. If you have been provided with a home protection policy, read it carefully. Such policies usually only cover insignificant costs, such as that of roofer service, and the representatives of some insurance companies can be expected to deny coverage on the grounds that a given condition was preexisting or not covered because of what they claim to be a code violation or manufacturers defect. Therefore, you should read such policies very carefully, and depend upon our company for any consultation that you may need.

FURTHERMORE, you are advised to seek two professional opinions and acquire estimates of repair as to any defects, comments, improvements or recommendations mentioned in this report. We recommend that the professional making any repairs inspect the property further in order to discover and repair related problems that were not identified in the report. We recommend that all repairs, corrections, and cost estimates be completed and documented prior to closing or purchasing the property. Feel free to hire other professionals to inspect the property prior to closing. Including HVAC professionals, electricians, engineers, window professionals roofers etc.

Thank you for taking the time to read this report, and call us if you have any questions or observations whatsoever. I am always attempting to improve the quality of my service and this report, and I will continue to adhere to the highest standards of the real estate industry and to treat everyone with kindness, courtesy, and respect.

22: POOL/SPA - FSHI EVALUATED

Information

Pool and Equipment Pictures:
Picture of Pool Equipment Area



Tiles: Tiles
Needs Service

Drain Covers: Type
Anti-Vortex
Type of pool floor drain cover noted.

Interior Finish: Finish Type
Pebble-tech
Type of interior pool finish.

Expansion Joints: Satisfactory
The expansion joints in the pool decking appear satisfactory.

Pool Filter: Type of Filter
Sand Filter
Type of pool filter onsite.



Deck & Steps & Coping: Steps
Steps Need Service

Expansion Joints: Expansion Joints Noted
Satisfactory
Pool Filter: Sand Pool Filter / Functional
The sand pool filter is functional.

Spa/Hot Tub Filter: Type of Filter
Sand Filter
Type of pool filter onsite.

Skimmer & Cleaning System: Weir Door
None Noted

Skimmer & Cleaning System: Return Draw
Draw/Satisfactory

Skimmer & Cleaning System: Pool Floor Cleaning System Type
Pop Ups, Floor Sweep/Navigator

Skimmer & Cleaning System: Weir Door/Satisfactory
The weir door on the skimmer return box is in place and appears functional.

Skimmer & Cleaning System: Skimmer Box
Satisfactory

Skimmer & Cleaning System: Skimmer Basket
In Place/Satisfactory

Supply & Return Lines Etc: Supply & Return Lines Etc: Self
& Return Lines / Valves
Hard PVC Pipe Noted, Ball Valves
Condition as noted below.

Leveler
In Place at Pool



Supply & Return Lines Etc:
Aerator Valve Type
Ball Valve

Salt Cell, Chlorinator, Ozone: Salt
System Components Onsite
Chlorinator

Electrical: GFI Outlets /
Satisfactory

The GFCI outlets in the general vicinity of the pool are functional.

Heater: Heater
Gas Heater

Heater: Grounding/Bonding
Connection Noted
Grounded

Visible grounding or bonding connection as noted.

Spa Blower: Blower
None Noted



Pool and Equipment Pictures: Picture of Pool



General : Comments

The interior finish of pools is rarely perfect and never remains so, and particularly those on pools with colored plasters, and certainly if the chemical balance of the water is not properly maintained. Also, calcium and other minerals does leech through the material and mar the finish. This is equally true of pool tiles, on which mineral scaling is not only common but difficult to remove. Even the harshest abrasives will not remove some scaling, which sometimes has to be removed by bead-blasting, which in turn reduces the luster of the tiles. However, such imperfections have only a cosmetic significance. Similarly, the decks around pools and spas tend to develop cracks that have only a cosmetic significance. The commonest are relatively small, and are often described as being curing fractures. Some of these will contour the outline of the pool, or the point at which the bond beam, or structural wall of the pool, meets the surrounding soil. These too have little structural significance, but some cracks are larger and result from seismic motion, or from settling due to poorly compacted soils, or they confirm the presence of expansive soils, which can be equally destructive, but which should be confirmed by a geo-structural engineer. However, any crack in the shell of a pool or spa should be dye-tested or otherwise evaluated by a specialist. I strongly recommend having the pool evaluated by a qualified pool service, prior to the close of escrow, for a full and detailed inspection, due to the visual limitations and limited scope of a home inspection.

General : Disclaimers

Pools and spas do leak, but without specialized equipment this may be impossible to confirm. However, it could become apparent from secondary evidence during our inspection, which is purely visual. Regardless, the owner or the occupant of a property would be aware that the water level drops regularly and must be topped off, and this should be disclosed. Unusually high water bills could reveal this, but only a pressure test of the pipes, a dye test of cracks, or a geo-phone test of specific areas would confirm it, and any such specialized test is beyond the scope of our service. Therefore, you should ask the sellers to guarantee that the spa does not leak, request to review the water bills for a twelve-month period, or obtain comprehensive insurance to cover such an eventuality.

Deck & Steps & Coping: Decking / Satisfactory

The pool decking is in satisfactory condition, unless specifically noted otherwise.

Drain Covers: Anti Vortex Noted

The drain cover on the bottom of the pool is a safer and satisfactory anti-vortex type .

Skimmer & Cleaning System: Pop-Up Floor Cleaning System

The pool floor pop up style cleaning system appears to be working properly at the time of the inspection. I was able to see most of the floor pop up heads cycling or moving up and down as they progress through their cleaning cycle.

Skimmer & Cleaning System: Skimmer Box & Cover / Satisfactory

The skimmer box and its cover are functional and appear to work as intended.

Supply & Return Lines Etc: Supply Lines, Return Lines, Valves / Satisfactory

The visible supply lines, return lines, and valves are in acceptable condition, unless otherwise noted.

Supply & Return Lines Etc: Automatic Self-Leveler / Satisfactory

The automatic self leveling pool water supply is satisfactory and responds on demand.

Pool Pump and Motor: Pool Pumps & Motors

Multi

Number of and condition of pool pumps and motors in the pool equipment area.

Pool Pump and Motor: Grounding Connection

Visible/Satisfactory

The pool pumps and motors appear to be properly grounded or bonded, unless otherwise noted.

Electrical: Timer / Satisfactory

The pool timer was visually operational and should work as intended. I recommend having the timer checked by a qualified pool professional for more information or for a demonstration.

Heater: Heater Responds to Controls

The heater in the pool equipment area appears functional, but should be kept clean and serviced seasonally. The heater was turned on momentarily and worked on demand. I did not test or verify any water temperature gain after running the heater. Further evaluation of this heater is recommended from a qualified pool contractor, before your take possession of the property and at least before use, especially if you have any concerns.

Observations

22.3.1 Pool Observations

SPA


The spa appears to be dirty with dirt on the bottom. Recommend service by qualified professional.

Recommendation

Contact a qualified professional.



Unsatisfactory Item



22.3.2 Pool Observations

POOL

This is a complex pool system. The home inspection was a general overall inspection of the pool ,spa and Equipment area. There are multiple issues and I recommend further evaluation from a qualified pool professional for full evaluation above and beyond this Home Inspection.This will allow a full evaluation at well as approximate repair estimates.

Recommendation

Contact a qualified professional.



Unsatisfactory Item

22.4.1 Enclosure Safety Observations

NO SELF CLOSING FEATURE


There is no self closing feature on the rear sliding glass door. This is important for child pool safety reasons.

Recommendation

Contact a qualified professional.



Unsatisfactory Item



22.5.1 Interior Finish

CRACKS ON POOL STEPS

There is a crack on the top pool step that should be further evaluated by a qualified pool contractor for service as necessary.

Recommendation

Contact a qualified Swimming Pool Contractor



Unsatisfactory Item



22.5.2 Interior Finish




Unsatisfactory Item

CRACKS ON POOL INTERIOR

There are cracks at many areas on the pool interior plaster finish that appear cosmetic, but should be further evaluated by a qualified pool contractor, preferably within the inspection period. Evaluation is important to help determine the level of service necessary and any potential repair cost involved.

Recommendation

Contact a qualified Swimming Pool Contractor



22.6.1 Deck & Steps & Coping



Unsatisfactory Item

CRACKING NOTED / STEPS

There are crack located on the pool steps. I recommend having a qualified pool contractor service this as necessary. This is important to help prevent pool water from getting behind the pool finish and causing further issues.

Recommendation

Contact a qualified professional.



22.6.2 Deck & Steps & Coping

DECK CRACKS NOTED



Unsatisfactory Item

There is a typical curing crack in the pool decking however it appears an edge of the pool coping has cracked off and was secured back in place. I recommend further evaluation from a qualified contractor for more detailed information and additional service as necessary.

Recommendation

Contact a qualified professional.



22.7.1 Tiles

TILES MISSING




Unsatisfactory Item

There are missing pool wall tiles which should be replaced by a qualified contractor.

Recommendation

Contact a qualified Swimming Pool Contractor



22.11.1 Spa/Hot Tub Filter

PRESSURE GAUGE / BROKEN

Unsatisfactory Item

The pressure gauge on the pool filter, which is designed to reveal when the filter needs to be cleaned, and includes a purge valve, is broken and should be replaced.

Recommendation

Contact a qualified Swimming Pool Contractor

22.12.1 Skimmer & Cleaning System

MISSING DIVERTER

Unsatisfactory Item

The diverter is missing inside the skimmer box; located on the bottom. I recommend having it replaced by a qualified contractor.

Recommendation

Contact a qualified Swimming Pool Contractor



22.12.2 Skimmer & Cleaning System

POP UPS NOT RETRACTING

Unsatisfactory Item

Many pool floor pop-up heads do not retreat into their collars. This should be further evaluated and repaired as determined necessary by a qualified contractor.

Recommendation

Contact a qualified Swimming Pool Contractor

22.12.3 Skimmer & Cleaning System

MISSING POOL FLOOR HEADS

Unsatisfactory Item

There are missing pop-up heads in the pool floor of the pool cleaning system. They should be replaced and the cleaning system evaluated and serviced as necessary by a qualified pool technician.

Recommendation

Contact a qualified Swimming Pool Contractor



22.12.4 Skimmer & Cleaning System


GEARS NOT ROTATING

 Unsatisfactory Item

The pool floor pop-up heads are not all working. The distributor zone gears are likely not properly moving through the different zones. Gauges are also broken. Further evaluation is recommended from a qualified pool contractor for more detailed information and service as determined necessary.

Recommendation

Contact a qualified Swimming Pool Contractor



22.12.5 Skimmer & Cleaning System

FLOOR SWEEP AND POP UPS NOTED

 Unsatisfactory Item

There is a pool floor sweep and pool floor pop-ups both in use. I recommend further evaluation from a qualified pool contractor for more detailed information. Usually, there is either only one or the other in use.

Recommendation

Contact a qualified professional.

22.13.1 Supply & Return Lines Etc

AERATOR VALVE HANDLE / DAMAGED

 Unsatisfactory Item

The red aerator valve handle in the pool equipment area is damaged (broken wings) and should be replaced as necessary by a qualified pool contractor.

Recommendation

Contact a qualified Swimming Pool Contractor

22.13.2 Supply & Return Lines Etc

PAINT & LABEL PVC PIPES

The PVC pipes at the pool equipment area should be painted to help prevent sun damage or wearing. They should also be properly labeled for ease of use.

Recommendation

Contact a qualified Swimming Pool Contractor



Unsatisfactory Item



22.13.3 Supply & Return Lines Etc

VALVE HANDLE DAMAGED



Handles are damaged on a valves in the pool equipment area. It should be evaluated and repaired or replaced as necessary by a qualified contractor.

Recommendation

Contact a qualified Swimming Pool Contractor



Unsatisfactory Item



22.13.4 Supply & Return Lines Etc

VALVE

There is a unused valve in the pool area. I recommend asking seller for further information. Recommend service by qualified professional.

Recommendation

Contact a qualified professional.



Unsatisfactory Item



22.15.1 Pool Pump and Motor




Unsatisfactory Item

MOTOR OR PUMP / DOES NOT RESPOND

The pool pump/motor for the Water Feature is frozen, or did not respond to the controls. It will need to be further evaluated by a qualified pool contractor and repaired or replaced as determined necessary.

Recommendation

Contact a qualified Swimming Pool Contractor



22.15.2 Pool Pump and Motor



Unsatisfactory Item

PUMP/MOTOR LEAKING

There is a leak at the pool pump/motor which should be further evaluated and serviced as necessary by a qualified pool contractor.

Recommendation

Contact a qualified Swimming Pool Contractor



22.15.3 Pool Pump and Motor



Unsatisfactory Item

NOISY

The pool pump/motors are all noisy or louder than typical. This is indicative a worn bearing or other issue that should be evaluated by a qualified contractor and serviced as determined necessary.

Recommendation

Contact a qualified Swimming Pool Contractor

22.16.1 Electrical



Unsatisfactory Item

EXPOSED WIRE / NEEDS CONDUIT

The exposed electrical wire in the pool equipment area should be properly covered in conduit for safety reasons. Service as necessary is recommended from a qualified contractor.

Recommendation

Contact a qualified professional.



22.16.2 Electrical



Unsatisfactory Item

SPA DISPLAY

The spa display did not function and the digital readout it's not visible. Recommend service by qualified professional.

Recommendation

Contact a qualified professional.



22.17.1 Pool Light

POOL LIGHT / NO RESPONSE


The pool light did not respond and should be demonstrated by the seller or serviced by a qualified contractor, if necessary, and confirmed to have ground-fault protection.

Recommendation

Contact a qualified Swimming Pool Contractor



Unsatisfactory Item



22.17.2 Pool Light

SPA LIGHT / NO RESPONSE

The spa light did not respond, and should be demonstrated by the seller or serviced if necessary and confirmed to have ground-fault protection. However, for reasons of safety, the circuit should be tested periodically to ensure that its ground fault protection is functional.

Recommendation

Contact a qualified Swimming Pool Contractor



Unsatisfactory Item



22.18.1 Heater

NO TPR VALVE ON HEATER

I was not able to view or locate a temperature pressure relief valve (TPR) on this heater during the inspection. I recommend further evaluation from a qualified contractor to add one as necessary for safety reasons.

Recommendation

Contact a qualified Swimming Pool Contractor




Unsatisfactory Item

23: HALF BATHROOM


Information

Bathroom: Location & Picture

1st Floor

**Trap and Drain: Condition**


Functional Drainage Noted

**Valves and Connectors: Type Noted**

Pull Valve

**Toilet: Condition**

Flushes On Demand

**Doors: Condition**

Works on Demand

Flooring: Type Noted

Tile

Windows: Type


Dual Pane

**Walls and Ceiling: Type Noted**

Drywall

Countertop: Condition

Satisfactory

**Cabinets/Drawers/Shelves: Type**

None Noted

Cabinets/Drawers/Shelves: None Noted

There are not any cabinets in this half bathroom.

Closet: Condition

None

Lights / Wall Switches: Wall Switches / Functional The wall switches are functional and respond on demand.	Lights / Wall Switches: Type / Lights Wall Lights Type of lighting installed.	Outlets / Electrical: GFI Outlets / Reset Location Hallway Bathroom
Exhaust Fan: Condition Works on Demand	Exhaust Fan: Functional The bathroom exhaust fan is functional and responds on demand.	

Bathroom: Checking Water Supply/Flow

The water supply and water flow was tested in this bathroom for a minimum of five (5) minutes. We do this to try and simulate conditions that may show leaking or other related water issues. Please be aware that conditions and components will change over time.

Sink and Faucet: Water Flow Pictures

Works on Demand
Pictures of functional water flow at the residence bathroom sinks.



Sink and Faucet: Satisfactory Comment

The sink and faucet were functional and in good condition, unless otherwise specifically noted.

Trap and Drain: Satisfactory Comment

The bathroom sink traps and drains are functional. No leaking was noted unless specifically indicated.

Valves and Connectors: Satisfactory Comment

The valves and connectors below the bathroom sinks and toilet appear functional. Valves were not turned or tested, however no leaking was noted at the time of inspection, unless specifically noted otherwise. Valves are not in daily use and will inevitably become stiff or frozen and need service or replacement.

Toilet: Satisfactory Comment

This bathroom toilet is functional, flushes properly and no leaking was noted, unless otherwise specifically stated.

Doors: Satisfactory Comment

The door in this bathroom is functional and in satisfactory condition, unless otherwise specifically noted.

Flooring: Satisfactory Comment

The floors in the bathrooms are in satisfactory condition unless otherwise specifically noted.

Windows: Satisfactory Comment

The windows in the bathroom are in satisfactory and functional condition, unless otherwise noted.

Walls and Ceiling: Satisfactory Comment

The walls and ceilings in this bathroom are in acceptable condition, unless otherwise noted.

Walls and Ceiling: Cosmetic Issues Noted

The walls and/or ceilings have typical and minor cosmetic damage such as: (scuffs, scrapes, nail holes etc) that you should view yourself and correct as desired.

Countertop: Satisfactory

The visible areas of the bathroom countertops are in satisfactory condition.

Lights / Wall Switches: Lights / Satisfactory

The lights in this bathroom are satisfactory, unless specifically noted otherwise.

Outlets / Electrical: GFI / Satisfactory

The bathroom outlets are functional and include ground fault protection (GFI) that resets in the noted location(s),

Observations

23.4.1 Valves and Connectors


HALF BATHROOM

When the half bathroom sink hot water is on there is noticeable water expansion sounds coming from the Hot Water Heater. I recommend you viewing to determine Services necessary.

Recommendation

Contact a qualified professional.

 Unsatisfactory Item



STANDARDS OF PRACTICE

Foundation and Structure

I. The inspector shall inspect: A. the foundation; B. the basement; C. the crawlspace; and D. structural components. II. The inspector shall describe: A. the type of foundation; and B. the location of the access to the under-floor space. III. The inspector shall report as in need of correction: A. observed indications of wood in contact with or near soil; B. observed indications of active water penetration; C. observed indications of possible foundation movement, such as sheetrock cracks, brick cracks, out-of-square door frames, and unlevel floors; and D. any observed cutting, notching and boring of framing members that may, in the inspector's opinion, present a structural or safety concern.

IV. The inspector is not required to: A. enter any crawlspace that is not readily accessible, or where entry could cause damage or pose a hazard to him/herself. B. move stored items or debris. C. operate sump pumps with inaccessible floats. D. identify the size, spacing, span or location or determine the adequacy of foundation bolting, bracing, joists, joist spans or support systems. E. provide any engineering or architectural service. F. report on the adequacy of any structural system or component.

Hallways

Our inspection of living space includes the visually accessible areas of walls, floors, cabinets, and closets, and includes the testing of a representative number of windows and doors, switches and outlets. However, we do not evaluate window treatments or move furniture, lift carpets or rugs, empty closets or cabinets, and we do not comment on cosmetic deficiencies. We may not comment on the cracks that appear around windows and doors, or which follow the lines of framing members and the seams of drywall and plasterboard. These cracks are a consequence of movements, such as wood shrinkage, common settling, and seismic activity, and will often reappear if they are not correctly repaired. Such cracks can become the subject of disputes, and are therefore best evaluated by a specialist. Similarly, there are a number of environmental pollutants that we have already elaborated upon, the specific identification of which is beyond the scope of our service but which can become equally contentious. In addition, there is a host of lesser contaminants, such as that from moisture penetrating carpet-covered cracks in floor slabs, as well as odors from household pets and cigarette smoke that can permeate walls, carpets, heating and air conditioning ducts, and other porous surfaces, and which can be difficult to eradicate. However, inasmuch as the sense of smell adjusts rapidly, and the sensitivity to such odors is certainly not uniform, we recommend that you make this determination for yourself, and particularly if you or any member of your family suffers from allergies or asthma, and then schedule whatever remedial services may be deemed necessary before the close of escrow.

Home Interior / Living Areas

Our inspection of living space includes the visually accessible areas of walls, floors, cabinets, and closets, and includes the testing of a representative number of windows and doors, switches and outlets. However, we do not evaluate window treatments or move furniture, lift carpets or rugs, empty closets or cabinets, and we do not comment on cosmetic deficiencies. We may not comment on the cracks that appear around windows and doors, or which follow the lines of framing members and the seams of drywall and plasterboard. These cracks are a consequence of movements, such as wood shrinkage, common settling, and seismic activity, and will often reappear if they are not correctly repaired. Such cracks can become the subject of disputes, and are therefore best evaluated by a specialist. Similarly, there are a number of environmental pollutants that we have already elaborated upon, the specific identification of which is beyond the scope of our service but which can become equally contentious. In addition, there is a host of lesser contaminants, such as that from moisture penetrating carpet-covered cracks in floor slabs, as well as odors from household pets and cigarette smoke that can permeate walls, carpets, heating and air conditioning ducts, and other porous surfaces, and which can be difficult to eradicate. However, inasmuch as the sense of smell adjusts rapidly, and the sensitivity to such odors is certainly not uniform, we recommend that you make this determination for yourself, and particularly if you or any member of your family suffers from allergies or asthma, and then schedule whatever remedial services may be deemed necessary before the close of escrow.

Plumbing

I. The inspector shall inspect: A. the main water supply shut-off valve; B. the main fuel supply shut-off valve; C. the water heating equipment, including the energy source, venting connections, temperature/pressure-relief (TPR) valves, Watts 210 valves, and seismic bracing; D. interior water supply, including all fixtures and faucets, by running the water; E. all toilets for proper operation by flushing; F. all sinks, tubs and showers for functional drainage; G. the drain, waste and vent system; and H. drainage sump pumps with accessible floats. **II. The inspector shall describe:** A. whether the water supply is public or private based upon observed evidence; B. the location of the main water supply shut-off valve; C. the location of the main fuel supply shut-off valve; D. the location of any observed fuel-storage system; and E. the capacity of the water heating equipment, if labeled. **III. The inspector shall report as in need of correction:** A. deficiencies in the water supply by viewing the functional flow in two fixtures operated simultaneously; B. deficiencies in the installation of hot and cold water faucets; C. mechanical drain stops that were missing or did not operate if installed in sinks, lavatories and tubs; and D. toilets that were damaged, had loose connections to the floor, were leaking, or had tank components that did not operate. **IV. The inspector is not required to:** A. light or ignite pilot flames. B. measure the capacity, temperature, age, life expectancy or adequacy of the water heater. C. inspect the interior of flues or chimneys, combustion air systems,

water softener or filtering systems, well pumps or tanks, safety or shut-off valves, floor drains, lawn sprinkler systems, or fire sprinkler systems. D. determine the exact flow rate, volume, pressure, temperature or adequacy of the water supply. E. determine the water quality, potability or reliability of the water supply or source. F. open sealed plumbing access panels. G. inspect clothes washing machines or their connections. H. operate any valve. I. test shower pans, tub and shower surrounds or enclosures for leakage or functional overflow protection. J. evaluate the compliance with conservation, energy or building standards, or the proper design or sizing of any water, waste or venting components, fixtures or piping. K. determine the effectiveness of anti-siphon, backflow prevention or drain-stop devices. L. determine whether there are sufficient cleanouts for effective cleaning of drains. M. evaluate fuel storage tanks or supply systems. N. inspect wastewater treatment systems. O. inspect water treatment systems or water filters. P. inspect water storage tanks, pressure pumps, or bladder tanks. Q. evaluate wait time to obtain hot water at fixtures, or perform testing of any kind to water heater elements. R. evaluate or determine the adequacy of combustion air. S. test, operate, open or close: safety controls, manual stop valves, temperature/pressure-relief valves, control valves, or check valves. T. examine ancillary or auxiliary systems or components, such as, but not limited to, those related to solar water heating and hot water circulation. U. determine the existence or condition of polybutylene plumbing. V. inspect or test for gas or fuel leaks, or indications thereof.

Main Electrical Panel

The inspector shall inspect: A. the service drop; B. the overhead service conductors and attachment point; C. the service head, goose neck and drip loops; D. the service mast, service conduit and raceway; E. the electric meter and base; F. service-entrance conductors; G. the main service disconnect; H. panel boards and over-current protection devices (circuit breakers and fuses); I. service grounding and bonding; J. a representative number of switches, lighting fixtures and receptacles, including receptacles observed and deemed to be arc-fault circuit interrupter (AFCI)-protected using the AFCI test button, where possible; K. all ground-fault circuit interrupter receptacles and circuit breakers observed and deemed to be GFCI's using a GFCI tester, where possible; and L. smoke and carbon-monoxide detectors. II. The inspector shall describe: A. the main service disconnect's amperage rating, if labeled; and B. the type of wiring observed. III. The inspector shall report as in need of correction: A. deficiencies in the integrity of the service entrance conductors insulation, drip loop, and vertical clearances from grade and roofs; B. any unused circuit-breaker panel opening that was not filled; C. the presence of solid conductor aluminum branch-circuit wiring, if readily visible; D. any tested receptacle in which power was not present, polarity was incorrect, the cover was not in place, the GFCI devices were not properly installed or did not operate properly, evidence of arcing or excessive heat, and where the receptacle was not grounded or was not secured to the wall; and E. the absence of smoke detectors. IV.

The inspector is not required to: A. insert any tool, probe or device into the main panel board, sub-panels, distribution panel boards, or electrical fixtures. B. operate electrical systems that are shut down. C. remove panel board cabinet covers or dead fronts. D. operate or re-set over-current protection devices or overload devices. E. operate or test smoke or carbon-monoxide detectors or alarms. F. inspect, operate or test any security, fire or alarms systems or components, or other warning or signaling systems. G. measure or determine the amperage or voltage of the main service equipment, if not visibly labeled. H. inspect ancillary wiring or remote-control devices. I. activate any electrical systems or branch circuits that are not energized. J. inspect low-voltage systems, electrical de-icing tapes, swimming pool wiring, or any timecontrolled devices. K. verify the service ground. L. inspect private or emergency electrical supply sources, including, but not limited to: generators, windmills, photovoltaic solar collectors, or battery or electrical storage facility. M. inspect spark or lightning arrestors. N. inspect or test de-icing equipment. O. conduct voltage-drop calculations. P. determine the accuracy of labeling. Q. inspect exterior lighting.

Bedrooms

Our inspection of bedrooms includes the visually accessible areas of walls, floors, cabinets, and closets, and includes the testing of a representative number of windows and doors, switches and outlets. However, we do not evaluate window treatments or move furniture, lift carpets or rugs, empty closets or cabinets, and we do not comment on cosmetic deficiencies. We may not comment on the cracks that appear around windows and doors, or which follow the lines of framing members and the seams of drywall and plasterboard. These cracks are a consequence of movements, such as wood shrinkage, common settling, and seismic activity, and will often reappear if they are not correctly repaired. Such cracks can become the subject of disputes, and are therefore best evaluated by a specialist. Similarly, there are a number of environmental pollutants that we have already elaborated upon, the specific identification of which is beyond the scope of our service but which can become equally contentious. In addition, there is a host of lesser contaminants, such as that from moisture penetrating carpet-covered cracks in floor slabs, as well as odors from household pets and cigarette smoke that can permeate walls, carpets, heating and air conditioning ducts, and other porous surfaces, and which can be difficult to eradicate. However, inasmuch as the sense of smell adjusts rapidly, and the sensitivity to such odors is certainly not uniform, we recommend that you make this determination for yourself, and particularly if you or any member of your family suffers from allergies or asthma, and then schedule whatever remedial services may be deemed necessary before the close of escrow.