



# MOUNTAINS TO SOUND HOME INSPECTION LLC

253.344.4714

[brandon@mshomeinspection.com](mailto:brandon@mshomeinspection.com)

<https://www.mshomeinspection.com/>



## HOME INSPECTION REPORT

2505 SW Cloverdale St  
Seattle WA 98106

James & Stacey Morrison  
JULY 3, 2018



Inspector

**Brandon Goff**

Home Inspector Lic. 1014 SPI Lic. #88798

253.334.8631

[brandon@mshomeinspection.com](mailto:brandon@mshomeinspection.com)



Agent

**Christine Zahn**

(253) 332-1864

[christinezahn@cbbain.com](mailto:christinezahn@cbbain.com)

## Table of Contents

Table of Contents	2
SUMMARY	3
1: POSITIVE ATTRIBUTES OF THE HOME	5
2: INSPECTION DETAILS	6
3: EXTERIOR	7
4: ROOF	10
5: GARAGE(S)	11
6: MAIN ELECTRICAL PANEL	13
7: ELECTRIC HEATING SYSTEM	14
8: WATER HEATER & PLUMBING	15
9: KITCHEN	18
10: KITCHEN APPLIANCES	20
11: BATHROOMS	22
12: LAUNDRY	25
13: INTERIORS, WINDOWS & DOORS	27
14: ATTIC	30
15: GENERAL COMMENTS	32
16: REASONABLE EXPECTATIONS OF A HOME INSPECTION	35
17: REPORT CONCLUSION	37
STANDARDS OF PRACTICE	38

# SUMMARY



COSMETIC - MONITOR -  
MAINTENANCE



RECOMMENDATIONS



SAFETY ITEMS - IMMEDIATE  
ACTIONS

-  3.2.1 Exterior - Driveway, Walkways & Patio: Cracks in walkways
-  3.5.1 Exterior - Exterior Siding Notes: Earth to Wood contact
-  3.5.2 Exterior - Exterior Siding Notes: Exterior vents need repair
-  3.9.1 Exterior - Downspouts: Some downspouts are missing or need to be reconnected or serviced
-  3.14.1 Exterior - Outlets, Electrical Observations: Missing weather seals
-  3.14.2 Exterior - Outlets, Electrical Observations: Open neutral outlet
-  5.4.1 Garage(s) - Entry Door Into the House: Home entry not self closing
-  6.5.1 Main Electrical Panel - Wiring Notes: Hot neutral wires
-  7.1.1 Electric Heating System - Electric Heating Notes: Heater cover missing
-  8.1.1 Water Heater & Plumbing - Water Heating System: Seismic Straps - Missing/Insufficient
-  8.1.2 Water Heater & Plumbing - Water Heating System: Beyond expected life
-  9.4.1 Kitchen - Countertop: Missing or Deteriorated Caulk/Grout
-  9.4.2 Kitchen - Countertop: Backsplash minor Damaged
-  9.5.1 Kitchen - Exhaust Fan Notes: Exhaust vent leak
-  9.8.1 Kitchen - Windows: Missing or damaged hardware
-  9.10.1 Kitchen - Outlets, Electrical Observations: Missing Coverplate
-  10.2.1 Kitchen Appliances - Dishwasher: No Air Gap/High Loop
-  10.3.1 Kitchen Appliances - Garbage Disposal: Frozen
-  11.1.1 Bathrooms - Sink and Faucet: Overflow Leak
-  11.1.2 Bathrooms - Sink and Faucet: Low Water Pressure
-  11.1.3 Bathrooms - Sink and Faucet: Sink has scratches/chips
-  11.1.4 Bathrooms - Sink and Faucet: Sink stopper(s) missing
-  11.4.1 Bathrooms - Tub-Shower: Missing or deteriorated caulk/grout
-  11.4.2 Bathrooms - Tub-Shower: Tub valve inoperable
-  11.8.1 Bathrooms - Exhaust Fan: Exhaust fan did not work on demand
-  12.6.1 Laundry - Exhaust Fan: Exhaust fan did not work on demand
-  12.12.1 Laundry - Outlets, Electrical Observations: Missing coverplate
-  13.5.1 Interiors, Windows & Doors - Windows: Broken seals

- 
-  13.7.1 Interiors, Windows & Doors - Smoke & CO Detectors Notes: Add carbon monoxide detector
  -  13.7.2 Interiors, Windows & Doors - Smoke & CO Detectors Notes: The smoke detectors missing
  -  13.11.1 Interiors, Windows & Doors - Lights, Wall Switches: Light not working
  -  13.12.1 Interiors, Windows & Doors - Outlets, Electrical: Missing covers
  -  14.3.1 Attic - Roof Decking Notes: Deck Staining
  -  14.3.2 Attic - Roof Decking Notes: H-clips Not Used
  -  14.6.1 Attic - Common Observations: Rodent Activity
  -  14.7.1 Attic - Exhaust Ducts: Bathroom exhaust separated needs repair
  -  14.8.1 Attic - Ventilation: Limited Ventilation

# 1: POSITIVE ATTRIBUTES OF THE HOME

## Information

---

### Plumbing

The plumbing system was  
Copper plumbing

### Roof

The Roof was New

### Addition Features

Wood Burning Fireplace

### Description

Well kept, 1998 built townhome in Southwest Seattle. Two car garage on first level with large kitchen and living room with wood burning fireplace on 2nd level. Master Suite on 3rd floor with private bathroom including his and her sinks. Newer roof.



## 2: INSPECTION DETAILS

### Information

---

**Start Time**

1pm

**In Attendance**

Client's Agent

**Occupancy**

Vacant

**Style**

Multi-level

**Weather Conditions**

Clear

**Year Built**

1998

**Temperature**

70-80 degrees

**Type of Building**

Condominium / Townhouse

**The images here are the directional locations of the home used throughout the report. Ensure you get yourself orientated to what direction the house is situated in order to better follow along.**



## 3: EXTERIOR

### Information

---

#### **Driveway, Walkways & Patio: Driveway Acceptable**

The driveway is in acceptable condition.

#### **Driveway, Walkways & Patio: Walkway Acceptable**

The walkways are in acceptable condition.

#### **Exterior Siding Notes: Siding Type**

Wooden Siding

#### **Doorbell: Acceptable**

The doorbell is functional and works on demand.

#### **General Comments: Exterior comments**

It is important to maintain a property, including painting or sealing walkways, decks, and other hard surfaces, and it is particularly important to keep the house walls sealed, which provide the only barrier against deterioration. Unsealed cracks around windows, doors, and thresholds can permit moisture intrusion, which is the principle cause of the deterioration of any surface. Unfortunately, the evidence of such intrusion may only be obvious when it is raining. We have discovered leaking windows while it was raining that may not have been otherwise apparent. Regardless, there are many styles of windows but only two basic types, single and dual-glazed. Dual-glazed windows are superior, because they provide a thermal as well as an acoustical barrier. However, the hermetic seals on these windows can fail at any time, and cause condensation to form between the panes. Unfortunately, this is not always apparent, which is why we disclaim an evaluation of hermetic seals. Nevertheless, in accordance with industry standards, we test a representative number of unobstructed windows, and ensure that at least one window in every bedroom is operable and facilitates an emergency exit.

#### **Grading & Drainage: General Grading Comments**

Water can be destructive and foster conditions that are deleterious to health. For this reason, the ideal property will have soils that slope away from the residence and the interior floors will be several inches higher than the exterior grade. Also, the residence will have roof gutters and downspouts that discharge into area drains with catch basins that carry water away to hard surfaces. However, we cannot guarantee the condition of any subterranean drainage system, but if a property does not meet this ideal, or if any portion of the interior floor is below the exterior grade, we cannot endorse it and recommend that you consult with a grading and drainage contractor, even though there may not be any evidence of moisture intrusion. The sellers or occupants will obviously have a more intimate knowledge of the site than we could possibly hope to have during our limited visit, however we have confirmed moisture intrusion in residences when it was raining that would not have been apparent otherwise. Also, in conjunction with the cellulose material found in most modern homes, moisture can facilitate the growth of biological organisms that can compromise building materials and produce mold-like substances that can have an adverse affect on health.

#### **Exterior Siding Notes: Acceptable**

The exterior house wall finish is in acceptable condition. Any exceptions will be noted below.

#### **Foundation as Viewed from the Exterior: Exterior View**

The foundation was in acceptable condition as viewed from the exterior. Any exceptions will be noted.

#### **Fascia, Trim & Eaves: Acceptable**

The fascia boards, trim and eaves are in acceptable condition. Any exceptions will be noted below.

#### **Exterior Plumbing: Hose bibs Functional**

The hose bibs that were found and accessible were functional. Any exceptions will be noted.

**Exterior Plumbing: House Pressure PICTURE-Acceptable**

The pressure at the street was within industry standards, between 40 and 80 and a regulator is not required on the plumbing system.



**Downspouts: Acceptable**

The downspouts appear to be in acceptable condition. Any exceptions will be noted below. We recommend downspouts always drain away from the structure and foundation

**Exterior Doors: Exterior Doors Acceptable**

The exterior doors were in acceptable condition. Any exceptions will be noted.

**Lights: Acceptable**

The lights outside the doors of the residence are functional. Any sensor or light sensitive fixture lights were not tested.

**Observations**

3.2.1 Driveway, Walkways & Patio

 Cosmetic - Monitor - Maintenance

**CRACKS IN WALKWAYS**

There are a few cracks in the walkways around the residence that are mostly cosmetic. We suggest you view these yourself and repair as necessary.

Recommendation

Contact a qualified professional.



3.5.1 Exterior Siding Notes

 Recommendations

**EARTH TO WOOD CONTACT**

The siding was in contact with or nearly contacting soil or mulch or concrete. This is a condition conducive to deterioration and wood destroying organism infestation. We recommend removing soil a six-inch space between any siding material and soil where possible and repairs to any damaged or deteriorated siding.



3.5.2 Exterior Siding Notes

 Recommendations

**EXTERIOR VENTS NEED REPAIR**

The vent is missing or damaged and is in need of replacement.

Recommendation

Contact a qualified professional.




3.9.1 Downspouts

**SOME DOWNSPOUTS ARE MISSING OR NEED TO BE RECONNECTED OR SERVICED**

Some downspouts are missing parts or need to be reconnected or serviced.

Recommendation

Contact a qualified roofing professional.



3.14.1 Outlets, Electrical Observations

**MISSING WEATHER SEALS**

REAR

There is at least one exterior outlets that are missing weather seals or covers which are recommended for safety and to keep moisture from damaging the outlet.

Recommendation

Contact a qualified handyman.



3.14.2 Outlets, Electrical Observations

**OPEN NEUTRAL OUTLET**

REAR

An outlet has an open neutral, and should be serviced.

Recommendation

Contact a qualified electrical contractor.



## 4: ROOF

### Information

---

#### **Method of Evaluation & Photos:**

##### **Method of Evaluation & Photos**

Limited View w/ Drone

#### **Method of Evaluation & Photos: Height Restraints**

Physical restraints or the height off the ground forced the inspection of the roof to be conducted from the ground only or accessible surfaces as noted.

NOTE: Because the roof surface was too high above the ground or some adjoining surfaces, the inspector was not able to actually walk upon the surface to evaluate it in detail. The comments herein were based solely upon a limited visual inspection from a distance.

#### **Composition Shingle Roof Notes: Acceptable**

The roof is in generally acceptable condition. Any exceptions will be noted below. NOTE: This is not a guarantee against leaks.

#### **Composition Shingle Roof Notes: Estimated Age**

New

Because the exact installation date is unknown, this is an estimated guess of the age of the roof based on the current condition of the roof.

#### **Composition Shingle Roof Notes: General Comments and Description**

There are a wide variety of composition shingle roofs, which are comprised of asphalt or fiberglass materials impregnated with mineral granules that are designed to deflect the deteriorating ultra-violet rays of the sun. The commonest of these roofs are warranted by manufacturers to last from twenty to twenty-five years, and are typically guaranteed against leaks by the installer for three to five years. The actual life of the roof will vary, depending on a number of interrelated factors besides the quality of the material and the method of installation. However, the first indication of significant wear is apparent when the granules begin to separate and leave pockmarks or dark spots. This is referred to as primary decomposition, which means that the roof is in decline, and therefore susceptible to leakage. This typically begins with the hip and ridge shingles and to the field shingles on the south facing side. This does not mean that the roof needs to be replaced, but that it should be monitored more regularly and serviced when necessary. Regular maintenance will certainly extend the life of any roof, and will usually avert most leaks that only become evident after they have caused other damage.

## 5: GARAGE(S)

### Information

#### Picture and size of garage:

#### Picture and size of garage

Double Car Garage

The garage and its components were evaluated



#### Automatic Opener: Acceptable

The automatic garage door opener is acceptable

#### Automatic Opener: Safety lights- Acceptable

The garage door safety lights open the door when obstructed

#### Garage Door & Hardware: Acceptable

The sectional garage door and its hardware are functional.

#### Firewall Separation: Acceptable

The firewall separating the garage from the residence is functional.

#### Walls and Ceiling: Acceptable

The visible walls and ceiling are in acceptable condition.

#### Outlets, Electrical Observations: Acceptable

The outlets were in acceptable condition.

#### Slab Floor: Acceptable

The visible garage slab floor is in acceptable condition. Small cracks are common and result as a consequence of the curing process, seismic activity, common settling, or the presence of expansive soils, but are not structurally threatening.

#### Parking Space: Check parking space to accommodate your vehicles

It would be prudent for you to see that the parking space is adequate to accommodate your vehicles.

### Observations

#### 5.4.1 Entry Door Into the House

#### HOME ENTRY NOT SELF CLOSING



Recommendations

The house garage entry door is functional but does not self-close. It also rubs on the frame and has some minor frame damage. This may not have been required when the house was built and you may elect to have self-closing hinges installed for modern fire safety.

Recommendation

Contact a qualified handyman.



## 6: MAIN ELECTRICAL PANEL

### Information

#### Service Entrance: Main Lines

Underground

#### Panel Size, Location & Photo:

Panel Amps, Location and Picture

Garage, 125



#### Panel Cover Condition:

Acceptable

The electrical panel cover is in acceptable condition.

#### Wiring Notes: Electrical Service Conductors

Aluminum

#### Wiring Notes: Acceptable

The visible portions of the wiring have no deficiencies.

#### Circuit Breakers: Acceptable

There are no visible deficiencies with the circuit breakers.

#### Panel Size, Location & Photo: Earth Ground

Earth Ground Rod

The main panel grounding was observed and found to be in good repair and of adequate function at the time of the inspection.

#### Main Panel Notes: Acceptable

The panel and its components have no visible deficiencies. Any exceptions will be noted below.

#### Wiring Notes: Romex wiring

The residence is wired predominantly with a modern vinyl conduit known as Romex.

### Observations


#### 6.5.1 Wiring Notes

#### HOT NEUTRAL WIRES

Neutral wires (white) which are being used as hot power, were not taped to show use as HOT. Recommend that black electrical tape be installed on these white wires.

Recommendation

Contact a qualified professional.



## 7: ELECTRIC HEATING SYSTEM

### Information

---

#### Electric Heating Notes: Equipment Photo



#### Electric Heating Notes: Resistance Heaters

The resistance heaters were functional.

#### Electric Heating Notes: Baseboard Heat

The baseboard heaters were functional. Installing resistance wall unit heaters is would be a beneficial upgrade

### Observations

---

#### 7.1.1 Electric Heating Notes



Cosmetic - Monitor - Maintenance

#### **HEATER COVER MISSING**

3RD FLOOR RIGHT REAR BEDROOM

One or more of the heater covers were missing. Recommend replacing as needed.

Recommendation

Contact a qualified professional.



## 8: WATER HEATER & PLUMBING

### Information

---

**Water Heating System: Power Source/Type**  
Electric

**Water Heating System: Year**  
1994

**Water Heating System: Location**  
Garage

**Water Heating System: Capacity**  
50


**Water Heating System: Drain Valve-Acceptable**  
The drain valve is in place and presumed to be functional.

**Water Heating System: Electrical Connections-Acceptable**  
The electrical connection to the water heater is functional.

**Main Water Shut-Off, Distribution & Supply: Main Water Shut off Location**  
Garage, Front

**Main Water Shut-Off, Distribution & Supply: Water Meter Location**  
Unknown

**Main Water Shut-Off, Distribution & Supply: Water Supply Material To House**  
Copper



**Drain, Waste, & Vent Systems: Waste pipe Material**  
ABS

**Water Heating System: Manufacturer and picture**

Rheem

I recommend flushing & servicing your water heater tank annually for optimal performance. Water temperature should be set to at least 120 degrees F to kill microbes and no higher than 130 degrees F to prevent scalding.

[Here is a nice maintenance guide from Lowe's to help.](#)

**Water Heating System: Water Shut-Off Valve & Connectors**

The shut-off valve and water connectors appear functional but was not tested.

**Water Heating System: Relief Valve & Discharge Pipe-Acceptable**

The water heater is equipped with a mandated pressure-temperature relief valve and pipe.

**Water Heating System: Thermal Expansion Tank**

This water heater includes a safety feature known as a thermal expansion tank or potable water expansion tank that appears acceptable

**Main Water Shut-Off, Distribution & Supply: Plumbing acceptable**

The plumbing was generally in acceptable condition. Any exceptions will be noted low.

**Main Water Shut-Off, Distribution & Supply: Water Distribution Material**

Copper

A representative amount of the plumbing distribution system was observed and found to be in good repair.

**Drain, Waste, & Vent Systems: Acceptable**

Based on industry recommended water tests, the drainpipes are functional and acceptable at this time and functional drainage was noted. However, only a video-scan of the main drainpipe could confirm its actual condition which is beyond the scope of a general home inspection. Any exceptions will be noted below.

**Drain, Waste, & Vent Systems: Side Sewer Notes**

For a full evaluation of the waste line, we recommend that a sewer scope be completed.

## Observations

### 8.1.1 Water Heating System

 Safety Items - Immediate Actions

#### SEISMIC STRAPS - MISSING/INSUFFICIENT

The hot water heater was missing seismic straps or was insufficiently anchored. Recommend two straps to properly secure water heater in the case of an earthquake.

Recommendation

Contact a qualified professional.



### 8.1.2 Water Heating System

 Recommendations

#### BEYOND EXPECTED LIFE

The water heater is beyond its expected life. The need for replacement can be expected in the near future.

Recommendation

Contact a qualified professional.



# 9: KITCHEN

## Information

### Kitchen-PICTURE



### Sink and Faucet: Acceptable

The kitchen sink and faucet are functional.

### Trap and Drain: Acceptable

The kitchen trap and drain are functional. No leaking was noted.

### Exhaust Fan Notes: Acceptable

Vents to Exterior  
The kitchen exhaust fan was functional.

### Walls and Ceiling: Acceptable

The walls and ceiling are textured drywall and in acceptable condition.

### Cabinets: Acceptable

The cabinets are functional, and do not have any significant damage.

### Outlets, Electrical Observations: Acceptable

The outlets functioned as intended.

### Lights, Wall Switches: Acceptable

The wall switches are functional.

### Lights, Wall Switches: Acceptable

The ceiling lights are functional.

### Valves and Connectors: Acceptable

The kitchen valves and connectors below the sink appear functional. Valves were not turned, however no leaking was noted at the time of inspection. Valves are not in daily use and will inevitably become stiff or frozen.

### Flooring: Acceptable

The floor is in satisfactory condition and has no significant visible defects.

## Observations

### 9.4.1 Countertop

 Cosmetic - Monitor - Maintenance

### MISSING OR DETERIORATED CAULK/GROUT

The caulking or grout for the backsplash is missing, has gaps and/or not installed properly. We advise caulking/grout be installed and/or gaps filled to prevent possible water intrusion.

#### Recommendation

#### Recommended DIY Project



## 9.4.2 Countertop

**BACKSPLASH MINOR DAMAGED**

The backsplash is missing. Recommend repair.

Recommendation

Contact a qualified professional.



## 9.5.1 Exhaust Fan Notes

**EXHAUST VENT LEAK**

The exhaust vent has a gap or opening which allows air to leak out. Recommend sealing.

Recommendation

Contact a qualified professional.



## 9.8.1 Windows

**MISSING OR DAMAGED HARDWARE**

The window is missing or has damaged hardware and is in need of service to be functional.

Recommendation

Contact a qualified professional.

9.10.1 Outlets, Electrical  
Observations**MISSING COVERPLATE**

There was missing covers that should be installed.

Recommendation

Contact a qualified professional.



# 10: KITCHEN APPLIANCES

## Information

### Range: Acceptable

The range is functional.

### Range: Range type

Electric range

### Refrigerator: Acceptable

The fridge was functional and achieved acceptable fridge and freezer temperatures. This is a limited courtesy fridge inspection you should ask the sellers about its full operation. You should make sure to set your fridge at appropriate temps.

### Dishwasher: Acceptable

The dishwasher is functional, completes an entire cycle, drains properly and no leaking was noted.

### Built in Microwave: Acceptable

The built in microwave was functional during the inspection, but I did not test it for leakage, which would require a specialized instrument. However, their power diminishes over time, and the specific measurement of the microwaves, as well as their containment within the unit, requires specialized instruments, which is beyond the scope of our service.

## Observations

### 10.2.1 Dishwasher




Cosmetic - Monitor - Maintenance

### NO AIR GAP/HIGH LOOP

Dishwasher drain pipe was installed without an air gap/high loop to prevent cross contamination. Recommend a qualified licensed professional evaluate and or repair.

Recommendation

Recommended DIY Project



### 10.3.1 Garbage Disposal



Recommendations

### FROZEN

The kitchen garbage disposal is frozen or does not work properly, most likely from inactivity. However, it is not uncommon for them to continue freeze up, in which case they must be replaced.

Recommendation

Contact a qualified handyman.



# 11: BATHROOMS

## Information

### Sink and Faucet: Acceptable

The sinks were functional.

### Trap and Drain: Acceptable

The trap and drain are functional. No leaking was noted.

### Toilet: Acceptable

The toilets were functional, flushes properly and no leaking noted.

### Countertop: Acceptable

The countertops were functional.

### Cabinets: Acceptable

The cabinets are functional, and do not have any significant damage.

### Doors: Acceptable

The door(s) are functional.

### Walls and Ceiling: Acceptable

The walls and ceiling are textured drywall and in acceptable condition.

### Lights, Wall Switches: Acceptable

The ceiling/wall lights are functional.

### Lights, Wall Switches: Acceptable

The wall switches are functional.

### Outlets, Electrical Observations: Serviceable HVAC: Acceptable

All tested Outlets were serviceable. Any exceptions will be noted.

Heating was acceptable.

## Bathroom Photos

These photos are to show the condition of the bathrooms at the time of the inspection.



### Bathrooms In Acceptable Condition

The bathrooms are overall in acceptable and serviceable condition. Any exceptions will be noted in their perspective areas.

### Valves and Connectors: Acceptable

The valves and connectors below the sink appear functional. Valves were not turned, however no leaking was noted at the time of inspection. Valves are not in daily use and will inevitably become stiff or frozen.

### Flooring: Acceptable

The floor is in satisfactory condition and has no significant visible defects.

## Observations

11.1.1 Sink and Faucet

Recommendations

**OVERFLOW LEAK**

2ND FLOOR BATHROOM

The overflow drain on the sink was leaking. The sink should be replaced to restore proper function.

Recommendation

Contact a qualified professional.



11.1.2 Sink and Faucet

Recommendations

**LOW WATER PRESSURE**

MASTER BATHROOM

The water pressure was low. Recommend further evaluation to determine the cause and repair as needed.

Recommendation

Contact a qualified professional.



11.1.3 Sink and Faucet

Cosmetic - Monitor - Maintenance

**SINK HAS SCRATCHES/CHIPS**

MASTER BATHROOM

The sink has scratches or chips which should be monitored or repaired.

Recommendation

Contact a qualified countertop contractor.



11.1.4 Sink and Faucet

Recommendations

**SINK STOPPER(S) MISSING**

MASTER BATHROOM

Sink stoppers should be installed if desired.

Recommendation

Contact a qualified handyman.



11.4.1 Tub-Shower

Cosmetic - Monitor - Maintenance

**MISSING OR DETERIORATED CAULK/GROUT**

The tub surround is has missing or deteriorated caulk/grout. Recommend caulking or sealing to prevent moisture intrusion.

Recommendation

Contact a qualified professional.



11.4.2 Tub-Shower

### TUB VALVE INOPERABLE

3RD FLOOR HALLWAY BATHROOM

The tub valve is inoperable. We recommend repair or replacement to resume design function.

Recommendation

Contact a qualified professional.

 Recommendations



11.8.1 Exhaust Fan

### EXHAUST FAN DID NOT WORK ON DEMAND

2ND FLOOR BATHROOM

The bathroom exhaust fan does not respond properly to the control switch, and should be serviced.

Recommendation

Contact a qualified handyman.

 Recommendations



# 12: LAUNDRY

## Information

---

### Washer & Dryer: Equipment photos



### Washer & Dryer: Dryer power source

220 Electric

### Doors: Acceptable

The door is functional.

### Walls & Ceiling: Acceptable

The walls and ceiling are in acceptable condition.

### Cabinets and Shelves: Acceptable

The shelves are satisfactory

### Cabinets and Shelves: Acceptable

The cabinets are functional.

### Lights, Wall Switches: Acceptable

The ceiling lights are functional.

### Lights, Wall Switches: Acceptable

The wall switches are functional.

### Outlets, Electrical Observations: Serviceable

### Washer & Dryer: Washer acceptable

At the time of inspection the washer was working. It was ran momentarily on one cycle and appeared to be working correctly. This is a limited washer inspection and you should ask the seller about all the appliances and ask about any issues.

### Washer & Dryer: Dryer acceptable

The dryer was briefly tested and produced heat and appeared to be working on at least one cycle. Efficiency or capability was not tested. This is a limited Dryer inspection and you should ask the seller about all the appliances.

### Dryer Vent: Acceptable

The visible dryer vent connection appears correct. NOTE: Faulty dryer vents have been responsible for thousands of fires, hundreds of injuries, and even deaths. The best vents are a smooth-walled metal type that travels a short distance; all other types should be regarded as suspect, and should be inspected bi-annually to ensure that they do not contain trapped lint or moisture.

### 220 Volt Receptacle: 220 In-Use

The 220 volt receptacle for the dryer is in use and power supply was verified at the outlet. I recommend you should evaluate this outlet style to be sure the dryer you plan on using here is compatible with it.

### Trap & Drain: Acceptable

The washing machine drain line appears satisfactory but is not visible because it's behind or within the wall.

### Valves & Connectors: Acceptable

The washing machine valves and connectors appear functional but were not tested. No leaking was noted. However, because they are not in daily use they typically become stiff or frozen.

### Flooring: Acceptable

The floor is in satisfactory condition and has no significant visible defects.

## Observations

---

### 12.6.1 Exhaust Fan

#### **EXHAUST FAN DID NOT WORK ON DEMAND**

The laundry exhaust fan does not respond properly to the control switch, and should be serviced.



Recommendations



### 12.12.1 Outlets, Electrical Observations

#### **MISSING COVERPLATE**

A switch or outlet is missing a cover and one should be installed

Recommendation

Contact a qualified handyman.



Cosmetic - Monitor - Maintenance



# 13: INTERIORS, WINDOWS & DOORS

## Information

### Doors: Acceptable

The door(s) are functional.

### Walls and Ceiling: Acceptable

The walls and ceiling are textured drywall and in acceptable condition.

### Windows: Acceptable

The windows are functional.

### Closet: Acceptable

The door(s) are functional.

### Closet: Acceptable

The closet was inspected and appeared to be in acceptable condition

### Fireplace Notes: Type of fireplace & Photo

Wood Burning



### Lights, Wall Switches: Acceptable

The wall switches are functional.

### Lights, Wall Switches: Acceptable

The ceiling lights are functional.

### Outlets, Electrical: Acceptable

The outlets were functional and grounded. Exceptions will be noted.

### Outlets, Electrical: Light switches acceptable

The light switches were functional during the inspection.

### General Notes: Interior Photos

These photos are to show the condition of the interiors at the day of the inspection.



### General Notes: Bedrooms Photos

These photos are to show the condition of the bedrooms at the time of the inspection.



**General Notes: Interiors in Acceptable condition**

Windows, doors, floor and fixtures were overall in acceptable and serviceable condition. This also includes wall, ceilings and other surfaces. Any exceptions will be noted in their perspective areas.

**Flooring: Acceptable**

The floor is in satisfactory condition and has no significant visible defects.

**Smoke & CO Detectors Notes: The smoke detectors Present**

The smoke detectors were located where minimally required. Our recommendation is that they be installed in each bedroom, outside of sleeping areas, and at least one on each floor. They should be checked periodically.

**Fireplace Notes: Wood Burning Fireplace Acceptable**

The Wood burning fireplace appeared to be in functional condition. Note that lighting fires is not part of a home inspection.

The National Fire Protection Association has stated that an in-depth Level 2 chimney inspection should be part of every sale or transfer of property with a wood-burning device. Such an inspection may reveal defects that are not apparent to the home inspector. This is our recommendation as well.

**Handrails & Guardrails: Acceptable**

The handrail or guardrail on the stairs is satisfactory and in good condition.

**Floor Treads & Risers: Acceptable**

The stair treads and risers appear satisfactory. The rise should not be less than 4 inches, nor greater than 7 inches, and the treads should not be less than 11 inches. In addition, the dimensions of the treads and the risers should not exceed 3/8 of an inch from the smallest dimension on the entire run of the stairs.

**GFCI Notes: GFCI OK**

GFCI (Ground Fault Circuit Interrupter) protection was installed for all of the receptacles where this type of protection was required at the time of the dwellings construction. All suggested locations include garages, bathrooms, kitchens, laundry rooms, and all other locations with plumbing fixtures. We recommend testing these devices on a monthly basis.

**GFCI Notes: GFCI Overview**

GFCI (ground fault circuit interrupter) protection is a modern safety device designed to help prevent shock hazards. GFCI breakers and receptacle's function is to de-energize a circuit or a portion of a circuit when a hazardous condition exists. GFCI protection is inexpensive and can provide a substantial increased margin of safety.

Present requirement standards include receptacles near sink and wash basins. In Bathrooms, Kitchen, Garages, Exterior, Crawl Spaces and sump pump equipment.

## Observations

---

### 13.5.1 Windows

#### **BROKEN SEALS**

##### MASTER BEDROOM

A window(s) has broken hermetic seals, and should be replaced. This is evident from fogging, or condensation forming between the panes of glass, that confirm that the seal has failed. If you are concerned we recommend that you have a professional check out all the windows within the residence.



Recommendation

Contact a qualified window repair/installation contractor.

13.7.1 Smoke & CO Detectors Notes

 Safety Items - Immediate Actions

**ADD CARBON MONOXIDE DETECTOR**

In order to ensure that your home has maximum protection, it's important to have a **CO detector** on every floor. **Carbon monoxide detectors** can get the best reading of your home's air when they are **placed per manufacturer's instructions**.

Recommendation

Contact a qualified handyman.

13.7.2 Smoke & CO Detectors Notes

 Safety Items - Immediate Actions

**THE SMOKE DETECTORS MISSING**

GARAGE

The smoke detector is missing and should be installed as a fire safety feature.



Recommendation

Contact a qualified handyman.


13.11.1 Lights, Wall Switches

 Cosmetic - Monitor - Maintenance

**LIGHT NOT WORKING**

3RD FLOOR HALLWAY

A light fixture did not have light bulbs or the bulbs were burnt out. Recommend replacing bulbs and testing.



Recommendation

Contact a qualified handyman.

13.12.1 Outlets, Electrical

 Cosmetic - Monitor - Maintenance

**MISSING COVERS**

3RD FLOOR LEFT REAR BEDROOM

There were missing covers that should be installed



Recommendation

Contact a qualified handyman.

# 14: ATTIC

## Information

### Attic Access Location

Hallway

### Insulation Notes: Acceptable

Insulation is acceptable

### Insulation Notes: Insulation Type

Blown, Fiberglass

### Plumbing Vents: Acceptable

The accessible plumbing vents were in acceptable condition.

### Attic Photos



### General Info

In accordance with our standards, we do not attempt to enter attics that have less than thirty-six inches of headroom, are restricted by ducts, or in which the insulation obscures the joists and thereby makes mobility hazardous, in which case we would inspect them as best we can from the access point. In regard to evaluating the type and amount of insulation on the attic floor, we use only generic terms and approximate measurements, and do not sample or test the material for specific identification. Also, we do not disturb or move any portion of it, and it may well and often does obscure water pipes, electrical conduits, junction boxes, exhaust fans, heating and cooling ducts and other components.

### Method of Evaluation: From Hatch Only

The attic was evaluated from the access due to inadequate clearance or risk of damage to insulation and other components.

### Framing Notes: Factory-built truss system - Acceptable

The roof framing is in satisfactory condition. The roof framing consists of a factory- built wood truss system, comprised of components called chords, webs, and struts that are connected by metal gussets nailed in place. Each component of the truss is designed for a specific purpose, and cannot be removed or modified without compromising the integrity of the entire truss. The lowest component, which is called the chord and to which the ceiling is attached, can move by thermal expansion and contraction and cause creaking sounds, which are more pronounced in the mornings and evenings along with temperature changes. Such movement has no structural significance, but can result in small cracks or divots in the drywall or plaster.

### Roof Decking Notes: OSB decking-Acceptable

The visible portions of the oriented strand board roof or OSB decking are in acceptable condition and should conform to the standards of the year in which they were installed.

### Electrical Notes: Attic electrical-Acceptable

The attic electrical components that are easily visible and not covered by insulation appear to be in acceptable condition.

### Ventilation: Ventilation - Acceptable

Ventilation is provided by a combination soffit, gable or roof vents and should be adequate. However, contacting a qualified insulation contractor about having your attic ventilation upgraded could help lower energy costs by cooling down your attic during the warmer summer months.

## Observations

### 14.3.1 Roof Decking Notes

 Cosmetic - Monitor - Maintenance

#### DECK STAINING

Discoloration and dark staining was observed on the roof sheathing. This is often caused by poor ventilation and is commonly considered a microbial growth. Recommend improving ventilation and cleaning.



### 14.3.2 Roof Decking Notes

 Cosmetic - Monitor - Maintenance

#### H-CLIPS NOT USED

This roof is lacking adequate spacing or "H" clips between sheets of sheathing as is common practice in modern construction.

NOTE: This roof could have possible buckling in some areas in the future as the dwelling ages. The panels will expand as they absorb moisture and buckle if there is no room for expansion. We recommend repairs when re-roofing or only if necessary.

Recommendation

Contact a qualified professional.

### 14.6.1 Common Observations

 Recommendations

#### RODENT ACTIVITY

The attic has evidence of rodent activity. We recommend ceiling access points in eliminating any active rodent activity



### 14.7.1 Exhaust Ducts

 Recommendations

#### BATHROOM EXHAUST SEPARATED NEEDS REPAIR

The bathroom exhaust duct is separated, and should be repaired.



### 14.8.1 Ventilation

 Cosmetic - Monitor - Maintenance

#### LIMITED VENTILATION

Ventilation is limited, and could be improved. Therefore, we recommend that you have a second opinion from a licensed contractor. Contacting a qualified insulation contractor about having your attic ventilation upgraded could help lower energy costs by cooling down your attic during the warmer summer months.

# 15: GENERAL COMMENTS

## Information

---

### General Info

This report is the exclusive property of Mountains to Sound Home Inspection, LLC and the client whose name appears herewith, and its use by any unauthorized persons is strictly prohibited.

The observations and opinions expressed in this report are those of Mountains to Sound Home Inspection, LLC and supersede any alleged verbal comments. I inspect all of the systems, components, and conditions described in accordance with the standards of the Washington State Home Inspector Standards of Practice and those that I do not inspect are clearly disclaimed in the contract and/or in the aforementioned standards. However, some components that are inspected and found to be functional may not necessarily appear in the report, simply because we do not wish to waste our client's time by having them read an unnecessarily lengthy report about components that do not need to be serviced.

In accordance with the terms of the contract, the service recommendations that I make in this report should be completed well before the close of escrow by licensed specialists, who may well identify additional defects or recommend some upgrades that could affect your evaluation of the property.

This report has been produced in accordance with our signed contract and is subject to the terms and conditions agreed upon therein. All printed comments and the opinions expressed herein are those of the Inspection Company.

### Scope of work

You have contracted with Mountains to Sound Home Inspection, LLC to perform a generalist inspection in accordance with the standards of practice established by the state of Washington and the International Association of Certified Home Inspectors (InterNACHI), a copy of which is available upon request. Generalist inspections are essentially visual, and distinct from those of specialists, inasmuch as they do not include the use of specialized instruments, the dismantling of equipment, or the sampling of air and inert materials. Consequently, a generalist inspection and the subsequent report will not be as comprehensive, nor as technically exhaustive, as that generated by specialists, and it is not intended to be. The purpose of a generalist inspection is to identify significant defects or adverse conditions that would warrant a specialist evaluation. Therefore, you should be aware of the limitations of this type of inspection, which is clearly indicated in the standards. However, the inspection is not intended to document the type of cosmetic deficiencies that would be apparent to the average person, and certainly not intended to identify insignificant deficiencies. Similarly, we do not inspect for vermin infestation, which is the responsibility of a licensed exterminator.

Most homes built after 1978, are generally assumed to be free of asbestos and many other common environmental contaminants. However, as a courtesy to our clients, we are including some well documented, and therefore public, information about several environmental contaminants that could be of concern to you and your family, all of which we do not have the expertise or the authority to evaluate, such as asbestos, radon, methane, formaldehyde, termites and other wood-destroying organisms, pests and rodents, molds, microbes, bacterial organisms, and electromagnetic radiation, to name some of the more commonplace ones. Nevertheless, we will attempt to alert you to any suspicious substances that would warrant evaluation by a specialist. However, health and safety, and environmental hygiene are deeply personal responsibilities, and you should make sure that you are familiar with any contaminant that could affect your home environment. You can learn more about contaminants that can affect your home from a booklet published by The Environmental Protection Agency, which you can read online at [www.epa.gov/iaq/pubs/insidest.htm](http://www.epa.gov/iaq/pubs/insidest.htm).

MOLD is one such contaminant. It is a microorganism that has tiny seeds, or spores, that are spread in the air then land and feed on organic matter. It has been in existence throughout human history and actually contributes to the life process. It takes many different forms, many of them benign, like mildew. Some characterized as allergens are relatively benign but can provoke allergic reactions among sensitive people, and others characterized as pathogens can have adverse health effects on large segments of the population, such as the very young, the elderly, and people with suppressed immune systems. However, there are less common molds that are called toxins that represent a serious health threat. All molds flourish in the presence of moisture, and we make a concerted effort to look for any evidence of it wherever there could be a water source, including that from condensation. Interestingly, the molds that commonly appear on ceramic tiles in bathrooms do not usually constitute a health threat, but they should be removed. However, some visibly similar molds that form on cellulose materials, such as on drywall, plaster, and wood, are potentially toxigenic. If mold is to be found anywhere within a home, it will likely be in the area of tubs, showers, toilets, sinks, water heaters, evaporator coils, inside attics with unvented bathroom exhaust fans, and return-air compartments that draw outside air, all

of which are areas that we inspect very conscientiously. Nevertheless, mold can appear as though spontaneously at any time, so you should be prepared to monitor your home, and particularly those areas that we identified. Naturally, it is equally important to maintain clean air-supply ducts and to change filters as soon as they become soiled because contaminated ducts are a common breeding ground for dust mites, rust, and other contaminants. Regardless, although some mold-like substances may be visually identified, the specific identification of molds can only be determined by specialists and laboratory analysis and is absolutely beyond the scope of our inspection. Nonetheless, as a prudent investment in environmental hygiene, we categorically recommend that you have your home tested for the presence of any such contaminants, and particularly if you or any member of your family suffers from allergies or asthma. Also, you can learn more about mold from an Environmental Protection Agency document entitled "A Brief Guide to Mold, Moisture, and Your Home," by visiting their website at: <http://www.epa.gov/iaq/molds/moldguide.html/>, from which it can be downloaded.

ASBESTOS is a notorious contaminant that could be present in any home built before 1978. It is a naturally occurring mineral fiber that was first used by the Greek and Romans in the first century, and it has been widely used throughout the modern world in a variety of thermal insulators, including those in the form of paper wraps, bats, blocks, and blankets. However, it can also be found in a wide variety of other products too numerous to mention, including duct insulation and acoustical materials, plasters, siding, floor tiles, heat vents, and roofing products. Although perhaps recognized as being present in some documented forms, asbestos can only be specifically identified by laboratory analysis. The most common asbestos fiber that exists in residential products is chrysotile, which belongs to the serpentine or white-asbestos group, and was used in the clutches and brake shoes of automobiles for many years. However, a single asbestos fiber is said to be able to cause cancer and is, therefore, a potential health threat and a litigious issue. Significantly, asbestos fibers are only dangerous when they are released into the air and inhaled, and for this reason authorities such as the Environmental Protection Agency [EPA] and the Consumer Product Safety Commission [CPSC] distinguish between asbestos that is in good condition, or non-friable, and that which is in poor condition, or friable, which means that its fibers could be easily crumbled and become airborne. However, we are not specialists and, regardless of the condition of any real or suspected asbestos-containing material [ACM], we would not endorse it and recommend having it evaluated by a specialist.

POPCORN CEILING- In early formulations, it often contained white asbestos fibers. When asbestos was banned in ceiling treatments by the Clean Air Act of 1978 in the United States,[1] popcorn ceilings fell out of favor in much of the country. However, in order to minimize economic hardship to suppliers and installers, existing inventories of asbestos-bearing texturing materials were exempt from the ban, so it is possible to find asbestos in popcorn ceilings that were applied through the 1980s. According to the EPA, the use of asbestos in textured ceiling paint was banned in 1977. Inhaled in large quantities, asbestos fibers can cause lung disease, scarring of the lungs and lung cancer. However, not all popcorn ceilings contain asbestos. Moreover, if left undisturbed or contained, asbestos is not dangerous.

RADON is a gas that results from the natural decay of radioactive materials in the soil and is purported to be the second leading cause of lung cancer in the United States. The gas is able to enter homes through the voids around pipes in concrete floors or through the floorboards of poorly ventilated crawlspaces, and particularly when the ground is wet and the gas cannot easily escape through the soil and be dispersed into the atmosphere. However, it cannot be detected by the senses, and its existence can only be determined by sophisticated instruments and laboratory analysis, which is completely beyond the scope of our service. However, you can learn more about radon and other environmental contaminants and their effects on health, by contacting the Environmental Protection Agency (EPA), at [www.epa.gov/radon/images/hmbuygud.pdf](http://www.epa.gov/radon/images/hmbuygud.pdf), and it would be prudent for you to inquire about any high radon readings that might be prevalent in the general area surrounding your home.

LEAD poses an equally serious health threat. In the 1920's, it was commonly found in many plumbing systems. In fact, the word "plumbing" is derived from the Latin word "plumbum," which means lead. When in use as a component of a waste system, it is not an immediate health threat, but as a component of potable water pipes, it is a definite health hazard. Although rarely found in modern use, the lead could be present in any home build as recently as the nineteen forties. For instance, lead was an active ingredient in many household paints, which can be released in the process of sanding, and even be ingested by small children and animals chewing on painted surfaces. Fortunately, the lead in painted surfaces can be detected by industrial hygienists using sophisticated instruments, but testing for it is not cheap. There are other environmental contaminants, some of which we have already mentioned, and others that may be relatively benign. However, we are not environmental hygienists, and as we stated earlier we disclaim any responsibility for testing or establishing the presence of any environmental contaminant, and recommend that you schedule whatever specialist inspections that may deem prudent within the contingency period.

CRACKS AND WINDOWS Unsealed cracks around windows, doors, and thresholds can permit moisture intrusion, which is the principal cause of the deterioration of any surface. Unfortunately, the evidence of such intrusion may only be obvious when it is raining. We have discovered leaking windows while it was raining that may not

have been apparent otherwise. Regardless, there are many styles of windows but only two basic types, single and dual-glazed. Dual-glazed windows are superior because they provide a thermal as well as an acoustical barrier. However, the hermetic seals on these windows can fail at any time, and cause condensation to form between the panes. Many environmental factors come into play when and if hermetic seals have failed and Unfortunately, it is not always apparent, which is why we disclaim an evaluation of hermetic seals or unnoticed fogging glass. Nevertheless, in accordance with industry standards, we test a representative number of unobstructed windows and ensure that at least one window in every bedroom is operable and facilitates an emergency exit.

FURTHERMORE, you are advised to seek two professional opinions and acquire estimates of repair as to any defects, comments, improvements or recommendations mentioned in this report. We recommend that the professional making any repairs inspect the property further in order to discover and repair related problems that were not identified in the report. We recommend that all repairs, corrections, and cost estimates be completed and documented prior to closing or purchasing the property. Feel free to hire other professionals to inspect the property prior to closing. Including HVAC professionals, electricians, engineers, window professionals roofers etc.

All conditions are reported as they existed at the time of the inspection. The information contained in this report may be unreliable beyond the date of the inspection due to changing conditions.

# 16: REASONABLE EXPECTATIONS OF A HOME INSPECTION

## Information

---

### Setting Reasonable Expectations

Setting Reasonable Expectations When Things Go Wrong.

There may come a time that you discover something wrong with the house, and you may be upset or disappointed with your home inspection.

### Intermittent Or Concealed Problems

Some problems can only be discovered by living in a house. They cannot be discovered during the few hours of a home inspection. For example, some shower stalls leak when people are in the shower, but do not leak when you simply turn on the tap. Some roofs and basements only leak when specific conditions exist. Some problems will only be discovered when carpets were lifted, furniture is moved or finishes are removed.

### No Clues

These problems may have existed at the time of the inspection but there were no clues as to their existence. Our inspections are based on the past performance of the house. If there are no clues of a past problem, it is unfair to assume we should foresee a future problem.

### We Always Miss Some Minor Things

Some say we are inconsistent because our reports identify some minor problems but not others. The minor problems that are identified were discovered while looking for more significant problems. We note them simply as a courtesy. The intent of the inspection is not to find the \$200 problems; it is to find the \$2,000 problems. These are the things that affect peoples decisions to purchase.

### Contractors Advice

The main source of dissatisfaction with home inspectors comes from comments made by contractors. Contractors opinions often differ from ours. Dont be surprised when three roofers all say the roof needs replacement when we said that, with some minor repairs, the roof will last a few more years.

### Last Man In Theory

While our advice represents the most prudent thing to do, many contractors are reluctant to undertake these repairs. This is because of the Last Man In Theory. The contractor fears that if he is the last person to work on the roof, he will get blamed if the roof leaks, regardless of whether the roof leak is his fault or not. Consequently, he wont want to do a minor repair with high liability when he could re-roof the entire house for more money and reduce the likelihood of a callback. This is understandable.

### Most Recent Advice Is Best

There is more to the Last Man In Theory. It suggests that it is human nature for homeowners to believe the last bit of expert advice they receive, even if it is contrary to previous advice. As home inspectors, we unfortunately find ourselves in the position of First Man In and consequently it is our advice that is often disbelieved.

### Why Didnt We See It

Contractors may say I cant believe you had this house inspected, and they didnt find this problem. There are several reasons for these apparent oversights:

#### 1. Conditions During Inspection

It is difficult for homeowners to remember the circumstances in the house, at the time of the inspection. Homeowners seldom remember that it was snowing, there was storage everywhere in the basement or that the

furnace could not be turned on because the air conditioning was operating, et cetera. Its impossible for contractors to know what the circumstances were when the inspection was performed.

## **2. The Wisdom Of Hindsight**

When the problem manifests itself, it is very easy to have 20/20 hindsight. Anybody can say that the basement is wet when there is 2 inches of water on the floor. Predicting the problem is a different story.

## **3. A Long Look**

If we spent 1/2 an hour under the kitchen sink or 45 minutes disassembling the furnace, wed find more problems too. Unfortunately, the inspection would take several days and would cost considerably more.

## **4. Were Generalists**

We are generalists; we are not specialists. The heating contractor may indeed have more heating expertise than we do.

## **5. An Invasive Look**

Problems often become apparent when carpets or plaster are removed, when fixtures or cabinets are pulled out, and so on. A home inspection is a visual examination. We dont perform any invasive or destructive tests.

## **Not Insurance**

In conclusion, a home inspection is designed to better your odds. It is not designed to eliminate all risk. For that reason, a home inspection should not be considered an insurance policy. The premium that an insurance company would have to charge for a policy with no deductible, no limit and an indefinite policy period would be considerably more than the fee we charge. It would also not include the value added by the inspection.

We hope this is food for thought.

# 17: REPORT CONCLUSION

## Information

---

### Conclusion

Congratulations on the purchase of your new home. Since we never know who will be occupying or visiting a property, whether it be children or the elderly, we ask you to consider following these general safety recommendations: install and monitor smoke and carbon monoxide detectors; identify all escape and rescue ports; rehearse an emergency evacuation of the home; upgrade older electrical systems (if present) by at least adding ground-fault outlets; never service any electrical equipment without first disconnecting its power source; safety-film all non-tempered glass; ensure that every elevated window and the railings of stairs, landings, balconies, and decks are child-safe, meaning that barriers are in place or that the distance between the rails is not wider than three inches; regulate the temperature of water heaters to prevent scalding; make sure that goods that contain caustic or poisonous compounds, such as bleach, drain cleaners, and nail polish removers be stored where small children cannot reach them; ensure that all garage doors are well balanced and have a safety device, particularly if they are the heavy wooden type; remove any double-cylinder deadbolts from exterior doors; and consider installing child-safe locks and alarms on the exterior doors of all pool and spa properties.

We are proud of our service and trust that you will be completely satisfied with the quality of our report. We have made every effort to provide you with an accurate assessment of the condition of the property and its components and to alert you to any significant defects or adverse conditions. However, we may not have tested every outlet, and opened every window and door, or identified every minor defect. Also because we are not specialists or because our inspection is essentially visual, latent defects could exist. Therefore, you should not regard our inspection as conferring a guarantee or warranty. It does not. It is simply a report on the general condition of a particular property at a given point in time. Furthermore, as a homeowner, you should expect problems to occur. Roofs will leak, drain lines will become blocked, and components and systems will fail without warning. For these reasons, you should take into consideration the age of the house and its components and keep a comprehensive insurance policy current. If you have been provided with a home protection policy, read it carefully. Such policies usually only cover insignificant costs, such as that of roofer service, and the representatives of some insurance companies can be expected to deny coverage on the grounds that a given condition was preexisting or not covered because of what they claim to be a code violation or manufacturers defect. Therefore, you should read such policies very carefully, and depend upon our company for any consultation that you may need.

FURTHERMORE, you are advised to seek two professional opinions and acquire estimates of repair as to any defects, comments, improvements or recommendations mentioned in this report. We recommend that the professional making any repairs inspect the property further in order to discover and repair related problems that were not identified in the report. We recommend that all repairs, corrections, and cost estimates be completed and documented prior to closing or purchasing the property. Feel free to hire other professionals to inspect the property prior to closing. Including HVAC professionals, electricians, engineers, window professionals roofers etc.

Thank you for taking the time to read this report, and call us if you have any questions or observations whatsoever. I am always attempting to improve the quality of my service and this report, and I will continue to adhere to the highest standards of the real estate industry and to treat everyone with kindness, courtesy, and respect.

---

# STANDARDS OF PRACTICE

---

## **Exterior**

This inspection is not intended to address or include any geological conditions or site stability information. For information concerning these conditions a geologist or soils engineer should be consulted. Any reference to grade is limited to only areas around the exterior of the exposed foundation or exterior walls. This inspection is visual in nature and does not attempt to determine drainage performance of the site or the condition of any underground piping, including municipal water and sewer service piping or septic systems.

When decks and porches are built close to the ground where no viewing or access is possible, we cannot make accurate opinions. These areas as well as others that are too low to enter, or in some other manner not accessible, are excluded from the inspection and are not addressed in this report. We routinely recommend that inquiry be made with the seller about knowledge of conditions, repairs are usually noted in the form seventeen.

Our inspection of the Exterior grounds includes the surface drainage, grading, some fencing, gates, sidewalks, patios, driveways, and retaining walls adjacent to the structure. The inspection of the exterior of the building includes the cladding, trim, eaves, fascias, decks, porches, downspouts, railings, doors, windows and flashings. Areas hidden from view by finished walls or stored items can not be judged and are not a part of this inspection. Minor cracks are typical in many foundations and most do not represent a structural problem. If major cracks are present along with rotation, we routinely recommend further evaluation be made by a qualified professional structural engineer. All exterior grades should allow for surface and roof water to flow away from the foundation. All concrete slabs experience some degree of cracking due to shrinkage in the drying process or minor settlement.

Where deck carpeting, stacked firewood, excessive vegetation, soil and other coverings are installed, the materials or their nature of construction and condition of the underneath cannot be determined. All items listed are inspected for their proper function, poor installation, excessive wear and general state of repair.

## **Roof**

The inspection of the roof system includes a visual examination of the surface materials, connections, penetrations and roof drainage systems. We examine the roofing material for damage and deterioration. We examine the roof system for possible leaks, damage and conditions that suggest limited remaining service life. We may offer opinions concerning repair and/or replacement if warranted. Opinions stated herein concerning the roofing material are based on the general condition of the roof system as evidenced by our visual inspection.

These do not constitute a warranty that the roof is or will remain, free of leaks. All roofing systems require annual maintenance. Failure to perform routine maintenance will usually result in leaks and accelerated deterioration of the roof covering and flashings. When provided, our estimates of the roof's life expectancy are based on the assumption that the roof will be properly maintained during that period.

This report is issued in consideration of a foregoing disclaimer in the future. The only way to determine whether a roof is absolutely water tight is to observe it during a prolonged rainfall. Many times, this situation is not present during the inspection and we cannot confirm this condition. We suggest that an annual inspection of the Attic area be performed where accessible to identify if any leaks are evident.

## **Garage(s)**

The Garage is inspected as best as possible, but can be limited due to parked cars or personal stored items. Due to this area being cluttered or areas being inaccessible, it is common for sections that cannot be fully inspected or items identified during our limited inspection. We suggest that a walk-through be performed once the home is vacant. If this is a new construction inspection or vacant home this area will be inspected thoroughly. Determining the heat resistance rating of fire walls and doors is beyond the scope of this inspection. Flammable materials should not be stored within the Garage area if possible.

## **Main Electrical Panel**

Our examination of the electrical system includes a visual examination of the exposed and accessible branch circuits, wiring, service panel, over current protection devices, lighting fixtures, switches, and receptacles. Service equipment, proper grounding, wiring methods and bonding are focal points. We inspect for adverse conditions such as improper installation of aluminum wiring, lack of grounding and bonding, over-fusing, exposed wiring, open-air wire splices, reverse polarity and defective GFCI's. The hidden nature of the electrical wiring prevents inspection of every length of wire or their connections. Telephone, video, cable, audio, security systems and other low voltage systems were not included in this inspection unless specifically noted. We recommend you have the seller or a specialist demonstrate the serviceability or locations of these systems to you if necessary.

Any electrical repairs attempted by anyone other than a licensed electrician should be approached with caution. The power to the entire house should be turned off prior to beginning any repair efforts, no matter how trivial the repair may seem. Aluminum wiring requires periodic inspection and maintenance by a licensed electrician. Operation of time clock motors is not verified. Inoperative light fixtures often lack bulbs or have dead bulbs installed. Light bulbs are not changed during the inspection, due to time constraints. Smoke Alarms should be installed within 15 feet of all Bedroom doors and in Bedrooms. These units should be tested monthly.

### **Electric Heating System**

Our examination of the heating system includes a visual examination of the exposed and accessible heating equipment, thermostat, safety controls, venting and the means of air distribution. Our inspection of the heating system includes activating the heating system via the thermostat and a visual examination of the accessible components listed below.

These items are examined for proper function, excessive or unusual wear and general state of repair. Heat exchangers are inaccessible by design, and are not part of the Washington standards of practice. They must be completely removed from the furnace to be fully evaluated. Our inspection does not include disassembly of the furnace. The inspector cannot light pilot lights due to the liability. Safety devices are not tested by the inspector. To obtain maximum efficiency and reliability from your heating system, we recommend annual servicing and inspections by a qualified heating specialist.

Determining the condition of oil tanks, whether exposed or buried, is beyond the scope of this inspection. Leaking oil tanks represent an environmental hazard which is sometimes a costly condition to address.

### **Water Heater & Plumbing**

Our inspection of the water heater includes a visual examination of the accessible portions of the tank, gas, electrical and/or water connections, venting and safety valves. These items are examined for proper function, excessive or unusual wear, leakage and general state of repair.

Our Inspection of the plumbing system includes a visual examination of the exposed portions of the domestic water supply, drain waste, vent, gas lines, faucets, fixtures, valves, drains, traps, exposed pipes and fittings. These items are examined for proper function, excessive or unusual wear, leakage and general state of repair. The hidden nature of piping prevents inspection of every pipe and joint connection, especially in walls, floors and ceiling voids. A sewer lateral test is necessary to determine the condition of the underground sewer lines is beyond the scope of this inspection.

Our review of the plumbing system does not include landscape irrigation systems, water wells, on site and/or private water supply systems, off site community water supply systems, or private (septic) waste disposal systems unless specifically noted. Review of these systems could be performed by qualified specialists prior to closing of escrow.

### **Kitchen**

Inspection of the stand alone refrigerators, freezers and built-in ice makers are outside the scope of the inspection. No opinion is offered as to the adequacy of dishwasher operation. Ovens, self or continuous cleaning operations, cooking functions, clocks, timing devices, lights and thermostat accuracy are not tested during this inspection. Appliances are not moved during the inspection to inspect below or behind them. Portable dishwashers are not inspected, as they require connection to facilitate testing and are sometimes not left with the home.

### **Bathrooms**

Our inspection of the bathrooms included a visual examination of the readily accessible portions of the floors, walls, ceilings, cabinets, countertops and plumbing fixtures. Bathrooms are inspected for water drainage, damage, deterioration to floor and walls, proper function of components, active leakage, unusual wear and general state of repair. Bathroom fixtures are run simultaneously to check for adequate water flow and pressure. Fixtures are tested using normal operating controls. Vent fans and their duct work are tested for their proper operation and examined where visible.

Shower pans are visually checked for leakage, but leaks often do not show except when the shower is in actual use. Determining whether shower pans, tub/shower surrounds are water tight is beyond the scope of this inspection. It is very important to maintain all grouting and caulking in the bath areas. Very minor imperfections can allow water to get into the wall or floor areas and cause damage. Proper ongoing maintenance will be required in the future.

### **Interiors, Windows & Doors**

Our inspection of the Interior includes a visual inspection of the readily accessible portions of the walls, ceilings, floors, doors, cabinetry, countertops, steps, stairways, balconies and railings. Please note that a representative sample of the accessible windows and electrical receptacles are inspected. These features are examined for proper function, excessive wear and general state of repair. In some cases, all or portions of these components may not be

visible because of furnishings and personal items. In these cases some of the items may not be inspected.

The condition of walls behind wall coverings, paneling and furnishings cannot be judged. Only the general condition of visible portions of floors is included in this inspection. As a general rule, cosmetic deficiencies are considered normal wear and tear and are not reported. Determining the source of odors or like conditions is not a part of this inspection. Floor covering damage or stains may be hidden by furniture. The condition of floors underlying floor coverings is not inspected. Determining the condition of insulated glass windows is not always possible due to temperature, weather and lighting conditions. Check with owners for further information. All fireplaces should be cleaned and inspected on a regular basis to make sure that no cracks have developed. Large fires in the firebox can overheat the firebox and flue liners, sometimes resulting in internal damage.

### **Attic**

Our inspection of the Attic includes a visual examination of the roof framing, plumbing, electrical and mechanical systems. There are often heating ducts, bathroom vent ducts, electrical wiring, chimneys and appliance vents in the Attic. We examined these systems and components for proper function, unusual wear and general state of repair, leakage, venting and unusual or improper improvements. When low clearances and deep insulation prohibits walking in an unfinished Attic, inspection will be from the access opening only. Vaulted ceilings cannot be inspected.