



616-836-2208 bluehousehi@gmail.com https://www.bluehousehomeinspections.com/



RESIDENTIAL HOME INSPECTION

1544 Lark Lane St SE Kentwood MI 49508

> Kendal Wabeke AUGUST 12, 2020



Inspector Kendal Wabeke

InterNACHI Certified Home Inspector 616-836-2208 bluehousehi@gmail.com

TABLE OF CONTENTS

1: Inspection Details	5
2: Basement, Foundation, Crawlspace & Structure	6
3: Roof	9
4: Exterior	9
5: Heating	13
6: Cooling	16
7: Plumbing	17
8: Electrical	20
9: Attic, Insulation & Ventilation	22
10: Kitchen and Appliances	23
11: Built-in Appliances	25
12: Doors, Windows & Interior	27
13: Garage	28



How to Read this Report:

Thank you for the opportunity to conduct your home inspection. The function of this report is to help you make an informed decision about your purchase. The report contains a review of the major and minor components of the home including many comments which are meant to help you further understand certain conditions observed. It is important that you read the report in its entirety to obtain a full understanding of the scopek limitations, and exclusions of the inspection.

The following three categories are used throughout the report based on observations at the time of the inspection:



Minor Concerns are noted in blue and are items that were found to be in need of recurring or basic general maintenance and/or may need minor repairs which may improve their functionality.



Moderate Concerns are noted in orange and are items that were found to include a deficiency. These items may have impaired functionality or a defect that may

lead to further problems. Repairs or replacement is recommended on these items to avoid future problems that may occur due to the defect.



Major Concerns are noted in red and are items that may require a major expense to correct and/or be a safety concern. These items may require further evaluation and repairs or replacement by a qualified

professional.

Certifications:

Kendal Wabeke is certified by the International Association of Certified Home Inspectors (InterNACHI). Kendal has a background in engineering, property management, and construction providing the necessary skills and experience needed to analyze the components of your home.

Standards of Practice and Code of Ethics:

Blue House Home Inspections, LLC follows the International Association of Certified Home Inspector's (InterNACHI) Residential **Standards of Practice** and **Code of Ethics.**

Limitations, exceptions, and exclusions from of a home inspection can be found at the links noted above.

Please reach out to me with any questions you may have!

Thank you,

Kendal Wabeke

InterNACHI Certified Home Inspector 616-836-2208 bluehousehi@gmail.com www.bluehousehomeinspections.com

1: INSPECTION DETAILS

Information

In Attendance

Client, Client's Agent

Temperature (approximate)

68 Fahrenheit (F)

Occupancy

Furnished, Vacant

Type of Building

Single Family

Style

Ranch

Weather Conditions

Dry, Hot, Humid

2: BASEMENT, FOUNDATION, CRAWLSPACE & STRUCTURE

		IN	NI	NP	D
2.1	Foundation	Χ			Χ
2.2	Floor Structure	Χ			
2.3	Wall Structure	Χ			
2.4	Basements & Crawlspaces	Χ			Χ
2.5	Ceiling Structure	Χ			
2.6	Roof Structure & Attic	Χ			

IN = Inspected NI = Not Inspected NP = Not Present D = Deficiencies

Information

Inspection Method Foundation: Material Floor Structure: Basement Floor

Attic Access, Visual Concrete, Masonry Block Concrete, Carpet

Floor Structure: Crawlspace Floor Floor Structure: Floor Structure Floor Structure: Sub-floor

N/a **Material** Wood Rafters Plywood

Wall Structure: Wall Structure Basements & Crawlspaces: Roof Structure & Attic: Roof

Wood Stud Crawlspace Structure
N/a Wood Rafter

Roof Structure & Attic: Roof Type Roof Structure & Attic: Roof

Gable Decking Material

OSB, Plywood

Limitations

General


BASEMENT STORAGE

Visibility was very limited due to basement storage. Extensive basement storage can limit or eliminate visibility of walls and flooring and any potential past or current damages that may be present.

Deficiencies


2.1.1 Foundation

FOUNDATION CRACKS - SIGNIFICANT EXPENSE



Severe cracking noted at the foundation. This is typically consistent with soil movement and could lead to serious damage to structural components, foundation and/or slab. There were large vertical cracks through the foundation and some abnormal settling in multiple locations that should be further evaluated by a foundation/structural specialist. Vertical cracking larger than 1/8" can lead to larger structural problems and may require immediate attention or repairs.

Here is an informational article on foundation cracks.



South, Walkway and Entry

Garage



2.4.1 Basements & Crawlspaces

STANDING WATER



Observed signs that standing water may have been present on basement floor. Recommend a qualified contractor evaluate and find potential source of moisture.



3: ROOF

		IN	NI	NP	D
3.1	Coverings	Χ			
3.2	Roof Drainage Systems			Χ	
3.3	Flashings	Χ			
3.4	Skylights, Chimneys & Other Roof Penetrations	Χ			

Information

Inspection Method Ladder, Walked Roof Roof Type/Style
Gable

Coverings: Material Fiberglass



Roof Drainage Systems: Gutter Material Aluminum **Flashings: Material** Aluminum

4: EXTERIOR

4.1 Sid	ling, Flashing & Trim	Χ		
	<u> </u>	^		
4.2 Ext	rerior Doors	Χ		Χ
4.3 Wa	ılkways, Patios & Driveways	Χ		Χ
4.4 Dec	cks, Balconies, Porches & Steps	Χ		
4.5 Eav	ves, Soffits & Fascia	Χ		
4.6 Veg	getation, Grading, Drainage & Retaining Walls	Χ		Χ

Information

Inspection Method

Visual

Siding, Flashing & Trim: Siding

Material

Aluminum, Brick Veneer

Sidewalk and Walkway

Walkways, Patios & Driveways:

Driveway Material

Concrete

Walkways, Patios & Driveways:

Concrete

Siding, Flashing & Trim: Siding

Style

Traditional Lap

Decks, Balconies, Porches &

Steps: Appurtenance

Deck, Patio, Retaining Wall,

Sidewalk

Decks, Balconies, Porches &

Steps: Material Concrete, Wood

Deficiencies

4.2.1 Exterior Doors

DOOR DOES NOT CLOSE OR LATCH

BASEMENT SLIDER

The basement slider door was in need of repairs or replacement. The fixed side of the door was loose and not properly sealed in the track. Screws had been added to the bottom side of the door to try to prop in place. Sealant had been added to the exterior of the door to prevent leaking into the basement space.







Moderate Concern

4.2.2 Exterior Doors

WEATHERSTRIPPING NOT PRESENT/DAMAGED

GARAGE SERVICE DOOR

Door has missing or damaged standard weatherstripping. This can result in significant energy loss and moisture intrusion. Recommend installation of standard weatherstripping. This door latch was misaligned or not functioning and will also require adjustment/repair for proper function

Here is a DIY guide on weatherstripping.







4.3.1 Walkways, Patios & Driveways

PATIO CRACKING/SETTLING - MAJOR



FRONT ENTRY

Significant settling & cracking observed. Further deterioration could result. Recommend concrete contractor evaluate & repair.




4.3.2 Walkways, Patios & Driveways

WALKWAY CRACKING/SETTLING - MAJOR

FRONT ENTRY

Major cracks observed. Recommend concrete contractor evaluate and correct to prevent trip hazard & preserve appearance.









4.6.1 Vegetation, Grading, Drainage & Retaining Walls

OVERGROWN VEGETATION



Tree limbs, shrubs, and/or bushes overgrown against the home wall and roof coverings. Recommend keeping all tree limbs and shrubs trimmed back from the home's exterior coverings to protect the materials from potential damages and wear.





5: HEATING

		IN	NI	NP	D
5.1	Equipment	Χ			Χ
5.2	Normal Operating Controls	Χ			Χ
5.3	Distribution Systems	Χ			
5.4	Presence of Installed Heat Source in Each Room	Χ			
5.5	Carbon Monoxide Monitoring	Χ			

Information

Approximate Age Capacity Equipment: Heat Type

29 Years 75,000 BTU Forced Air

Equipment: Brand Equipment: Energy Source Distribution Systems: Heat

Goodman, Janitrol Natural Gas **Distribution**Ductwork

Distribution Systems: Ductwork
Non-insulated, Galvanized

Presence of Installed Heat Source
in Each Room: Heat Source in

Each Room

AFUE Rating

80-90%

AFUE (Annual fuel utilization efficiency) is a metric used to measure furnace efficiency in converting fuel to energy. A higher AFUE rating means greater energy efficiency. 90% or higher meets the Department of Energy's Energy Star program standard.

Furnace General Info

The furnace fired when activated by the thermostat at the time of the inspection and produced sufficient heat at tested registers throughout the home (Normal expected range is between 110-120+ degrees Fahrenheit at registers). Return air was pulling sufficient air back to the furnace (holding tissue paper against vent). Note that disposable filters should be changed at least every other month during peak usage seasons (summer cooling & winter heating). A clogged or backwards filter will decrease the efficiency of the furnace and make the unit work harder as air flow is being restricted.









Normal Operating Controls: General


We suggest regular service/preventative maintenance by a licensed HVAC contractor to help prolong the life and efficiency of the unit. Generally, the best time for service is right before start-up as the temperature drops in the Fall. Typical average lifespan of standard forced air furnace is 20-25 years

Carbon Monoxide Monitoring: CO Monitor Reading

The maximum monitored carbon monoxide (CO) measured for the duration of the inspection was 2ppm (parts per million) – no concern. Max allowable for short-term exposure is 9ppm (see chart below).








Deficiencies

5.1.1 Equipment

CORROSION







5.1.2 Equipment

NEEDS SERVICING/CLEANING



Furnaces should be cleaned and serviced annually. Recommend a qualified HVAC contractor clean, service and certify furnace.

Here is a resource on the importance of furnace maintenance.

5.2.1 Normal Operating Controls

FURNACE AGE



The furnace should be considered a potential service, repair or replacement item within the next 5 years due to its age (typical average lifespan is 20-25 years).

6: COOLING

		IN	NI	NP	D
6.1	Cooling Equipment	Χ			Χ
6.2	Normal Operating Controls	Χ			Χ
6.3	Distribution System	Χ			Χ
6.4	Presence of Installed Cooling Source in Each Room	Χ			

Information

Approximate Age Capacity Cooling Equipment: Brand


12 Years 2 Ton Goodman

Cooling Equipment: EnergyCooling Equipment: LocationDistribution System:Source/TypeExterior WestConfigurationElectric, Central Air ConditionerCentral

A/C Information

The A/C functioned properly when tested at the time of the inspection and produced sufficient cool air at tested registers throughout the home (Normal expected range is between 45-55 degrees Fahrenheit at registers). We do recommend covering the exterior condenser as much as possible in the fall and winter months to protect against debris collecting inside and falling ice from the roof that can damage the unit.







Normal Operating Controls: General

We suggest regular service/preventative maintenance by a licensed HVAC contractor to help prolong the life and efficiency of the unit. Generally, the best time for service is right before start-up in the Spring. Typical average lifespan is of standard A/C condenser is 15-20 years

Deficiencies

6.1.1 Cooling Equipment

INSULATION MISSING OR DAMAGED





The A/C line-set (copper tubing) was missing insulation around the larger, suction line that should be replaced. Insulation around this larger, copper refrigerant line is to promote efficiency by minimizing temperature change. Missing or damaged insulation on the refrigerant line can cause energy loss and condensation.

7: PLUMBING

		IN	NI	NP	D
7.1	Main Water Shut-off Device	Χ			
7.2	Drain, Waste, & Vent Systems	Χ			Χ
7.3	Water Supply, Distribution Systems & Fixtures	Χ			
7.4	Hot Water Systems, Controls, Flues & Vents	Χ			Χ
7.5	Fuel Storage & Distribution Systems	Χ			Χ
7.6	Sump Pump			Χ	
7.7	Bathroom	Χ			

Information

Filters Water Source Main Water Shut-off Device:

None Public **Location**

Basement, North

Drain, Waste, & Vent Systems:

Material

PVC

Water Supply, Distribution Systems & Fixtures: Water Service Entrance Material Copper

Hot Water Systems, Controls, Flues & Vents: Capacity 40 gallons

Fuel Storage & Distribution
Systems: Main Gas Shut-off
Location
Gas Meter

Bathroom: Shower Wall

Fiberglass

Water Supply, Distribution Systems & Fixtures: Water Distribution Material Copper

Hot Water Systems, Controls, Flues & Vents: Location Basement, Utility Room

Bathroom: FeaturesBuilt in tub, Toilet, Lavatory,
Vanity, Window

Hot Water Systems, Controls, Flues & Vents: Power Source/Type Gas

Bathroom: Room Floor Ceramic Tile

Hot Water Systems, Controls, Flues & Vents: Manufacturer

Bradford & White

Recommend flushing & servicing your water heater tank annually for optimal performance. Water temperature should be set to at least 120 degrees F to kill microbes and no higher than 130 degrees F to prevent scalding.

Here is a nice maintenance guide from Lowe's to help.

Hot Water Systems, Controls, Flues & Vents: Water Heater Information

The water heater produced sufficient hot water at tested faucets at the time of the inspection (Expected range is 110-120 degrees Fahrenheit). Typical average lifespan is 10-15 years.

Age: 12 Years







Deficiencies

7.2.1 Drain, Waste, & Vent Systems

LEAKING PIPE

KITCHEN SINK

A drain, waste and/or vent pipe showed signs of a leak. Recommend a qualified plumber evaluate and repair.







7.4.1 Hot Water Systems, Controls, Flues & Vents

Moderate Concern

WATER HEATER AGE

Water heater showed normal signs of wear and tear. Recommend monitoring its effectiveness and should be considered a potential service, repair or replacement item within the next 5 years (typical average lifespan is 10-15 years)

7.5.1 Fuel Storage & Distribution Systems

DAMAGED GAS VALVE

BASEMENT - GAS DRYER



Damaged gas valve should be replaced to allow for proper function and to avoid potential leaking. Recommend replacement by a qualified professional (Plumber or HVAC contractor).



7.6.1 Sump Pump

DRY CROCK/PIT



When a sump pit remains dry for extended periods of time, seals can dry out and crack. The inner workings of the pump can also seize up. We recommend pouring a few buckets of water once a month into your sump pit to lubricate the pump, exercise it, along with testing it out.

8: ELECTRICAL

		IN	NI	NP	D
8.1	Service Entrance Conductors	Χ			
8.2	Main & Subpanels, Service & Grounding, Main Overcurrent Device	Χ			Χ
8.3	Branch Wiring Circuits, Breakers & Fuses	Χ			Χ
8.4	Lighting Fixtures, Switches & Receptacles	Χ			Χ
8.5	GFCI & AFCI	Χ			Χ
8.6	Smoke Detectors	Χ			Χ
8.7	Carbon Monoxide Detectors	Χ			

Information

Service Entrance Conductors: Electrical Service Conductors Overhead, Aluminum, 120 Volts, 220 Volts

Main & Subpanels, Service & Grounding, Main Overcurrent Device: Panel Manufacturer
Westinghouse

Branch Wiring Circuits, Breakers & Fuses: Wiring MethodRomex

Main & Subpanels, Service & Grounding, Main Overcurrent Device: Main Panel Location

Basement

Main & Subpanels, Service & Grounding, Main Overcurrent Device: Panel Type
Circuit Breaker

GFCI & AFCI: GFCI LocationsExterior

Kitchen, Bathrooms, Exterior, Garage, Outbuildings

Main & Subpanels, Service & Grounding, Main Overcurrent Device: Panel Capacity

100 AMP

Branch Wiring Circuits, Breakers & Fuses: Branch Wire 15 and 20 AMPCopper

Main & Subpanels, Service & Grounding, Main Overcurrent Device: Sub Panel Location Basement





Main & Subpanels, Service & Grounding, Main Overcurrent Device: Main Panel Location





Deficiencies

8.3.1 Branch Wiring Circuits, Breakers & Fuses

WIRING CONNECTIONS - SAFETY



There were improper wiring connections and terminations noted during the inspection. All wiring connections should be housed in junction boxes and be kept covered to prevent potential electrical shock.

8.4.1 Lighting Fixtures, Switches & Receptacles

INCORRECT 3-WAY SWITCH WIRING

MAIN FLOOR BATHROOM



There are three-way switches wired incorrectly and not functioning properly during the inspection. Recommend contacting a licensed electrician for evaluation and correction

8.5.1 GFCI & AFCI

NO GFCI PROTECTION INSTALLED



KITCHEN, BATHROOM, GARAGE

No GFCI protection present in all locations. Recommend licensed electrician upgrade by installing ground fault receptacles in missing locations. Current construction code would require GFCI protection at all outlets in bathrooms, kitchen above-counter, garage, exterior and anywhere in close proximity to a water source. We recommend updating to current code.

Here is a link to read about how GFCI receptacles keep you safe.

8.5.2 GFCI & AFCI

GFCI FUNCTION



GFCI outlet test and reset buttons were not functioning properly when tested. The outlet still has power to it and works correctly but will not "trip" the circuit like it is designed to do. We recommend having this outlet replaced.

9: ATTIC, INSULATION & VENTILATION

		IN	NI	NP	D
9.1	Attic Insulation	Χ			Χ
9.2	Vapor Retarders (Crawlspace or Basement)			Χ	
9.3	Ventilation	Χ			
9.4	Exhaust Systems	Χ			

IN = Inspected NI = Not Inspected NP = Not Present D = Deficiencies

Information

Attic Insulation: Insulation Type

Attic Insulation: R-value

Ventilation: Ventilation Type

Fiberglass, Loose-fill

(estimated)

Ridge Vents, Soffit Vents

Exhaust Systems: Exhaust Fans

Flooring Insulation

None

15

Deficiencies

None

9.1.1 Attic Insulation



INSUFFICIENT INSULATION

Insulation depth was inadequate. Recommend a qualified attic insulation contractor install additional insulation to reach an approximate R40 value.





10: KITCHEN AND APPLIANCES

		IN	NI	NP	D
10.1	Appliances	Χ			
10.2	Clothes Dryer	Χ			Χ
10.3	Clothes Washer	Χ			
10.4	Kitchen	Χ			Χ

IN = Inspected NP = Not Present D = Deficiencies NI = Not Inspected

Information

Clothes Dryer: Clothes Dryer

Basement

Year: 2018



Clothes Dryer: Brand/Age

GΕ

Clothes Dryer: Dryer Power Source

Gas

Clothes Dryer: Dryer Vent Metal (Flex) Clothes Washer: Brand/Age Maytag **Clothes Washer: Clothes Washer** Basement

Year: 2019



Kitchen: Ventilation Kitchen: Floor Covering

None Ceramic

Kitchen: Sink Plumbing

Kitchen sink drain

Some Signs of Leaks

Active leak in kitchen sink drain. Recommend repairs by plumbing contractor.





11: BUILT-IN APPLIANCES

		IN	NI	NP	D
11.1	Dishwasher	Χ			Χ
11.2	Refrigerator	Χ			
11.3	Range/Oven/Cooktop	Χ			
11.4	Garbage Disposal			Χ	
11.5	Built-in Microwave	Χ			

Information

Dishwasher: Brand

GΕ

Dishwasher: Data plate

Year: 2008



Refrigerator: Brand

Maytag Year: 2005



Range/Oven/Cooktop: Exhaust Hood Type

None

Built-in Microwave: Brand/Age

Hotpoint

Range/Oven/Cooktop: Range/Oven Brand/Age Frigidaire

Range/Oven/Cooktop: Range/Oven Energy Source Gas

Built-in Microwave: Microwave

Year: 2005



General Appliance Remarks

All appliances in the home were functioning properly at the time of the inspection. All appliance functions were not tested, but only turned on/off to ensure all were operational. Appliance ages were taken from serial numbers or estimated if the serial number was unclear.

All appliance functions were not tested, but only turned on/off to ensure all were operational. Appliance ages were taken from serial numbers or estimated if the serial number was unclear. No active safety recalls were found from serial numbers unless otherwise noted

Minor Concern

Deficiencies

11.1.1 Dishwasher

DISHWASHER MISSING AIR GAP OR HIGH LOOP

DISHWASHER



The dishwasher drain did not have a visible high loop on the flex line before reaching the main drain connection, which is a general standard for all dishwashers (some newer models will have a high loop pre-installed on the

waste tee install side of the unit). We recommend adding – this can be as simple as securing the flexible drain to the bottom of the countertop or framing above.



12: DOORS, WINDOWS & INTERIOR

		IN	NI	NP	D
12.1	Doors	Χ			
12.2	Windows	Χ			
12.3	Floors	Χ			
12.4	Walls	Χ			
12.5	Ceilings	Χ			
12.6	Steps, Stairways & Railings	Χ			Χ
12.7	Countertops & Cabinets	Χ			

Information

Windows: Window ManufacturerFloors: Floor CoveringsWalls: Wall MaterialUnknownCarpet, Ceramic TileDrywall, Paneling, Wood

Ceilings: Ceiling Material Countertops & Cabinets:

Drywall Cabinetry
Wood

Windows: Window Type

Casement, Single Pane, Single-hung, Storm, Wood, Aluminum

Most windows in the home were older, wood framed windows with single pane glass – these will work fine but the home's efficiency will suffer. Storms windows installed on the exterior of the home should help with efficiency and draft if kept well maintained. All windows appeared in functional condition although some had been partially painted shut

Deficiencies

12.6.1 Steps, Stairways & Railings

LOOSE HANDRAIL



There were loose handrails that should be properly secured to the wall for safety in use. Recommend repairs by a handyman or qualified professional.





13: GARAGE

		IN	NI	NP	D
13.1	Ceiling	Χ			
13.2	Floor	Χ			
13.3	Walls & Firewalls	Χ			
13.4	Garage Door	Χ			Χ
13.5	Garage Door Opener	Χ			

Information

Garage Attached

Attached

Garage Door: MaterialNon-insulated, Aluminum

Ceiling: MaterialUnfinished

Garage Door: Type

Automatic

Floor: Material Concrete

Deficiencies

13.4.1 Garage Door

IMPROPER INSTALLATION

GARAGE DOOR

Weatherstripping missing around door perimeter. Recommend installation for proper weather seal.





13.4.2 Garage Door

PANEL DAMAGE



Garage door panel is damaged and may need repair/replacement. Recommend a qualified garage door contractor evaluate.

