

MOUNTAINS TO SOUND HOME INSPECTION LLC

253.344.4714

office@mshomeinspection.com https://www.mshomeinspection.com/



HOME INSPECTION REPORT

2133 N 115th St Seattle WA 98133

> Deb Doty JULY 22, 2019



Inspector
Allen Munn
Home Inspector Lic. 2267
(206) 484-1824
allen@mshomeinspection.com

Table of Contents

Table of Contents	2
SUMMARY	4
1: POSITIVE ATTRIBUTES OF THE HOME	6
2: INSPECTION DETAILS	7
3: EXTERIOR	8
4: ROOF	12
5: GARAGE(S)	14
6: MAIN ELECTRICAL PANEL	16
7: HEATING SYSTEM	17
8: WATER HEATER & PLUMBING	18
9: KITCHEN	23
10: KITCHEN APPLIANCES	25
11: BATHROOMS	26
12: LAUNDRY	29
13: INTERIORS, WINDOWS & DOORS	30
14: ATTIC	35
15: CRAWLSPACE, FOUNDATION, STRUCTURE & BASEMENTS	37
16: GENERAL COMMENTS	39
17: REASONABLE EXPECTATIONS OF A HOME INSPECTION	42
18: REPORT CONCLUSION	44
STANDARDS OF PRACTICE	45

Thank you for choosing Mountains to Sound Home Inspection.

Please carefully read through the <u>entire</u> inspection report. We are happy to assist with additional question you may have.

This report is based on a visual inspection of the building at the time and date of the inspection. Given the limited time allowed for an inspection, please do not expect that every concern or issue will be noted. Conditions of an occupied home can change after an inspection or sellers items may obscure our view of other defects. We strongly recommend that you and/or your representative carry out a final walk through immediately before closing to check the condition of the property.

Listed with most items of concern is a recommendation for a trade specialist. For your safety and liability, these concerns should be evaluated by the appropriate contractors prior to closing. Further recommendations may be given by a specialist. Lastly, we recommend obtaining at a minimum a full 1 year warranty as additional items for repair are likely to come about within that time. Here is a video walk-through on How to Read Your Inspection Report.

SUMMARY



23



LOW PRIORITY

MEDIUM PRIORITY

HIGH PRIORITY

- 3.3.1 Exterior Site & Other Observations: Cracked or deteriorated retaining wall
- 3.3.2 Exterior Site & Other Observations: Active Oil Tank
- 3.5.1 Exterior Exterior Siding Notes: Vegetation is encroaching
- 3.5.2 Exterior Exterior Siding Notes: Weathered Siding
- 3.5.3 Exterior Exterior Siding Notes: Seal penetations/gaps
- O 3.7.1 Exterior Fascia, Trim & Eaves: Sections of fascia & trim moisture damaged
- 3.8.1 Exterior Exterior Plumbing: Hose bib leaks while in use
- 3.13.1 Exterior Deck: Baluster Spacing
- 3.13.2 Exterior Deck: Deck rail loose or wobbly
- 5.3.1 Garage(s) Entry Door Into the House: Home entry not self closing
- 5.3.2 Garage(s) Entry Door Into the House: Door hardware missing/needs adjustment
- 5.4.1 Garage(s) Slab Floor: Full of storage slab blocked
- 5.7.1 Garage(s) Firewall Separation: No firewall separation between the garage and residence
- ▲ 8.1.1 Water Heater & Plumbing Water Heating System: Seismic Straps Missing/Insufficient
- 8.1.2 Water Heater & Plumbing Water Heating System: Expansion Tank Not Installed
- 8.1.3 Water Heater & Plumbing Water Heating System: Water temp too high
- 6 8.1.4 Water Heater & Plumbing Water Heating System: Water Stains-leakage
- 8.1.5 Water Heater & Plumbing Water Heating System: No discharge pipe

Θ

- **8.2.1** Water Heater & Plumbing Main Water Shut-Off, Distribution & Supply: Dripping pipe near or at water shut off valve
- 9.4.1 Kitchen Countertop: Missing or Deteriorated Caulk/Grout
- 11.1.1 Bathrooms Sink and Faucet: Sinks stopper needs work
- 11.4.1 Bathrooms Tub-Shower: Missing or deteriorated caulk/grout
- 11.5.1 Bathrooms Toilet: Functional but loose
- 11.6.1 Bathrooms Countertop: Missing or Deteriorated Caulk/Grout
- 11.8.1 Bathrooms Exhaust Fan: The exhaust fan is noisy
- (2) 13.1.1 Interiors, Windows & Doors General Notes: Unfinished Basement
- 13.2.1 Interiors, Windows & Doors Doors: Door striker plate

- 13.3.1 Interiors, Windows & Doors Flooring: Uneven floor under carpet.
- 2 13.4.1 Interiors, Windows & Doors Walls and Ceiling: Normal wear and tear
- 13.4.2 Interiors, Windows & Doors Walls and Ceiling: Possible Settlement crack
- 13.4.4 Interiors, Windows & Doors Walls and Ceiling: Patch/past repair
- (a) 13.5.1 Interiors, Windows & Doors Windows: Window stuck or difficult to open
- 13.8.1 Interiors, Windows & Doors Fireplace Notes: Minor fireplace cracking
- 13.8.2 Interiors, Windows & Doors Fireplace Notes: Tilework cracked
- 13.11.1 Interiors, Windows & Doors Lights, Wall Switches: Light fixture missing
- (a) 13.12.1 Interiors, Windows & Doors Outlets, Electrical: Ungrounded outlets
- 14.6.1 Attic Common Observations: Rodent Activity
- 14.6.2 Attic Common Observations: Effloresence on chimney wall
- (a) 15.1.1 Crawlspace, Foundation, Structure & Basements Foundation: Cracks Moderate
- 15.3.1 Crawlspace, Foundation, Structure & Basements Basement: Moisture Stains

1: POSITIVE ATTRIBUTES OF THE HOME

Information

Roof

Concrete Tile Roof

Water Heater

The Water Heater was Newer (under 5 years old)

Addition Features

Wood Burning Fireplace

Description

Charming and unique 1930's built home with 5 bedrooms and 2.5 baths. Featuring: unfinished basement, shop added on to garage space, rear deck with large hot tub, rear entrance garage parking + space for more. Just blocks from the Northgate Mall.

2: INSPECTION DETAILS

In Attendance

Clear

Inspector, Listing Agent

Weather Conditions

Information

Start Time

12pm

Style

Multi-level

Tompovotuvo

Temperature 60-70 degrees

Type of Building

Single Family

The images here are the directional locations of the home used throughout the report. Ensure you get yourself orientated to what direction the house is situated in order to better follow along.







Occupancy

Vacant

Year Built

1930



Notice to Absent Clients

We prefer to have our clients present, during, or immediately following the inspection so that we can elaborate on what may well be complicated or technical issues that could be somewhat difficult to understand. Since you were not present, we encourage you to read the whole report and not just the summary report, and to consult with us directly. Also, please verify with us anything that you believe we may have said.

Significant Repairs Needed

Based on the inspectors observations, this dwelling was judged to be poorly maintained and in need of significant repairs. Information concerning these conditions have been described in this report. Some additional reportable conditions will, in all likelihood, be discovered in the course of repairs or upgrading.

We recommend that you obtain repair estimates from competent specialists as an aid in planning your future course of action.

3: EXTERIOR

Information

Driveway, Walkways & Patio: Driveway Acceptable

The driveway is in acceptable condition.

Doorbell: Acceptable

The doorbell is functional and works on demand.

Driveway, Walkways & Patio: Walkway Acceptable

The walkways are in acceptable condition.

Exterior Siding Notes: Siding

Type

Wooden Siding

General Comments: Exterior comments

It is important to maintain a property, including painting or sealing walkways, decks, and other hard surfaces, and it is particularly important to keep the house walls sealed, which provide the only barrier against deterioration. Unsealed cracks around windows, doors, and thresholds can permit moisture intrusion, which is the principle cause of the deterioration of any surface. Unfortunately, the evidence of such intrusion may only be obvious when it is raining. We have discovered leaking windows while it was raining that may not have been otherwise apparent. Regardless, there are many styles of windows but only two basic types, single and dualglazed. Dual-glazed windows are superior, because they provide a thermal as well as an acoustical barrier. However, the hermetic seals on these windows can fail at any time, and cause condensation to form between the panes. Unfortunately, this is not always apparent, which is why we disclaim an evaluation of hermetic seals. Nevertheless, in accordance with industry standards, we test a representative number of unobstructed windows, and ensure that at least one window in every bedroom is operable and facilitates an emergency exit.

Grading & Drainage: General Grading Comments

Water can be destructive and foster conditions that are deleterious to health. For this reason, the ideal property will have soils that slope away from the residence and the interior floors will be several inches higher than the exterior grade. Also, the residence will have roof gutters and downspouts that discharge into area drains with catch basins that carry water away to hard surfaces. However, we cannot guarantee the condition of any subterranean drainage system, but if a property does not meet this ideal, or if any portion of the interior floor is below the exterior grade, we cannot endorse it and recommend that you consult with a grading and drainage contractor, even though there may not be any evidence of moisture intrusion. The sellers or occupants will obviously have a more intimate knowledge of the site than we could possible hope to have during our limited visit, however we have confirmed moisture intrusion in residences when it was raining that would not have been apparent otherwise. Also, in conjunction with the cellulose material found in most modern homes, moisture can facilitate the growth of biological organisms that can compromise building materials and produce mold-like substances that can have an adverse affect on health.

Foundation as Viewed from the Exterior: Exterior View

The foundation was in acceptable condition as viewed from the exterior. Any exceptions will be noted.

Fascia, Trim & Eaves: Acceptable

The fascia boards, trim and eaves are in acceptable condition. Any exceptions will be noted below.

Exterior Plumbing: Hose bibs Functional

The hose bibs that were found and accessible were functional. Any exceptions will be noted.

Downspouts: Acceptable

The downspouts appear to be in acceptable condition. Any exceptions will be noted below. We recommend downspouts always drain away from the structure and foundation

Exterior Doors: Exterior Doors Acceptable

The exterior doors were in acceptable condition. Any exceptions will be noted.

Lights: Acceptable

The lights outside the doors of the residence are functional. Any sensor or light sensitive fixture lights were not tested.

Limitations

Site & Other Observations

HOT TUB NOT INSPECTED

Evaluation of the hot tub is beyond the scope of Home Inspection. We did not inspect the hot tub. Recommend it be evaluated by a Pool & Spa Service Company.



Observations

3.3.1 Site & Other Observations

CRACKED OR DETERIORATED RETAINING WALL

REAR

The retaining wall is cracked or has deteriorated. Recommend monitoring and repair as needed.

Recommendation

Contact a qualified professional.



3.3.2 Site & Other Observations

ACTIVE OIL TANK

There is a active oil fuel storage tank on this property. Fuel tanks often contain fuel which can leak out into the soil as the tank deteriorates. The soil may have been contaminated by spills, even if the tank is in good condition. We recommend consulting the owner about past oil tank inspections that were performed on this property in the past.

If this is not available a oil tank inspection should be performed by a oil tank specialist to confirm its overall condition.

Recommendation

Contact a qualified professional.



3.5.1 Exterior Siding Notes

VEGETATION IS ENCROACHING

REAR



Vegetation is encroaching on the structure, and should be kept a minimum of twelve inches away for the general welfare of the walls and foundation.

Recommendation

Contact a qualified landscaping contractor



3.5.2 Exterior Siding Notes

Medium Priority

WEATHERED SIDING

ALL SIDES OF HOME

The exterior siding is weathered. Maintenance and minor repairs are recommended.

Recommendation

Contact a qualified professional.



3.5.3 Exterior Siding Notes

SEAL PENETATIONS/GAPS



Gaps and/or holes were observed on one or more sides in the siding around plumbing, gas, cable, wiring and/or other penetrations. We advise that all the holes and the gaps be caulked and/or sealed to prevent moisture and/or pest intrusion.

Recommendation

Contact a qualified professional.





3.7.1 Fascia, Trim & Eaves



SECTIONS OF FASCIA & TRIM MOISTURE DAMAGED

VARIOUS LOCATIONS

Sections of the fascia board or wood trim are weathered, moisture damaged and should be serviced or replaced as necessary by a qualified professional contractor to help prevent further wear or deterioration.



Contact a qualified handyman.



3.8.1 Exterior Plumbing

HOSE BIB LEAKS WHILE IN USE



REAR

The hose bib leaks at the handle while in use and you may want to have it repaired or replaced by a licensed professional. Sometimes they just need to be tightend.

Click Here go to fix yourself

Recommendation

Contact a qualified handyman.






3.13.1 Deck

BALUSTER SPACING







3.13.2 Deck

DECK RAIL LOOSE OR WOBBLY



The deck rail was loose or wobbly. Recommend repairs secure.

Recommendation

Contact a qualified professional.



4: ROOF

Information

Roof Electrical: Accept

The electrical strike and mast were in acceptable condition.



Method of Evaluation & Photos: Method of Evaluation & Photos

From the ground, Viewpoint from a ladder, Binoculars



Vents & Flashings: Acceptable

The roof flashings and vents are in acceptable condition where viewed. They appear to consist of metal flashing around roof penetrations and in valleys.

Gutters & Drainage: Acceptable

The gutters appear to be in acceptable condition. Any exceptions will be noted below.

Concrete Tile Roof: Acceptable

The concrete tile roof covering is in acceptable condition, but this is not a guarantee against leaks. For a guarantee, you would need to have a roofing company perform a water-test and issue a roof certification. Further evaluation from a qualified roofer is still recommended for more information about your roof, including maintenance tips and advise.

Concrete Tile Roof: Felt underlayment

Felt underlayment lasts 15 to 30 years. If the home is more than 15 years old or there was any exposed underlayment consult a licensed roofer for further evaluation.

Concrete Tile Roof: General Comments and Description

Concrete tile roofs are among the most expensive and durable of all roofs, and are warranted by the manufacturer to last for forty years or more, but are usually only guaranteed against leaks by the installer from three to five years. Like other pitched roofs, they are not designed to be waterproof, only water resistant, and are dependant on the integrity of the waterproof membrane beneath them, which cannot be seen without removing the tiles, but which can be split by movement, deteriorated through time, or by ultra-violet contamination. Significantly, although there is some leeway in installation specifications, the type and quality of membranes that are installed can vary from one installer to another, and leaks do occur. The majority of leaks result when a roof has not been well maintained or kept clean, and we recommend servicing them annually.

Concrete Tile Roof: This inspection is not a guarantee against leaks

This inspection is not a guarantee against leaks. For a guarantee, you would need to have a roofing company perform a water-test and issue a roof certification.

Chimney On Roof & Photo: Chimney Photo





Chimney On Roof & Photo: Acceptable

The the chimney above the roof is in acceptable condition. Any exceptions will be noted.

5: GARAGE(S)

Information

Picture and size of garage:

Picture and size of garage

Single car garage

The garage and its components were evaluated



Garage Door & Hardware: Acceptable

The sectional garage door and its hardware are functional.

Outlets, Electrical Observations: Acceptable

The outlets were in acceptable condition.

Slab Floor: Acceptable

The visable garage slab floor is in acceptable condition. Small cracks are common and result as a consequence of the curing process, seismic activity, common settling, or the presence expansive soils, but are not structurally threatening.

Parking Space: Check parking space to accommodate your vehicles

It would be prudent for you to see that the parking space is adequate to accommodate your vehicles.

Garage Side Door: Acceptable

The side door is functional. A solid steel panel security type door. Noted a deadbolt, door sweep, threshold and adequate weather stripping.

Limitations

Garage Door & Hardware

GARAGE DOOR AND HARDWARE NOT TESTED-BLOCKED OR LOCKED.

The garage door and its hardware could not be tested because it is blocked or locked, and should be demonstrated by the sellers.




Observations

5.3.1 Entry Door Into the House

HOME ENTRY NOT SELF CLOSING

The house garage entry door is functional but does not self-close. This may not have been required when the house was built and you may elect to have self closing hinges installed for modern fire safety.





Recommendation

Contact a qualified handyman.

5.3.2 Entry Door Into the House

Low Priority

Low Priority

DOOR HARDWARE MISSING/NEEDS ADJUSTMENT

Garage door has missing hardware and is in need of adjustment. Recommend repair.

Recommendation

Contact a qualified professional.



5.4.1 Slab Floor

FULL OF STORAGE SLAB BLOCKED

The garage is too full of storage to permit a clear view of the entire slab. I recommend evaluating the floor yourself once the storage is removed.

Recommendation

Recommended DIY Project



5.7.1 Firewall Separation

NO FIREWALL SEPARATION BETWEEN THE GARAGE AND RESIDENCE

There is no firewall separation between the garage and the residence, and one is mandated and should be installed.

Recommendation

Contact a qualified professional.



6: MAIN ELECTRICAL PANEL

Information

Service Entrance: Main Lines Overhead

Service Entrance: Main Lines Acceptable

The electrical service entrances are acceptable

Panel Size, Location & Photo: Panel Amps, Location and **Picture** Basement, 125



Panel Cover Condition: Acceptable

The electrical panel cover is in acceptable condition.

Wiring Notes: Electrical Service Circuit Breakers: Acceptable **Conductors**

120/240 volt, Aluminum

There are no visible deficiencies with the circuit breakers.

Panel Size, Location & Photo: Earth Ground

Not visible

The main panel groundingwas observed and found to be in good repair and of adequate function at the time of the inspection.

Main Panel Notes: Acceptable

The panel and its components have no visible deficiencies. Any exceptions will be noted below.

Main Panel Notes: Older Split Bus

The load center service panel was a split bus type in which a breaker located in an upper cluster of circuit breakers controlled power to another cluster of breakers located lower in the panel.

7: HEATING SYSTEM

Information

General Notes & Photos: Energy General Notes & Photos: Source/Type

Oil

Equipment Photos



Thermostats: Acceptable

The thermostats were functional at the time of the inspection

General Notes & Photos: Boiler Acceptable

The boiler appeared to functional

Vent Pipe: Acceptable

The gas furnace vent pipe is in acceptable condition.

8: WATER HEATER & PLUMBING

Information

Water Heating System: Energy Source/Type Electric

Water Heating System: Year



Water Heating System: Location Basement Bathroom

Water Heating System: Electrical

The electrical connection to the

Connections-Acceptable

Main Water Shut-Off.

Meter Location

Unknown

water heater is functional.

Distribution & Supply: Water

50

Water Heating System: Capacity Water Heating System: Drain Valve-Acceptable

> The drain valve is in place and presumed to be functional.

Water Heating System: Early Age Main Water Shut-Off,

The water heater is in the early years of its expected service life. **Distribution & Supply: Main Water Shut off Location** Basement



Drain, Waste, & Vent Systems: **Waste pipe Material** Copper, Iron





Water Heating System: Manufacturer and picture

Whirlpool

I recommend flushing & servicing your water heater tank annually for optimal performance. Water temperature should be set to at least 120 degrees F to kill microbes and no higher than 130 degrees F to prevent scalding.

Here is a nice maintenance guide from Lowe's to help.



Water Heating System: Water Shut-Off Valve & Connectors

The shut-off valve and water connectors appear functional but was not tested.



Main Water Shut-Off, Distribution & Supply: Plumbing acceptable

The plumbing was generally in acceptable condition. Any exceptions will be noted low.

Main Water Shut-Off, Distribution & Supply: Water Distribution Material

Copper, Galvanized, CPVC

A representative amount of the plumbing distribution system was observed and found to be in good repair.

Main Water Shut-Off, Distribution & Supply: House Pressure PICTURE-Acceptable

The pressure at the street was within industry standards, between 40 and 80 and a regulator is not required on the plumbing system.



Drain, Waste, & Vent Systems: Acceptable

Based on industry recommended water tests, the drainpipes are functional and acceptable at this time and functional drainage was noted. However, only a video-scan of the main drainpipe could confirm its actual condition which is beyond the scope of a general home inspection. Any exceptions will be noted below.


Drain, Waste, & Vent Systems: Side Sewer Notes

For a full evaluation of the waste line, we recommend that a sewer scope be completed.

Observations

8.1.1 Water Heating System

SEISMIC STRAPS - MISSING/INSUFFICIENT



Recommendation

Contact a qualified professional.





8.1.2 Water Heating System

EXPANSION TANK NOT INSTALLED



A thermal expansion tank was not installed. We recommend installation

Recommendation

Contact a qualified professional.



8.1.3 Water Heating System



WATER TEMP TOO HIGH

The water temperature is too high and is a potential hazard. Recommend water temperature be lowed not to exceed 120 degrees.

Recommendation

Recommended DIY Project



8.1.4 Water Heating System



WATER STAINS-LEAKAGE

Water stains were observed beneath and behind the water heater, indicating a past or present leak. Recommend further evaluation and repair by a qualified plumber.

Recommendation

Contact a qualified plumbing contractor.



8.1.5 Water Heating System



NO DISCHARGE PIPE

The pressure relief valve on the water heater does not have a discharge pipe. One should be installed that extends to the exterior and terminates approximately six inches above grade.

Recommendation

Contact a qualified plumbing contractor.



8.2.1 Main Water Shut-Off, Distribution & Supply



DRIPPING PIPE NEAR OR AT WATER SHUT OFF VALVE

There was a dripping pipe near the water shut off of the house. Recommend it be repaired by a licensed professional.

Recommendation

Contact a qualified plumbing contractor.





Bowl was in place to catch drips at the time of inspection.

9: KITCHEN

Information

Kitchen-PICTURE



Sink and Faucet: Acceptable

The kitchen sink and faucet are functional.

Trap and Drain: Acceptable

The kitchen trap and drain are functional. No leaking was noted.

Countertop: Acceptable

The visible areas of the kitchen countertops were functional.

Exhaust Fan Notes: Acceptable

Vents to Exterior The kitchen exhaust fan was functional.



Walls and Ceiling: Acceptable

The walls and ceiling are textured drywall and in acceptable condition.

Cabinets: Acceptable

The cabinets are functional, and do not have any significant damage.

Outlets, Electrical Observations: Lights, Wall Switches: Acceptable

The outlets functioned as intended.

Acceptable

The wall switches are functional.

Lights, Wall Switches:

Acceptable

The ceiling lights are functional.

Sink and Faucet: Water temp

The Water temp at the Kitchen Faucet is Currently noted in the photo below. The U.S. Consumer Product Safety Commission (CPSC) urges all users to keep their water heater temps at 120 degrees Fahrenheit to prevent scalding and bacteria prevention reasons.

Valves and Connectors: Acceptable

The kitchen valves and connectors below the sink appear functional. Valves were not turned, however no leaking was noted at the time of inspection. Valves are not in daily use and will inevitably become stiff or frozen.

Flooring: Acceptable

The floor is in satisfactory condition and has no significant visible defects.

Observations

9.4.1 Countertop



MISSING OR DETERIORATED CAULK/GROUT

The caulking or grout for the backsplash is missing, has gaps and/or not installed properly. We advise caulking/grout be installed and/or gaps filled to prevent possible water intrusion.

Recommendation

Recommended DIY Project



10: KITCHEN APPLIANCES

Information

Range: Acceptable Range: Range type

The range is functional Electric range

The range is functional.

Refrigerator: Acceptable

The fridge was functional and achieved acceptable fridge and freezer temperatures. This is a limited courtesy fridge inspection you should ask the sellers about its full operation. You should make sure to set your fridge at appropriate temps.

Dishwasher: Acceptable

The dishwasher is functional, completes an entire cycle, drains properly and no leaking was noted.

11: BATHROOMS

Information

Sink and Faucet: Acceptable

The sinks were functional.

Trap and Drain: Acceptable

The trap and drain are functional. No leaking was noted.

Toilet: Acceptable

The toilets were functional, flushes properly and no leaking noted.

Countertop: Acceptable

The countertops were functional.

The cabinets are functional, and do not have any significant damage.

Exhaust Fan: Acceptable

The bathroom exhaust fan is functional and works on

demand.

Doors: Acceptable

The door(s) are functional.

Walls and Ceiling: Acceptable

The walls and ceiling are textured drywall and in acceptable condition.

Closet: Acceptable

The closet was inspected and appeared to be in acceptable condition

Closet: Acceptable

The door(s) are functional.

Lights, Wall Switches: Acceptable

Cabinets: Acceptable

The wall switches are functional.

Lights, Wall Switches: Acceptable

The ceiling/wall lights are functional.

Outlets, Electrical Observations:

Serviceable

All tested Outlets were serviceable. Any exceptions will be noted.

Bathroom Photos

These photos are to show the condition of the bathrooms at the time of the inspection.







Valves and Connectors: Acceptable

The valves and connectors below the sink appear functional. Valves were not turned, however no leaking was noted at the time of inspection. Valves are not in daily use and will inevitably become stiff or frozen.

Tub-Shower: Acceptable

The tub/shower is functional. Hot and cold water supply temperature was verified and no leaking noted.

Flooring: Acceptable

The floor is in satisfactory condition and has no significant visible defects.

Observations

11.1.1 Sink and Faucet

Low Priority SINKS STOPPER NEEDS WORK

ALL BATHROOM SINKS

The sinkstopper does not work properly and repair is recommended.

Recommendation

Contact a qualified handyman.



11.4.1 Tub-Shower

MISSING OR DETERIORATED CAULK/GROUT

ALL BATHROOMS

The tub surround is has missing or deteriorated caulk/grout. Recommend caulking or sealing to prevent moisture intrusion.

Recommendation

Contact a qualified professional.





11.5.1 Toilet

FUNCTIONAL BUT LOOSE

MASTER BATHROOM

The toilet is functional, but loose on the floor and should be secured by a qualified technician, for safety reasons and to prevent possible damage or leaking from around the toilet.

Recommendation

Contact a qualified plumbing contractor.



11.6.1 Countertop

MISSING OR DETERIORATED CAULK/GROUT

BASEMENT BATHROOM

The caulking or grout for the backsplash is missing, has gaps and/or not installed properly. We advise caulking/grout be installed and/or gaps filled to prevent possible water intrusion.

Recommendation

Recommended DIY Project





11.8.1 Exhaust Fan

THE EXHAUST FAN IS NOISY



MAIN BATHROOM

The bathroom exhaust fan is functional, but noisy and you may want to upgrade it to a quieter one.

Recommendation

Contact a qualified handyman.





12: LAUNDRY

Information

Washer & Dryer: Equipment photos



Washer & Dryer: Dryer power source

220 Electric

Walls & Ceiling: Acceptable

The walls and ceiling are in acceptable condition.

Cabinets and Shelves:

Acceptable

The shelves are satisfactory

Cabinets and Shelves:

Acceptable

The cabinets are functional.

Lights, Wall Switches:

Acceptable

The ceiling lights are functional.

Lights, Wall Switches:

Acceptable

The wall switches are functional.

Outlets, Electrical Observations:

Serviceable

Washer & Dryer: Washer acceptable

At the time of inspection the washer was working. It was ran momentarily on one cycle and and appeared to be working correctly. This is a limited washer inspection and you should ask the seller about all the appliances and ask about any issues.

Washer & Dryer: Dryer acceptable

The dryer was breifly tested and produced heat and appeard to be working on at least one cycle. Efficiency or capability was not tested. This is a limited Dryer inspection and you should ask the seller about all the appliances.

Dryer Vent: Acceptable

The visible dryer vent connection appears correct. NOTE: Faulty dryer vents have been responsible for thousands of fires, hundreds of injuries, and even deaths. The best vents are a smooth-walled metal type that travels a short distance; all other types should be regarded as suspect, and should be inspected bi-annually to ensure that they do not contain trapped lint or moisture.

220 Volt Receptacle: 220 In-Use

The 220 volt receptacle for the dryer is in use. Power supply was not tested at the outlet. I recommend you should evaluate this outlet style to be sure the dryer you plan on using here is compatible with it.

Trap & Drain: Acceptable

The washing machine drain line appears satisfactory but is not visible because it's behind or within the wall.

Valves & Connectors: Acceptable

The washing machine valves and connectors appear functional but were not tested. No leaking was noted. However, because they are not in daily use they typically become stiff or frozen.

Flooring: Acceptable

The floor is in satisfactory condition and has no significant visible defects.

13: INTERIORS, WINDOWS & DOORS

Information

Doors: Acceptable

The door(s) are functional.

Walls and Ceiling: Acceptable

The walls and ceiling are texture drywall and in acceptable condition.

Windows: Acceptable

The walls and ceiling are textured The windows are functional.

Closet: Acceptable

The door(s) are functional.

Closet: Acceptable

The closet was inspected and appeared to be in acceptable condition

Lights, Wall Switches: Acceptable

The wall switches are functional.

Outlets, Electrical: Acceptable

The outlets were functional and grounded. Exceptions will he noted.

Outlets, Electrical: Light switches acceptable

The light switches were functional during the inspection.

General Notes: Interior Photos

These photos are to show the condition of the interiors at the day of the inspection.





General Notes: Bedrooms Photos

These photos are to show the condition of the bedrooms at the time of the inspection.









General Notes: Interiors in Acceptable condition

Windows, doors, floor and fixtures were overall in acceptable and serviceable condition. This also includes wall, ceilings and and other surfaces. Any exceptions will be noted in their perspective areas.

General Notes: Obsolete two prong ungrounded type

Many outlets throughout the residence are an obsolete, two prong, ungrounded type that are recommended to be evaluated by an electrician, before the close of escrow, and upgraded to have ground-fault protection as a modern safety feature.



Flooring: Acceptable

The floor is in satisfactory condition and has no significant visible defects.

Smoke & CO Detectors Notes: Smoke & carbon Monoxide present

Unless noted there was at least the minimally required amount of smoke and CO detectors in the living areas. Our recommendation is that smoke detectors be installed in each bedroom, outside of sleeping areas, and at least one on each floor. Carbon monoxide detectors should be on each floor. It is recommended they should be checked periodically for fire safety and replaced as necessary.

Fireplace Notes: Type of fireplace & Photo

Wood Burning





Handrails & Guardrails: Acceptable

The handrail or guardrail on the stairs is satisfactory and in good condition.

Floor Treads & Risers: Acceptable

The stair treads and risers appear satisfactory. The rise should not be less than 4 inches, nor greater than 7 inches, and the treads should not be less than 11 inches. In addition, the dimensions of the treads and the risers should not exceed 3/8 of an inch from the smallest dimension on the entire run of the stairs.

Observations

13.1.1 General Notes

UNFINISHED BASEMENT



There is an unfinished basement on the property. In addition, much of the ceiling, walls, and flooring are in the middle stages of repair and/or replacement. Recommend viewing for yourself and repairing or updating as needed.

Recommendation

Contact a qualified professional.

Low Priority







13.2.1 Doors

DOOR STRIKER PLATE

DOOR TO REAR DECK

The door striker plate needs to be adjusted or installed for the striker pin to engage.

Recommendation

Contact a qualified handyman.



13.3.1 Flooring

UNEVEN FLOOR UNDER CARPET.

1ST FLOOR

The floor is uneven under the carpet. The carpet should be pulled back and the slab inspected. And repaired if necessary.


Recommendation

Contact a qualified concrete contractor.



13.4.1 Walls and Ceiling

NORMAL WEAR AND TEAR



Recommendation

Recommended DIY Project





13.4.2 Walls and Ceiling

POSSIBLE SETTLEMENT CRACK

REAR LEFT BEDROOM, MASTER BATHROOM

One or more drywall settlement cracks were observed. These cracks can be the result of foundation settling. Recommend further evaluation by a qualified contractor.



Low Priority

Recommendation

Contact a qualified professional.





13.4.3 Walls and Ceiling

Low Priority

MOISTURE STAIN

REAR LIVING AREA

Moisture stains were observed. Recommend monitoring.

Recommendation

Contact a qualified roofing professional.



13.4.4 Walls and Ceiling

PATCH/PAST REPAIR

REAR MIDDLE BEDROOM

Patches or repairs were observed in the wall or ceiling. We could not determine the reason for the repairs. Recommend monitoring.

Recommendation

Contact a qualified professional.



13.5.1 Windows

WINDOW STUCK OR DIFFICULT TO OPEN



Various windows is were stuck or difficult to open. Recommend service by a qualified professional.

Recommendation

Contact a qualified window repair/installation contractor.



13.8.1 Fireplace Notes

MINOR FIREPLACE CRACKING

Minor cracking was observed in the fireplace bricks. These should be monitored and repaired as needed.

Recommendation

Contact a qualified professional.





Deb Doty 2133 N 115th St

13.8.2 Fireplace Notes



TILEWORK CRACKED

Fireplace floor tilework had cracks and missing tiles. Recommend repairing/replacing as needed.

Recommendation

Contact a qualified professional.



13.11.1 Lights, Wall Switches

Low Priority LIGHT FIXTURE MISSING

MASTER BEDROOM

There was a light fixture that had been damaged or removed. Recommend installing one, or having the wiring properly sealed behind a protective plate.

Recommendation

Contact a qualified professional.



13.12.1 Outlets, Electrical



Several of the Interior Outlets are ungrounded. This is common in older homes. Grounding all Outlets would be a beneficial and recommended update.

Recommendation

Contact a qualified electrical contractor.



14: ATTIC

Information

Attic Access Location

Master Bedroom closet

Exhaust Ducts: Acceptable

The visible portions of the exhaust ducts appear to be functional.

Insulation Notes: Acceptable

Insulation is acceptable

Plumbing Vents: Acceptable

The accessible plumbing vents were in acceptable condition.

Insulation Notes: Insulation

Type

Batt, Fiberglass

Attic Photos











Method of Evaluation: Entered

The attic was evaluated by direct access to easily accessible areas, and viewed from easy vantage points. Vaulted ceilings have limited access.

Framing Notes: Factory-built truss system - Acceptable

The roof framing is in satisfactory condition. The roof framing consists of a factory- built wood truss system, comprised of components called chords, webs, and struts that are connected by metal gussets nailed in place. Each component of the truss is designed for a specific purpose, and cannot be removed or modified without compromising the integrity of the entire truss. The lowest component, which is called the chord and to which the ceiling is attached, can move by thermal expansion and contraction and cause creaking sounds, which are more pronounced in the mornings and evenings along with temperature changes. Such movement has no structural significance, but can result in small cracks or divots in the drywall or plaster.

Roof Decking Notes: Plywood decking-Acceptable

The visible portions of the plywood roof decking are in acceptable condition and should conform to the standards of the year in which they were installed.

Ventilation: Ventilation - Acceptable

Ventilation is provided by a combination soffit, gable or roof vents and should be adequate. However, contacting a qualified insulation contractor about having your attic ventilation upgraded could help lower energy costs by cooling down your attic during the warmer summer months.

Observations

14.6.1 Common Observations



RODENT ACTIVITY

The attic has evidence of rodent activity. We recommend ceiling access points in eliminating any active rodent activity



14.6.2 Common Observations



EFFLORESENCE ON CHIMNEY WALL

There were signs of a past leak or moisture build up around the sides of the chimney viewable from the attic. Unknown if the leak was at all current. Recommend monitor and repair as needed.

Recommendation

Contact a qualified professional.



15: CRAWLSPACE, FOUNDATION, STRUCTURE & BASEMENTS

Information

Foundation: Inspection Method

Basement

Foundation: Material/Type

Concrete

Thefoundation showed only the normal signs of weathering and or cracking at the time of the inspection.

Foundation: Foundation Acceptable

The foundation was found to be in acceptable condition. Any exceptions will be noted below.

Sub-floor Structure: Serviceable Condition

The visible Beams, posts and piers and other sub-floor components were in acceptable condition at the time of the inspections. Any exceptions will be noted below.

Basement: Flooring

Concrete, Vinyl

The flooring was in good acceptable condition with only normal wear observed at the time of the inspection.

Basement: Room Photos







Basement: Sink/Faucet

The sink was partially filled and the faucet operated properly with no leaks found at the time of the inspection.

Basement: Stairway & Handrails

The stairway was observed to be in good repair, with all treads and handrails being secure and meeting safety requirements at the time of the inspection.

Basement: Toilet

The toilet was flushed multiple times and was properly secured to the floor at the time of the inspection.

Basement: Walls/Ceiling(s) - Materials & Condition

Concrete, Unfinished Drywall

The walls and ceilings were observed to have normal wear, cracking etc. at the time of the inspection.

Observations

15.1.1 Foundation



CRACKS MODERATE

RIGHT SIDE GARAGE

Moderate sized cracks were observed on a section of foundation. This could suggest unstable or settling soils. Recommend a soil or structural engineer should be consulted for corrective repairs. This may include sealing the pieces back together with a concrete or similar patch. A structural engineer would evaluate and provide a report on course of action and remedy.



Recommendation

Contact a qualified professional.

15.3.1 Basement

MOISTURE STAINS



Moisture stains were visible in several areas of the basement. This indicates possible water intrusion. These areas were dry at the time of the inspection. Recommended monitoring for future leaks.







16: GENERAL COMMENTS

Information

General Info

This report is the exclusive property of Mountains to Sound Home Inpection, LLC and the client whose name appears herewith, and its use by any unauthorized persons is strictly prohibited.

The observations and opinions expressed in this report are those of Mountains to Sound Home Inspection, LLC and supersede any alleged verbal comments. I inspect all of the systems, components, and conditions described in accordance with the standards of the Washington State Home Inspector Standards of Practice and those that I do not inspect are clearly disclaimed in the contract and/or in the aforementioned standards. However, some components that are inspected and found to be functional may not necessarily appear in the report, simply because we do not wish to waste our client's time by having them read an unnecessarily lengthy report about components that do not need to be serviced.

In accordance with the terms of the contract, the service recommendations that I make in this report should be completed well before the close of escrow by licensed specialists, who may well identify additional defects or recommend some upgrades that could affect your evaluation of the property.

This report has been produced in accordance with our signed contract and is subject to the terms and conditions agreed upon therein. All printed comments and the opinions expressed herein are those of the Inspection Company.

Scope of work

You have contracted with Mountains to Sound Home Inspection, LLC to perform a generalist inspection in accordance with the standards of practice established by the state of Washington and the International Association of Certified Home Inspectors (InterNACHI), a copy of which is available upon request. Generalist inspections are essentially visual, and distinct from those of specialists, inasmuch as they do not include the use of specialized instruments, the dismantling of equipment, or the sampling of air and inert materials. Consequently, a generalist inspection and the subsequent report will not be as comprehensive, nor as technically exhaustive, as that generated by specialists, and it is not intended to be. The purpose of a generalist inspection is to identify significant defects or adverse conditions that would warrant a specialist evaluation. Therefore, you should be aware of the limitations of this type of inspection, which is clearly indicated in the standards. However, the inspection is not intended to document the type of cosmetic deficiencies that would be apparent to the average person, and certainly not intended to identify insignificant deficiencies. Similarly, we do not inspect for vermin infestation, which is the responsibility of a licensed exterminator.

Most homes built after 1978, are generally assumed to be free of asbestos and many other common environmental contaminants. However, as a courtesy to our clients, we are including some well documented, and therefore public, information about several environmental contaminants that could be of concern to you and your family, all of which we do not have the expertise or the authority to evaluate, such as asbestos, radon, methane, formaldehyde, termites and other wood-destroying organisms, pests and rodents, molds, microbes, bacterial organisms, and electromagnetic radiation, to name some of the more commonplace ones. Nevertheless, we will attempt to alert you to any suspicious substances that would warrant evaluation by a specialist. However, health and safety, and environmental hygiene are deeply personal responsibilities, and you should make sure that you are familiar with any contaminant that could affect your home environment. You can learn more about contaminants that can affect your home from a booklet published by The Environmental Protection Agency, which you can read online at www.epa.gov/iaq/pubs/insidest.htm.

MOLD is one such contaminant. It is a microorganism that has tiny seeds, or spores, that are spread in the air then land and feed on organic matter. It has been in existence throughout human history and actually contributes to the life process. It takes many different forms, many of them benign, like mildew. Some characterized as allergens are relatively benign but can provoke allergic reactions among sensitive people, and others characterized as pathogens can have adverse health effects on large segments of the population, such as the very young, the elderly, and people with suppressed immune systems. However, there are less common molds that are called toxins that represent a serious health threat. All molds flourish in the presence of moisture, and we make a concerted effort to look for any evidence of it wherever there could be a water source, including that from condensation. Interestingly, the molds that commonly appear on ceramic tiles in bathrooms do not usually constitute a health threat, but they should be removed. However, some visibly similar molds that form on cellulose materials, such as on drywall, plaster, and wood, are potentially toxigenic. If mold is to be found anywhere within a home, it will likely be in the area of tubs, showers, toilets, sinks, water heaters, evaporator coils, inside attics with unvented bathroom exhaust fans, and return-air compartments that draw outside air, all

of which are areas that we inspect very conscientiously. Nevertheless, mold can appear as though spontaneously at any time, so you should be prepared to monitor your home, and particularly those areas that we identified. Naturally, it is equally important to maintain clean air-supply ducts and to change filters as soon as they become soiled because contaminated ducts are a common breeding ground for dust mites, rust, and other contaminants. Regardless, although some mold-like substances may be visually identified, the specific identification of molds can only be determined by specialists and laboratory analysis and is absolutely beyond the scope of our inspection. Nonetheless, as a prudent investment in environmental hygiene, we categorically recommend that you have your home tested for the presence of any such contaminants, and particularly if you or any member of your family suffers from allergies or asthma. Also, you can learn more about mold from an Environmental Protection Agency document entitled "A Brief Guide to Mold, Moisture, and Your Home," by visiting their website at: http://www.epa.gov/iaq/molds/moldguide.html/, from which it can be downloaded.

ASBESTOS is a notorious contaminant that could be present in any home built before 1978. It is a naturally occurring mineral fiber that was first used by the Greek and Romans in the first century, and it has been widely used throughout the modern world in a variety of thermal insulators, including those in the form of paper wraps, bats, blocks, and blankets. However, it can also be found in a wide variety of other products too numerous to mention, including duct insulation and acoustical materials, plasters, siding, floor tiles, heat vents, and roofing products. Although perhaps recognized as being present in some documented forms, asbestos can only be specifically identified by laboratory analysis. The most common asbestos fiber that exists in residential products is chrysotile, which belongs to the serpentine or white-asbestos group, and was used in the clutches and brake shoes of automobiles for many years. However, a single asbestos fiber is said to be able to cause cancer and is, therefore, a potential health threat and a litigious issue. Significantly, asbestos fibers are only dangerous when they are released into the air and inhaled, and for this reason authorities such as the Environmental Protection Agency [EPA] and the Consumer Product Safety Commission [CPSC] distinguish between asbestos that is in good condition, or non-friable, and that which is in poor condition, or friable, which means that its fibers could be easily crumbled and become airborne. However, we are not specialists and, regardless of the condition of any real or suspected asbestos-containing material [ACM], we would not endorse it and recommend having it evaluated by a specialist.

POPCORN CEILING- In early formulations, it often contained white asbestos fibers. When asbestos was banned in ceiling treatments by the Clean Air Act of 1978 in the United States,[1] popcorn ceilings fell out of favor in much of the country. However, in order to minimize economic hardship to suppliers and installers, existing inventories of asbestos-bearing texturing materials were exempt from the ban, so it is possible to find asbestos in popcorn ceilings that were applied through the 1980s. According to the EPA, the use of asbestos in textured ceiling paint was banned in 1977. Inhaled in large quantities, asbestos fibers can cause lung disease, scarring of the lungs and lung cancer. However, not all popcorn ceilings contain asbestos. Moreover, if left undisturbed or contained, asbestos is not dangerous.

RADON is a gas that results from the natural decay of radioactive materials in the soil and is purported to be the second leading cause of lung cancer in the United States. The gas is able to enter homes through the voids around pipes in concrete floors or through the floorboards of poorly ventilated crawlspaces, and particularly when the ground is wet and the gas cannot easily escape through the soil and be dispersed into the atmosphere. However, it cannot be detected by the senses, and its existence can only be determined by sophisticated instruments and laboratory analysis, which is completely beyond the scope of our service. However, you can learn more about radon and other environmental contaminants and their effects on health, by contacting the Environmental Protection Agency (EPA), at www. epa.gov/radon/images/hmbuygud.pdf, and it would be prudent for you to inquire about any high radon readings that might be prevalent in the general area surrounding your home.

LEAD poses an equally serious health threat. In the 1920's, it was commonly found in many plumbing systems. In fact, the word "plumbing" is derived from the Latin word "plumbum," which means lead. When in use as a component of a waste system, it is not an immediate health threat, but as a component of potable water pipes, it is a definite health hazard. Although rarely found in modern use, the lead could be present in any home build as recently as the nineteen forties. For instance, lead was an active ingredient in many household paints, which can be released in the process of sanding, and even be ingested by small children and animals chewing on painted surfaces. Fortunately, the lead in painted surfaces can be detected by industrial hygienists using sophisticated instruments, but testing for it is not cheap. There are other environmental contaminants, some of which we have already mentioned, and others that may be relatively benign. However, we are not environmental hygienists, and as we stated earlier we disclaim any responsibility for testing or establishing the presence of any environmental contaminant, and recommend that you schedule whatever specialist inspections that may deem prudent within the contingency period.

CRACKS AND WINDOWS Unsealed cracks around windows, doors, and thresholds can permit moisture intrusion, which is the principal cause of the deterioration of any surface. Unfortunately, the evidence of such intrusion may only be obvious when it is raining. We have discovered leaking windows while it was raining that may not

have been apparent otherwise. Regardless, there are many styles of windows but only two basic types, single and dual-glazed. Dual-glazed windows are superior because they provide a thermal as well as an acoustical barrier. However, the hermetic seals on these windows can fail at any time, and cause condensation to form between the panes. Many environmental factors come into play when and if hermetic seals have failed and Unfortunately, it is not always apparent, which is why we disclaim an evaluation of hermetic seals or unnoticed fogging glass. Nevertheless, in accordance with industry standards, we test a representative number of unobstructed windows and ensure that at least one window in every bedroom is operable and facilitates an emergency exit.

FURTHERMORE, you are advised to seek two professional opinions and acquire estimates of repair as to any defects, comments, improvements or recommendations mentioned in this report. We recommend that the professional making any repairs inspect the property further in order to discover and repair related problems that were not identified in the report. We recommend that all repairs, corrections, and cost estimates be completed and documented prior to closing or purchasing the property. Feel free to hire other professionals to inspect the property prior to closing. Including HVAC professionals, electricians, engineers, window professionals roofers etc.

All conditions are reported as they existed at the time of the inspection. The information contained in this report may be unreliable beyond the date of the inspection due to changing conditions.

17: REASONABLE EXPECTATIONS OF A HOME INSPECTION

Information

Setting Reasonable Expectations

Setting Reasonable Expectations When Things Go Wrong.

There may come a time that you discover something wrong with the house, and you may be upset or disappointed with your home inspection.

Intermittent Or Concealed Problems

Some problems can only be discovered by living in a house. They cannot be discovered during the few hours of a home inspection. For example, some shower stalls leak when people are in the shower, but do not leak when you simply turn on the tap. Some roofs and basements only leak when specific conditions exist. Some problems will only be discovered when carpets were lifted, furniture is moved or finishes are removed.

No Clues

These problems may have existed at the time of the inspection but there were no clues as to their existence. Our inspections are based on the past performance of the house. If there are no clues of a past problem, it is unfair to assume we should foresee a future problem.

We Always Miss Some Minor Things

Some say we are inconsistent because our reports identify some minor problems but not others. The minor problems that are identified were discovered while looking for more significant problems. We note them simply as a courtesy. The intent of the inspection is not to find the \$200 problems; it is to find the \$2,000 problems. These are the things that affect peoples decisions to purchase.

Contractors Advice

The main source of dissatisfaction with home inspectors comes from comments made by contractors. Contractors opinions often differ from ours. Dont be surprised when three roofers all say the roof needs replacement when we said that, with some minor repairs, the roof will last a few more years.

Last Man In Theory

While our advice represents the most prudent thing to do, many contractors are reluctant to undertake these repairs. This is because of the Last Man In Theory. The contractor fears that if he is the last person to work on the roof, he will get blamed if the roof leaks, regardless of whether the roof leak is his fault or not. Consequently, he wont want to do a minor repair with high liability when he could re-roof the entire house for more money and reduce the likelihood of a callback. This is understandable.

Most Recent Advice Is Best

There is more to the Last Man In Theory. It suggests that it is human nature for homeowners to believe the last bit of expert advice they receive, even if it is contrary to previous advice. As home inspectors, we unfortunately find ourselves in the position of First Man In and consequently it is our advice that is often disbelieved.

Why Didnt We See It

Contractors may say I cant believe you had this house inspected, and they didnt find this problem. There are several reasons for these apparent oversights:

1. Conditions During Inspection

It is difficult for homeowners to remember the circumstances in the house, at the time of the inspection. Homeowners seldom remember that it was snowing, there was storage everywhere in the basement or that the

furnace could not be turned on because the air conditioning was operating, et cetera. Its impossible for contractors to know what the circumstances were when the inspection was performed.

2. The Wisdom Of Hindsight

When the problem manifests itself, it is very easy to have 20/20 hindsight. Anybody can say that the basement is wet when there is 2 inches of water on the floor. Predicting the problem is a different story.

3. A Long Look

If we spent 1/2 an hour under the kitchen sink or 45 minutes disassembling the furnace, wed find more problems too. Unfortunately, the inspection would take several days and would cost considerably more.

4. Were Generalists

We are generalists; we are not specialists. The heating contractor may indeed have more heating expertise than we do

5. An Invasive Look

Problems often become apparent when carpets or plaster are removed, when fixtures or cabinets are pulled out, and so on. A home inspection is a visual examination. We dont perform any invasive or destructive tests.

Not Insurance

In conclusion, a home inspection is designed to better your odds. It is not designed to eliminate all risk. For that reason, a home inspection should not be considered an insurance policy. The premium that an insurance company would have to charge for a policy with no deductible, no limit and an indefinite policy period would be considerably more than the fee we charge. It would also not include the value added by the inspection.

We hope this is food for thought.

18: REPORT CONCLUSION

Information

Conclusion

Congratulations on the purchase of your new home. Since we never know who will be occupying or visiting a property, whether it be children or the elderly, we ask you to consider following these general safety recommendations: install and monitor smoke and carbon monoxide detectors; identify all escape and rescue ports; rehearse an emergency evacuation of the home; upgrade older electrical systems (if present) by at least adding ground-fault outlets; never service any electrical equipment without first disconnecting its power source; safety-film all non-tempered glass; ensure that every elevated window and the railings of stairs, landings, balconies, and decks are child-safe, meaning that barriers are in place or that the distance between the rails is not wider than three inches; regulate the temperature of water heaters to prevent scalding; make sure that goods that contain caustic or poisonous compounds, such as bleach, drain cleaners, and nail polish removers be stored where small children cannot reach them; ensure that all garage doors are well balanced and have a safety device, particularly if they are the heavy wooden type; remove any double-cylinder deadbolts from exterior doors; and consider installing child-safe locks and alarms on the exterior doors of all pool and spa properties.

We are proud of our service and trust that you will be completely satisfied with the quality of our report. We have made every effort to provide you with an accurate assessment of the condition of the property and its components and to alert you to any significant defects or adverse conditions. However, we may not have tested every outlet, and opened every window and door, or identified every minor defect. Also because we are not specialists or because our inspection is essentially visual, latent defects could exist. Therefore, you should not regard our inspection as conferring a guarantee or warranty. It does not. It is simply a report on the general condition of a particular property at a given point in time. Furthermore, as a homeowner, you should expect problems to occur. Roofs will leak, drain lines will become blocked, and components and systems will fail without warning. For these reasons, you should take into consideration the age of the house and its components and keep a comprehensive insurance policy current. If you have been provided with a home protection policy, read it carefully. Such policies usually only cover insignificant costs, such as that of rooter service, and the representatives of some insurance companies can be expected to deny coverage on the grounds that a given condition was preexisting or not covered because of what they claim to be a code violation or manufacturers defect. Therefore, you should read such policies very carefully, and depend upon our company for any consultation that you may need.

FURTHERMORE, you are advised to seek two professional opinions and acquire estimates of repair as to any defects, comments, improvements or recommendations mentioned in this report. We recommend that the professional making any repairs inspect the property further in order to discover and repair related problems that were not identified in the report. We recommend that all repairs, corrections, and cost estimates be completed and documented prior to closing or purchasing the property. Feel free to hire other professionals to inspect the property prior to closing. Including HVAC professionals, electricians, engineers, window professionals roofers etc.

Thank you for taking the time to read this report, and call us if you have any questions or observations whatsoever. I am always attempting to improve the quality of my service and this report, and I will continue to adhere to the highest standards of the real estate industry and to treat everyone with kindness, courtesy, and respect.

STANDARDS OF PRACTICE

Exterior

This inspection is not intended to address or include any geological conditions or site stability information. For information concerning these conditions a geologist or soils engineer should be consulted. Any reference to grade is limited to only areas around the exterior of the exposed foundation or exterior walls. This inspection is visual in nature and does not attempt to determine drainage performance of the site or the condition of any underground piping, including municipal water and sewer service piping or septic systems.

When decks and porches are built close to the ground where no viewing or access is possible, we cannot make accurate opinions. These areas as well as others that are too low to enter, or in some other manner not accessible, are excluded from the inspection and are not addressed in this report. We routinely recommend that inquiry be made with the seller about knowledge of conditions, repairs are usually noted in the form seventeen.

Our inspection of the Exterior grounds includes the surface drainage, grading, some fencing, gates, sidewalks, patios, driveways, and retaining walls adjacent to the structure. The inspection of the exterior of the building includes the cladding, trim, eaves, fascias, decks, porches, downspouts, railings, doors, windows and flashings. Areas hidden from view by finished walls or stored items can not be judged and are not a part of this inspection. Minor cracks are typical in many foundations and most do not represent a structural problem. If major cracks are present along with rotation, we routinely recommend further evaluation be made by a qualified professional structural engineer. All exterior grades should allow for surface and roof water to flow away from the foundation. All concrete slabs experience some degree of cracking due to shrinkage in the drying process or minor settlement.

Where deck carpeting, stacked firewood, excessive vegetation, soil and other coverings are installed, the materials or their nature of construction and condition of the underneath cannot be determined. All items listed are inspected for their proper function, poor installation, excessive wear and general state of repair.

Roof

The inspection of the roof system includes a visual examination of the surface materials, connections, penetrations and roof drainage systems. We examine the roofing material for damage and deterioration. We examine the roof system for possible leaks, damage and conditions that suggest limited remaining service life. We may offer opinions concerning repair and/or replacement if warranted. Opinions stated herein concerning the roofing material are based on the general condition of the roof system as evidence by our visual inspection.

These do not constitute a warranty that the roof is or will remain, free of leaks. All roofing systems require annual maintenance. Failure to perform routine maintenance will usually result in leaks and accelerated deterioration of the roof covering and flashings. When provided, our estimates of the roof's life expectancy are based on the assumption that the roof will be properly maintained during that period.

This report is issued in consideration a foregoing disclaimer in the future. The only way to determine whether a roof is absolutely water tight is to observe it during a prolonged rainfall. Many times, this situation is not present during the inspection and we cannot confirm this condition. We suggest that a annual inspection of the Attic area be performed where accessible to identify if any leaks are evident.

Garage(s)

The Garage is inspected as best as possible, but can be limited due to parked cars or personal stored items. Due to this area be cluttered or areas being inaccessible, it is common for sections that cannot not be fully inspected or items identified during our limited inspection. We suggest that a walk-through be performed once the home is vacant. If this is a new construction inspection or vacant home this area will be inspected thoroughly. Determining the heat resistance rating of fire walls and doors is beyond the scope of this inspection. Flammable materials should not be stored within the Garage area if possible.

Main Electrical Panel

Our examination of the electrical system includes a visual examination of the exposed and accessible branch circuits, wiring, service panel, over current protection devices, lighting fixtures, switches, and receptacles. Service equipment, proper grounding, wiring methods and bonding are focal points. We inspect for adverse conditions such as improper installation of aluminum wiring, lack of grounding and bonding, over-fusing, exposed wiring, open-air wire splices, reverse polarity and defective GFCl's. The hidden nature of the electrical wiring prevents inspection of every length of wire or their connections. Telephone, video, cable, audio, security systems and other low voltage systems were not included in this inspection unless specifically noted. We recommend you have the seller or a specialist demonstrate the serviceability or locations of these systems to you if necessary.

Any electrical repairs attempted by anyone other than a licensed electrician should be approached with caution. The power to the entire house should be turned off prior to beginning any repair efforts, no matter how trivial the repair may seem. Aluminum wiring requires periodic inspection and maintenance by a licensed electrician. Operation of time clock motors is not verified. Inoperative light fixtures often lack bulbs or have dead bulbs installed. Light bulbs are not changed during the inspection, due to time constraints. Smoke Alarms should be installed within 15 feet of all Bedroom doors and in Bedrooms. These units should be tested monthly.

Heating System

Our examination of the heating system includes a visual examination of the exposed and accessible heating equipment, thermostat, safety controls, venting and the means of air distribution. Our inspection of the heating system includes activating the heating system via the thermostat and a visual examination of the accessible components listed below.

These items are examined for proper function, excessive or unusual wear and general state of repair. Heat exchangers are inaccessible by design, and are not part of the Washington standards of practice. They must be completely removed from the furnace to be fully evaluated. Our inspection does not include disassembly of the furnace. The inspector cannot light pilot lights due to the liability. Safety devices are not tested by the inspector. To obtain maximum efficiency and reliability from your heating system, we recommend annual servicing and inspections by a qualified heating specialist.

Determining the condition of oil tanks, whether exposed or buried, is beyond the scope of this inspection. Leaking oil tanks represent an environmental hazard which is sometimes a costly condition to address.

Water Heater & Plumbing

Our inspection of the water heater includes a visual examination of the accessible portions of the tank, gas, electrical and/or water connections, venting and safety valves. These items are examined for proper function, excessive or unusual wear, leakage and general state of repair.

Our Inspection of the plumbing system includes a visual examination of the exposed portions of the domestic water supply, drain waste, vent, gas lines, faucets, fixtures, valves, drains, traps, exposed pipes and fittings. These items are examined for proper function, excessive or unusual wear, leakage and general state of repair. The hidden nature of piping prevents inspection of every pipe and joint connection, especially in walls, floors and ceiling voids. A sewer lateral test is necessary to determine the condition of the underground sewer lines is beyond the scope of this inspection.

Our review of the plumbing system does not include landscape irrigation systems, water wells, on site and/or private water supply systems, off site community water supply systems, or private (septic) waste disposal systems unless specifically noted. Review of these systems could be performed by qualified specialists prior to closing of escrow.

Kitchen

Inspection of the stand alone refrigerators, freezers and built-in ice makers are outside the scope of the inspection. No opinion is offered as to the adequacy of dishwasher operation. Ovens, self or continuous cleaning operations, cooking functions, clocks, timing devices, lights and thermostat accuracy are not tested during this inspection. Appliances are not moved during the inspection to inspect below or behind them. Portable dishwashers are not inspected, as they require connection to facilitate testing and are sometimes not left with the home.

Bathrooms

Our inspection of the bathrooms included a visual examination of the readily accessible portions of the floors, walls, ceilings, cabinets, countertops and plumbing fixtures. Bathrooms are inspected for water drainage, damage, deterioration to floor and walls, proper function of components, active leakage, unusual wear and general state of repair. Bathroom fixtures are run simultaneously to check for adequate water flow and pressure. Fixtures are tested using normal operating controls. Vent fans and their duct work are tested for their proper operation and examined where visible.

Shower pans are visually checked for leakage, but leaks often do not show except when the shower is in actual use. Determining whether shower pans, tub/shower surrounds are water tight is beyond the scope of this inspection. It is very important to maintain all grouting and caulking in the bath areas. Very minor imperfections can allow water to get into the wall or floor areas and cause damage. Proper ongoing maintenance will be required in the future.

Interiors, Windows & Doors

Our inspection of the Interior includes a visual inspection of the readily accessible portions of the walls, ceilings, floors, doors, cabinetry, countertops, steps, stairways, balconies and railings. Please note that a representative sample of the accessible windows and electrical receptacles are inspected. These features are examined for proper function, excessive wear and general state of repair. In some cases, all or portions of these components may not be

visible because of furnishings and personal items. In these cases some of the items may not be inspected.

The condition of walls behind wall coverings, paneling and furnishings cannot be judged. Only the general condition of visible portions of floors is included in this inspection. As a general rule, cosmetic deficiencies are considered normal wear and tear and are not reported. Determining the source of odors or like conditions is not a part of this inspection. Floor covering damage or stains may be hidden by furniture. The condition of floors underlying floor coverings is not inspected. Determining the condition of insulated glass windows is not always possible due to temperature, weather and lighting conditions. Check with owners for further information. All fireplaces should be cleaned and inspected on a regular basis to make sure that no cracks have developed. Large fires in the firebox can overheat the firebox and flue liners, sometimes resulting in internal damage.

Attic

Our inspection of the Attic includes a visual examination of the roof framing, plumbing, electrical and mechanical systems. There are often heating ducts, bathroom vent ducts, electrical wiring, chimneys and appliance vents in the Attic. We examined these systems and components for proper function, unusual wear and general state of repair, leakage, venting and unusual or improper improvements. When low clearances and deep insulation prohibits walking in an unfinished Attic, inspection will be from the access opening only. Vaulted ceilings cannot be inspected.

Crawlspace, Foundation, Structure & Basements

Many of the dwellings structural elements and portions of it's mechanical systems are visible inside the Crawl Space. These include the foundation, portions of the structural framing, the distribution systems for electricity, plumbing and heating. Each accessible and visible component and system was examined for proper function, excessive wear or abnormal deterioration and general state of repair. It is not unusual to find occasional moisture and dampness in the Crawl Spaces and we advise annual inspections of this area.

Significant or frequent water accumulation can affect the structures foundation and support system and would indicate the need for further evaluation by professional drainage contractor. We advise to monitor your Crawl Space during the rainy season.