



# MOUNTAINS TO SOUND HOME INSPECTION LLC

253.344.4714

[office@mshomeinspection.com](mailto:office@mshomeinspection.com)

<https://www.mshomeinspection.com/>



## HOME INSPECTION REPORT

7122 Husky Way SE  
Olympia WA 98503

Megan and Aaron Clarke

JUNE 5, 2020



Inspector

**Kelen Lewis**

Home Inspector Lic. 2211 SPI Lic. #97213

253.344.4714

[kelen@mshomeinspection.com](mailto:kelen@mshomeinspection.com)



Agent

**Patrick Clark**

eXp Olympia

(360) 970-5434

[patrick.clark@exprealty.com](mailto:patrick.clark@exprealty.com)

---

# TABLE OF CONTENTS

1: Positive Attributes of the Home	6
2: Inspection Details	7
3: Exterior	8
4: Roof	15
5: Garage(s)	19
6: Main Electrical Panel	21
7: Electrical Sub Panel	23
8: Heating System	24
9: Water Heater & Plumbing	27
10: Kitchen	29
11: Kitchen Appliances	31
12: Bathrooms	32
13: Laundry	34
14: Interiors, Windows & Doors	35
15: Attic	39
16: Crawlspace, Foundation, Structure & Basements	43
17: General Comments	46
18: Reasonable Expectations of a Home Inspection	49
19: Report Conclusion	52
Standard of Practice	53

Thank you for choosing Mountains to Sound Home Inspection.

Please carefully read through the entire inspection report. We are happy to assist with additional question you may have.

This report is based on a visual inspection of the building at the time and date of the inspection. Given the limited time allowed for an inspection, please do not expect that every concern or issue will be noted. Conditions of an occupied home can change after an inspection or sellers items may obscure our view of other defects. We strongly recommend that you and/or your representative carry out a final walk through immediately before closing to check the condition of the property.

Listed with most items of concern is a recommendation for a trade specialist. For your safety and liability, these concerns should be evaluated by the appropriate contractors prior to closing. Further recommendations may be given by a specialist. Lastly, we recommend obtaining at a minimum a full 1 year warranty as additional items for repair are likely to come about within that time. Here is a video walk-through on [How to Read Your Inspection Report](#).

# SUMMARY

21

LOW PRIORITY

26

MEDIUM PRIORITY

- 🔧 3.2.1 Exterior - Driveway, Walkways & Patio: Moderate Cracks in Driveway
- 🔧 3.2.2 Exterior - Driveway, Walkways & Patio: Cracks in walkways
- 🔧 3.2.3 Exterior - Driveway, Walkways & Patio: Walkway-trip hazard
- ⊖ 3.5.1 Exterior - Exterior Siding Notes: Weathered Siding
- ⊖ 3.5.2 Exterior - Exterior Siding Notes: Missing/deteriorated mortar
- 🔧 3.6.1 Exterior - Foundation as Viewed from the Exterior: Small cracks
- ⊖ 3.6.2 Exterior - Foundation as Viewed from the Exterior: Cracks Moderate
- 🔧 3.7.1 Exterior - Fascia, Trim & Eaves: Moisture staining to eaves
- 🔧 3.7.2 Exterior - Fascia, Trim & Eaves: Eave Gaps
- ⊖ 3.7.3 Exterior - Fascia, Trim & Eaves: Sections of fascia or wood trim are weathered
- ⊖ 3.7.4 Exterior - Fascia, Trim & Eaves: Sections of fascia & trim moisture damaged
- ⊖ 3.9.1 Exterior - Downspouts: Downspouts Missing Components
- 🔧 3.11.1 Exterior - Crawlspace Vents: Below Grade
- ⊖ 4.2.1 Roof - Composition Shingle Roof Notes: Damaged Shingles
- 🔧 4.3.1 Roof - General Observations: Moss & Debris
- 🔧 4.3.2 Roof - General Observations: Overhanging branches
- ⊖ 4.3.3 Roof - General Observations: Roof Patch
- 🔧 4.5.1 Roof - Gutters & Drainage: Gutters need to be cleaned of debris
- 🔧 4.6.1 Roof - Chimney On Roof & Photo: The crown is cracked and should be sealed to help prevent further wear and moisture intrusion
- ⊖ 5.4.1 Garage(s) - Entry Door Into the House: Home entry not self closing
- ⊖ 5.12.1 Garage(s) - Outlets, Electrical Observations: Coverplate missing
- ⊖ 6.4.1 Main Electrical Panel - Panel Cover Condition: Void or open knockout underneath
- ⊖ 8.2.1 Heating System - Furnace Notes: Service Furnace/HVAC System
- ⊖ 8.8.1 Heating System - Registers: A register is missing
- ⊖ 8.9.1 Heating System - Ducting: No insulation on metal ductwork
- ⊖ 8.10.1 Heating System - Return-Air Compartment: Replace Filter
- ⊖ 10.2.1 Kitchen - Trap and Drain: Flexible drainpipes

- 🔧 12.6.1 Bathrooms - Countertop: Missing or Deteriorated Caulk/Grout
- 🔧 12.14.1 Bathrooms - Lights, Wall Switches: Ceiling light not working
- 🔧 14.3.1 Interiors, Windows & Doors - Flooring: Sloped Floors
- 🔧 14.4.1 Interiors, Windows & Doors - Walls and Ceiling: Typical settlement cracking/nail pops
- ⚠️ 14.8.1 Interiors, Windows & Doors - Fireplace Notes: Did not work
- ⚠️ 14.8.2 Interiors, Windows & Doors - Fireplace Notes: Doors/screen Missing
- ⚠️ 14.10.1 Interiors, Windows & Doors - Outlets, Electrical: Reversed polarity on outlet
- 🔧 15.3.1 Attic - Roof Decking Notes: Deck Staining
- 🔧 15.3.2 Attic - Roof Decking Notes: moisture stains on the underside decking.
- 🔧 15.4.1 Attic - Electrical Notes: Attic lights did not work
- 🔧 15.4.2 Attic - Electrical Notes: Electrical does not terminate in box
- ⚠️ 15.5.1 Attic - Insulation Notes: Displaced or removed insulation
- ⚠️ 15.7.1 Attic - Exhaust Ducts: Kitchen exhaust extend to exterior
- 🔧 15.8.1 Attic - Ventilation: Limited Ventilation
- ⚠️ 16.1.1 Crawlspace, Foundation, Structure & Basements - Crawlspace Notes: No subfloor insulation
- ⚠️ 16.1.2 Crawlspace, Foundation, Structure & Basements - Crawlspace Notes: Possibly Active Pest Activity
- ⚠️ 16.1.3 Crawlspace, Foundation, Structure & Basements - Crawlspace Notes: Vapor barrier missing
- ⚠️ 16.2.1 Crawlspace, Foundation, Structure & Basements - Foundation: Section undermined
- ⚠️
- 16.3.1 Crawlspace, Foundation, Structure & Basements - Sub-floor Structure: Piers have shifted or settled
- 🔧 16.3.2 Crawlspace, Foundation, Structure & Basements - Sub-floor Structure: Excessive shimming at posts

# 1: POSITIVE ATTRIBUTES OF THE HOME

## Information

---

<b>Plumbing</b>	<b>Roof</b>	<b>Water Heater</b>
The plumbing System was updated to Pex plumbing	Architectural Roof	Tankless

**Addition Features**  
The Home was Recently Updated,  
Gas Fireplace, Wood Burning  
Fireplace

**Description**  
1959 built home with 3 bedrooms, 1.75 bathrooms, fully updated interior, a master suite, large living room with a gas burning fireplace, a large bonus room with wood burning fireplace, and attached two car garage, and updated kitchen with stainless steel appliances.

## 2: INSPECTION DETAILS

### Information

**Start Time**

9am

**In Attendance**

Home Owner

**Occupancy**

Furnished, Occupied

**Style**

Single Level

**Weather Conditions**

Cloudy

**Year Built**

1959

**Temperature**

50-60 degrees

**Type of Building**

Single Family

The images here are the directional locations of the home used throughout the report. Ensure you get yourself orientated to what direction the house is situated in order to better follow along.



**Older Home Advisory**

This home is considered an older home, built in an era when building standards were not at today's standards. As further advisory to the below inspection findings, older homes tend to have quirks or other deficiencies about them that may not be visible during a home inspection. These items may included under ground oil tanks, hidden knob and tube wiring, substandard insulation, galvanized plumbing, etc. Additionally, hidden items and structures may not have been built to modern standards and may not have been visible at the time of inspection.



## 3: EXTERIOR

### Information

#### Driveway, Walkways & Patio: Driveway Acceptable

The driveway is in acceptable condition.

#### Driveway, Walkways & Patio: Walkway Acceptable

The walkways are in acceptable condition.

#### Exterior Siding Notes: Siding Type Wooden Siding, Brick

#### Crawlspace Vents: Crawlspace Vents

Vents were acceptable.

#### Fences & Gates: Acceptable

The fences are were in acceptable condition.

#### General Comments: Exterior comments

It is important to maintain a property, including painting or sealing walkways, decks, and other hard surfaces, and it is particularly important to keep the house walls sealed, which provide the only barrier against deterioration. Unsealed cracks around windows, doors, and thresholds can permit moisture intrusion, which is the principle cause of the deterioration of any surface. Unfortunately, the evidence of such intrusion may only be obvious when it is raining. In the past, we have discovered leaking windows while it was raining that may not have been otherwise apparent. Regardless, there are many styles of windows but only two basic types, single and dual-glazed. Dual-glazed windows are superior, because they provide a thermal as well as an acoustical barrier. However, the hermetic seals on these windows can fail at any time, and cause condensation to form between the panes. Unfortunately, this is not always apparent, which is why we disclaim an evaluation of hermetic seals. Nevertheless, in accordance with industry standards, we test a representative number of unobstructed windows, and ensure that at least one window in every bedroom is operable and facilitates an emergency exit.

#### Grading & Drainage: General Grading Comments

Water can be destructive and foster conditions that are deleterious to health. For this reason, the ideal property will have soils that slope away from the residence and the interior floors will be several inches higher than the exterior grade. Also, the residence will have roof gutters and downspouts that discharge into area drains with catch basins that carry water away to hard surfaces. However, we cannot guarantee the condition of any subterranean drainage system, but if a property does not meet this ideal, or if any portion of the interior floor is below the exterior grade, we cannot endorse it and recommend that you consult with a grading and drainage contractor, even though there may not be any evidence of moisture intrusion. The sellers or occupants will obviously have a more intimate knowledge of the site than we could possibly hope to have during our limited visit, however we have confirmed moisture intrusion in residences when it was raining that would not have been apparent otherwise. Also, in conjunction with the cellulose material found in most modern homes, moisture can facilitate the growth of biological organisms that can compromise building materials and produce mold-like substances that can have an adverse affect on health.

#### Grading & Drainage: Interior-Exterior Elevations

There is an acceptable difference in elevation between the exterior grade and the interior floors that should ensure that moisture intrusion would not threaten the living space, but of course I cannot guarantee that.

#### Exterior Siding Notes: Acceptable

The exterior house wall finish is generally in acceptable condition. Any exceptions will be noted below.

#### Foundation as Viewed from the Exterior: Exterior View

The foundation was in acceptable condition as viewed from the exterior. Any exceptions will be noted.

#### Fascia, Trim & Eaves: Acceptable

The fascia boards, trim and eaves are in acceptable condition. Any exceptions will be noted below.



**Exterior Plumbing: Hose bibs Functional**

The hose bibs that were found and accessible were functional. Any exceptions will be noted.

**Downspouts: Acceptable**

The downspouts appear to be in acceptable condition. Any exceptions will be noted below. We recommend downspouts always drain away from the structure and foundation

**Exterior Doors: Exterior Doors Acceptable**

The exterior doors were in acceptable condition. Any exceptions will be noted.

**Exterior Doors: Front door Acceptable**

The front door is in acceptable condition with door sweep and weather stripping.

**Exterior Doors: Sliding glass door(s) is dual pane glass-Acceptable**

The sliding glass door is dual pane glass, tempered, operates smoothly and in acceptable condition.

**Exterior Chimney: Serviceable Condition**

The exterior chimney was in serviceable condition. See additional notes in the roofing section of this report.

**Lights: Acceptable**

The lights outside the doors of the residence are functional. Any sensor or light sensitive fixture lights were not tested.

## Limitations

### Site & Other Observations

**AUXILIARY STRUCTURES**

I did not evaluate auxiliary structures as part of this inspection: such as tool sheds, storage sheds, above ground pools etc.



### Exterior Plumbing

**SPRINKLER SYSTEM NOT TESTED**

The site/grounds has an irrigation system installed. This system was not tested during our inspection, due to it being beyond the scope of our inspection.

**SUGGESTION:** We recommend consulting the homeowner or a irrigation specialist for a demonstration and inspection of this system. Any maintenance or repairs should be performed if warranted.

## Lights

**LIGHTS ON PHOTO SENSOR**

The lights were on a photocell sensor and not tested. You should ask the sellers about these to confirm their full function.

**Observations**

## 3.2.1 Driveway, Walkways &amp; Patio




Low Priority

**MODERATE CRACKS IN DRIVEWAY**

There are a few cracks in the driveway which is mostly cosmetic but you may want to view for yourself and repair as necessary.

## Recommendation

Recommend monitoring.



## 3.2.2 Driveway, Walkways &amp; Patio



Low Priority

**CRACKS IN WALKWAYS**

There are a few cracks in the walkways around the residence that are mostly cosmetic. We suggest you view these yourself and repair as necessary.

## Recommendation

Contact a qualified professional.



## 3.2.3 Driveway, Walkways &amp; Patio



Low Priority

**WALKWAY-TRIP HAZARD**

## FRONT

There is an offset in a walkway that could prove to be a trip-hazard. I recommend using caution when walking in this area.

## Recommendation

Contact a qualified concrete contractor.



## 3.5.1 Exterior Siding Notes



Medium Priority

**WEATHERED SIDING**

## FRONT

The exterior siding is weathered. Maintenance, paint and minor repairs are recommended.

## Recommendation

Contact a qualified professional.



## 3.5.2 Exterior Siding Notes

**MISSING/DETERIORATED MORTAR**

## FRONT

There are areas in the brick siding where mortar is missing or deteriorated. Recommend repairs by a licensed professional.

## Recommendation

Contact a qualified professional.



Medium Priority



## 3.6.1 Foundation as Viewed from the Exterior

**SMALL CRACKS**

## RIGHT SIDE

Hairline and/or small cracks, within normal tolerances were visible. This type of cracking is often a result of shrinkage of materials and/or minor settlement and usually does not affect the performance of the foundation.

## Recommendation

Recommend monitoring.



Low Priority



## 3.6.2 Foundation as Viewed from the Exterior

**CRACKS MODERATE**

## LEFT SIDE, FRONT

Moderate sized cracks were observed on the Exterior foundation. This suggests unstable or settling soils. Recommend a soil or structural engineer should be consulted for corrective repairs. This may include sealing the pieces back together with a concrete or similar patch. Sealing is to deny possible moisture entry. a structural engineer evaluate and provide a report on course of action and remedy.

[Here is an informational article](#) on foundation cracks.

## Recommendation

Contact a qualified professional.



Medium Priority





## 3.7.1 Fascia, Trim &amp; Eaves

**MOISTURE STAINING TO EAVES**

REAR

The eaves have some moisture staining which should be explored further and repaired.

Recommendation

Contact a qualified roofing professional.



Low Priority



## 3.7.2 Fascia, Trim &amp; Eaves

**EAVE GAPS**

REAR

One or more gaps in the eaves were observed. Recommend sealing to prevent pest intrusion.

Recommendation

Contact a qualified professional.



Low Priority



## 3.7.3 Fascia, Trim &amp; Eaves

**SECTIONS OF FASCIA OR WOOD TRIM ARE WEATHERED**

REAR, FRONT

Sections of the fascia board or wood trim around the residence are slightly weathered, and should be serviced as necessary to prevent further deterioration. Service such as scraping, repainting and sealing.

Recommendation

Contact a qualified handyman.



Medium Priority



### 3.7.4 Fascia, Trim & Eaves

#### **SECTIONS OF FASCIA & TRIM MOISTURE DAMAGED**

##### REAR

Sections of the fascia board or wood trim are weathered, moisture damaged and should be serviced or replaced as necessary by a qualified professional contractor to help prevent further wear or deterioration.

##### Recommendation

Contact a qualified handyman.



### 3.9.1 Downspouts

#### **DOWNSPOUTS MISSING COMPONENTS**

##### LEFT SIDE, FRONT, RIGHT SIDE

The downspouts are missing parts. Recommend repairs to allow for proper drainage away from the structure.

##### Recommendation

Contact a qualified professional.







### 3.11.1 Crawlspace Vents

#### **BELOW GRADE**

RIGHT SIDE, FRONT

The foundation vents were at or below grade level. This can allow moisture to infiltrate into the crawlspace. Monitor for water intrusion. If observed, proper drainage away from the vents is recommended.

Recommendation

Contact a qualified professional.

 Low Priority



# 4: ROOF

## Information

### Chimney On Roof & Photo: Rain Cap Acceptable

The chimney has a functional weather cap/spark arrestor.

### Chimney On Roof & Photo: Chimney flashings Acceptable

The chimney flashings are in acceptable condition.

### Roof Electrical : Acceptable

The electrical strike and mast were in acceptable condition.

### Roof Electrical : Electrical Strike Photo



### Method of Evaluation & Photos: Method of Evaluation & Photos

Walking on its surface



### Composition Shingle Roof Notes: Acceptable

The roof is in generally acceptable condition. Any exceptions will be noted below. NOTE: This is not guarantee against leaks.



## Composition Shingle Roof Notes: Estimated Age

15+ Years Old

Because the exact installation date is unknown, this is an estimated guess of the age of the roof based on the current condition of the roof.

## Composition Shingle Roof Notes: General Comments and Description

There are a wide variety of composition shingle roofs, which are comprised of asphalt or fiberglass materials impregnated with mineral granules that are designed to deflect the deteriorating ultra-violet rays of the sun. The commonest of these roofs are warranted by manufacturers to last from twenty to twenty-five years, and are typically guaranteed against leaks by the installer for three to five years. The actual life of the roof will vary, depending on a number of interrelated factors besides the quality of the material and the method of installation. However, the first indication of significant wear is apparent when the granules begin to separate and leave pockmarks or dark spots. This is referred to as primary decomposition, which means that the roof is in decline, and therefore susceptible to leakage. This typically begins with the hip and ridge shingles and to the field shingles on the south facing side. This does not mean that the roof needs to be replaced, but that it should be monitored more regularly and serviced when necessary. Regular maintenance will certainly extend the life of any roof, and will usually avert most leaks that only become evident after they have caused other damage.

## Vents & Flashings: Acceptable

The roof flashings and vents are in acceptable condition where viewed. They appear to consist of metal flashing around roof penetrations and in valleys.

## Gutters & Drainage: Acceptable

The gutters appear to be in acceptable condition. Any exceptions will be noted below.

## Chimney On Roof & Photo: Chimney Photo



## Chimney On Roof & Photo: Acceptable

The the chimney above the roof is in acceptable condition. Any exceptions will be noted.

## Chimney On Roof & Photo: The crown is in acceptable condition

The crown, which is designed to seal the chimney wall and to shed rainwater and thereby prevent moisture from deteriorating the chimney, is in acceptable condition.

## Observations

### 4.2.1 Composition Shingle Roof Notes

#### DAMAGED SHINGLES

There were one or more shingles that had damage. Recommend repairs by a licensed roofer.

Recommendation

Contact a qualified roofing professional.



Medium Priority




## 4.3.1 General Observations

**MOSS & DEBRIS**

Parts of the roof need to be cleaned of moss and/or debris. This can restrict drainage and lead to moisture intrusion and moisture damage if not corrected.

## Recommendation

Contact a qualified professional.




## 4.3.2 General Observations

**OVERHANGING BRANCHES**

Trees near the dwelling have overhanging branches and/or branches in contact with the roof surface, which may cause damage to the roof surface. This condition may also cause the obstruction of roof water runoff and is a access for rodents, animals and carpenter ants. All overhanging or touching branches in contact of the roof surface should be trimmed to eliminate this condition.

## Recommendation

Contact a qualified professional.



## 4.3.3 General Observations

**ROOF PATCH**

Repairs and/or patches have been made to the roofing material in several areas. We cannot determine the reason or condition of the repairs. Monitoring is advised for future issues or conditions. An additional evaluation of the roof would be appropriate.

## Recommendation

Contact a qualified professional.



## 4.5.1 Gutters &amp; Drainage

**GUTTERS NEED TO BE CLEANED OF DEBRIS**



The gutters need to be cleaned of debris and serviced to be sure they will drain properly. However, without water in them it is difficult to judge whether they are correctly pitched to direct water into the downspouts, but they should function as they were intended.

Recommendation

Contact a qualified roofing professional.



#### 4.6.1 Chimney On Roof & Photo

### **THE CROWN IS CRACKED AND SHOULD BE SEALED TO HELP PREVENT FURTHER WEAR AND MOISTURE INTRUSION**



The crown, which is designed to seal the chimney wall and shed rainwater, has minor cracks and should be sealed to help prevent further wear and moisture intrusion.

Recommendation

Contact a qualified handyman.




# 5: GARAGE(S)

## Information

<b>Automatic Opener: Acceptable</b> The automatic garage door opener is acceptable.	<b>Automatic Opener: Safety lights - Acceptable</b> The garage door safety lights open the door when obstructed.	<b>Garage Door &amp; Hardware: Acceptable</b> The sectional garage door and its hardware are functional.
<b>Firewall Separation: Acceptable</b> The firewall separating the garage from the residence is functional.	<b>Walls and Ceiling: Acceptable</b> The visible walls and ceiling are in acceptable condition.	<b>Windows: Acceptable</b> The windows are functional.
<b>Lights, Wall Switches: Acceptable</b> The ceiling lights are functional.	<b>Lights, Wall Switches: Acceptable</b> The wall switches are functional.	<b>Outlets, Electrical Observations: Acceptable</b> The outlets were in acceptable condition.

**Picture and size of garage: Picture and size of garage**

Double Car Garage  
The garage and its components were evaluated.



<b>Slab Floor: Acceptable</b> The visable garage slab floor is in acceptable condition. Small cracks are common and result as a consequence of the curing process, seismic activity, common settling, or the presence expansive soils, but are not structurally threatening.
<b>Parking Space: Check parking space to accommodate your vehicles</b> It would be prudent for you to see that the parking space is adequate to accommodate your vehicles.
<b>Garage Side Door: Acceptable</b> The side door is functional. A solid steel panel security type door. Noted a deadbolt, door sweep, threshold and adequate weather stripping.

## Observations


5.4.1 Entry Door Into the House  
**HOME ENTRY NOT SELF CLOSING**

Medium Priority

The house garage entry door is functional but does not self-close. This may not have been required when the house was built and you may elect to have self closing hinges installed for modern fire safety.

Recommendation

Contact a qualified handyman.



#### 5.12.1 Outlets, Electrical Observations


### COVERPLATE MISSING

Medium Priority

Coverplates were missing on outlets, switches or junction boxes. Recommend installing cover plates.


Recommendation

Contact a qualified handyman.



# 6: MAIN ELECTRICAL PANEL

## Information

<b>Service Entrance: Main Lines</b> Overhead	<b>Service Entrance: Main Lines</b> <b>Acceptable</b>  The electrical service entrances are acceptable.	<b>Panel Size, Location &amp; Photo:</b> <b>Panel Amps, Location and Picture</b> Garage, 200 AMP
		
<b>Panel Cover Condition:</b> <b>Acceptable</b>  The electrical panel cover is in acceptable condition.	<b>Wiring Notes: Electrical Service Conductors</b> Aluminum	<b>Wiring Notes: Acceptable</b>  The visible portions of the wiring have no deficiencies.
<b>Circuit Breakers: Acceptable</b>  There are no visible deficiencies with the circuit breakers.		
<b>Panel Size, Location &amp; Photo: Earth Ground</b> Not visible  The main panel grounding was observed and found to be in good repair and of adequate function at the time of the inspection.		
<b>Main Panel Notes: Acceptable</b>  The panel and its components have no visible deficiencies. Any exceptions will be noted below.		
<b>Main Panel Notes: Generator system installed</b>  This home is equipped with a generator system. This system appears to be in service, but was not tested during our inspection. We recommend further testing or a review be performed when a generator is provided. Consulting the owner about its proper operation and instruction manuals is advised. Testing a generator or its connections and system is not in the scope of a home inspection.		
<b>Wiring Notes: Romex wiring</b>  Based on what is visible the residence appears to be wired predominantly with a modern vinyl conduit known as Romex.		
<b>Circuit Breakers: Includes arc-faults</b>  The system does include arc-fault circuit interrupters that are mandated by current standards. An AFCI is an electrical safety device installed in new home bedroom circuits, in some jurisdictions, for construction permitted after January 1, 2002. The AFCI's purpose is to prevent fires, which may occur due to faulty electrical appliances connected to a bedroom circuit.		

## Observations

### 6.4.1 Panel Cover Condition

#### **VOID OR OPEN KNOCKOUT UNDERNEATH**

Medium Priority

The main electrical exterior cover panel has a void or open knockout beneath it that should be covered for safety reasons.

Recommendation

Contact a qualified electrical contractor.





# 7: ELECTRICAL SUB PANEL


## Information

**Sub Panel Information:**  
**Grounding Acceptable**

The panel ground appears correct.

**Sub Panel Information: Panel**  
**Amps Location and Picture**

Garage, 125



**Sub Panel Observations:**  
**Acceptable**

The panel and its components have no visible deficiencies.

**Panel Cover Observations:**  
**Acceptable - Exterior**

The exterior panel cover is in acceptable condition.

**Panel Cover Observations:**  
**Acceptable - Interior**

The interior panel cover is in acceptable condition.

**Circuit Breakers: Acceptable**

There are no visible deficiencies with the circuit breakers.

**Grounding, Neutrals: Acceptable**

The Sub panel ground appears correct.

**Wiring Observations: No deficiencies and copper wiring was noted**

The visible portions of the wiring have no deficiencies and copper wiring was noted.

**Wiring Observations: Romex wiring**

The residence is wired predominantly with a modern vinyl conduit known as Romex.

# 8: HEATING SYSTEM

## Information

<b>General Notes &amp; Photos: Energy Source/Type</b> Gas	<b>Furnace Notes: Year</b> 2000	<b>Furnace Notes: Power Source/Type</b> Gas
<b>Furnace Notes: Limit switches</b> The safety switches for the gas furnace were acceptable.	<b>Vent Pipe: Acceptable</b> The gas furnace vent pipe is in acceptable condition.	<b>Thermostats: Acceptable</b> The thermostats were functional at the time of the inspection.
<b>Registers: Acceptable</b> The air supply registers are reasonably clean and appear functional.		

### General Notes & Photos: Equipment Photos



### General Notes & Photos: Disclaimer

The components of most heating and air-conditioning systems have a design-life ranging from ten to twenty years, but can fail prematurely with poor maintenance, which is why we apprise you of their age whenever possible. We test and evaluate them in accordance with the standards of practice, which means that we do not dismantle and inspect the concealed portions of evaporator and condensing coils, the heat exchanger, which is also known as the firebox, electronic air-cleaners, humidifiers, ducts and in-line duct-motors or dampers. We perform a conscientious evaluation of both systems, but we are not specialists. However, even the most modern heating systems can produce carbon monoxide, which in a sealed or poorly ventilated room can result in sickness, debilitating injury, and even death. Therefore, in accordance with the terms of our contract, it is essential that any recommendations that we make for service or a second opinion be scheduled before the close of escrow, or within the inspection period if possible, because a specialist could reveal additional defects or recommend further upgrades that could affect your evaluation of the property, and our service does not include any form of warranty or guarantee. Having the heating and cooling system fully evaluated by a qualified HVAC technician before the close of escrow and at least annually is recommended, regardless of its condition.

### Furnace Notes: Acceptable

The furnace was functional and responds when prompted at it's thermostat. I recommend further review from a qualified HVAC technician for more information or a detailed evaluation, at least before the close of escrow, or as you feel necessary.

### Furnace Notes: Thermocouple ok

The thermocouple is a gas furnace component located near the pilot light burner. It is a safety device that shuts off the gas if the pilot light goes out or the electric igniter fails. This was viewed on the furnace and appears acceptable. However only a specialist can deturmine its functionality.

**Age Related Notes: System 20 plus years old**

The hvac system is functional but likely near or beyond its design life. Therefore, it will need to be more closely monitored, they should be serviced annually, and have its filters changed every two to three months. However, it would also be wise to keep a home protection policy current.

**Gas Valve & Connector: Acceptable**

The gas valve and connector are in acceptable, visible condition, however the valve itself was not turned or operated.

**Combustion-Air Vents: Acceptable**

The combustion-air vents appear to be adequate to support complete combustion.

**Ducting: Acceptable**

The easily visible ducts have no visible deficiencies. Any exceptions will be noted.

**Return-Air Compartment: Acceptable**

The return-air compartments are in acceptable condition. I recommend changing the filters every 30 - 60 days or as required by the manufacturer. Any interior or internal HVAC system filters were not evaluated as part of this inspection. This includes any filters located within the interior air handler or furnace unit where located in the attic, garage or a closet etc.

## Observations

### 8.2.1 Furnace Notes

Medium Priority

**SERVICE FURNACE/HVAC SYSTEM**

The last know service date of the HVAC system was over one year ago or a service record was not found on or around the HVAC system. Recommend a heating & cooling contractor thoroughly clean and inspect all HVAC equipment. Servicing would be appropriate prior to closing.

**Recommendation**


Contact a qualified heating and cooling contractor

### 8.8.1 Registers

Medium Priority

**A REGISTER IS MISSING****HALLWAY BATHROOM**

A register is missing and should be replaced.



### 8.9.1 Ducting

Medium Priority

**NO INSULATION ON METAL DUCTWORK**

A metal duct is missing insulation and should be further evaluated and repaired for efficiency.

**Recommendation**

Contact a qualified HVAC professional.



#### 8.10.1 Return-Air Compartment

### REPLACE FILTER

The filter(s) in the return air compartment is dirty and should be changed soon and again at least every two or three months.

Recommendation

Recommended DIY Project



Medium Priority



# 9: WATER HEATER & PLUMBING

## Information

<b>Tankless Water Heaters: Location &amp; Photo</b>	<b>Main Water Shut-Off, Distribution &amp; Supply: Main Water Shut off Location</b>	<b>Main Water Shut-Off, Distribution &amp; Supply: Water Meter Location</b>
Garage	Not found	Front
Hot water is provided by a tankless, water heater that is wall-mounted.		



<b>Main Water Shut-Off, Distribution &amp; Supply: Water Supply Material To House</b>	<b>Drain, Waste, &amp; Vent Systems: Waste pipe Material</b>	<b>Gas Components: Main Gas Shut-off Location</b>
Galvanized	ABS, Iron	Meter



### Tankless Water Heaters: General

Residential tankless water heaters are a relatively new invention. They provide virtually endless but not unlimited hot water, and require little maintenance beyond periodic monitoring for leaks, which is to be anticipated with any type of water heater.

### Tankless Water Heaters: Shut-Off Valve & Connectors

The shut-off valve and water connectors are functional. There is also a temperature pressure relief valve and discharge pipe to the exterior.

### Tankless Water Heaters: The gas exhaust vent pipe appears functional

The gas exhaust vent pipe appears functional. The gas supply line and shut-off valve appear functional.

### Main Water Shut-Off, Distribution & Supply: Plumbing acceptable

The plumbing was generally in acceptable condition. Any exceptions will be noted low.

**Main Water Shut-Off, Distribution & Supply: Water Distribution Material**

Copper, Galvanized, Pex

A representative amount of the plumbing distribution system was observed and found to be in good repair.

**Drain, Waste, & Vent Systems: Acceptable**

Based on industry recommended water tests, the drainpipes are functional and acceptable at this time and functional drainage was noted. However, only a video-scan of the main drainpipe could confirm its actual condition which is beyond the scope of a general home inspection. Any exceptions will be noted below.

**Drain, Waste, & Vent Systems: Side Sewer Notes**

For a full evaluation of the waste line, we recommend that a sewer scope be completed.

**Gas Components: Gas Supply Pipes-Acceptable**

The visible portions of the gas pipes and their supports appear to be in acceptable condition.

## 10: KITCHEN

### Information

#### Kitchen-PICTURE



#### Sink and Faucet: Acceptable

The kitchen sink and faucet are functional.

#### Trap and Drain: Acceptable

The kitchen trap and drain are functional. No leaking was noted.

#### Countertop: Acceptable

The visible areas of the kitchen countertops were functional.

#### Exhaust Fan Notes: Acceptable

Vents to Exterior  
The kitchen exhaust fan was functional.

#### Walls and Ceiling: Acceptable

The walls and ceiling are textured drywall and in acceptable condition.

#### Windows: Acceptable

The windows are functional.

#### Cabinets: Acceptable

The cabinets are functional, and do not have any significant damage.

#### Outlets, Electrical Observations: Acceptable

The outlets functioned as intended.

#### Lights, Wall Switches: Acceptable

The ceiling lights are functional.

#### Lights, Wall Switches: Acceptable

The wall switches are functional.

#### Sink and Faucet: Water temp

The Water temp at the Kitchen Faucet is Currently noted in the photo below. The U.S. Consumer Product Safety Commission (CPSC) urges all users to keep their water heater temps at 120 degrees Fahrenheit to prevent scalding and bacteria prevention reasons.



#### Valves and Connectors: Acceptable

The kitchen valves and connectors below the sink appear functional. Valves were not turned, however no leaking was noted at the time of inspection. Valves are not in daily use and will inevitably become stiff or frozen.

#### Flooring: Acceptable

The floor is in satisfactory condition and has no significant visible defects.



## Observations

### 10.2.1 Trap and Drain

#### **FLEXIBLE DRAINPIPES**

Flexible drainpipes clog more often than traditional rigid piping. I recommend monitoring and repairing as needed.

Recommendation

Contact a qualified professional.



Medium Priority



# 11: KITCHEN APPLIANCES

## Information

---

**Range: Acceptable**

The range is functional.

**Range: Range type**

Gas range

**Refrigerator: Acceptable**

The fridge was functional and achieved acceptable fridge and freezer temperatures. This is a limited courtesy fridge inspection you should ask the sellers about its full operation. You should make sure to set your fridge at appropriate temps.

**Dishwasher: Acceptable**

The dishwasher is functional, completes an entire cycle, drains properly and no leaking was noted.

**Garbage Disposal: Acceptable**

Garbage disposal was functional and ran quietly at the time of the inspection.

**Built in Microwave: Acceptable**

The built in microwave was functional during the inspection, but I did not test it for leakage, which would require a specialized instrument. However, their power diminishes over time, and the specific measurement of the microwaves, as well as their containment within the unit, requires specialized instruments, which is beyond the scope of our service.

# 12: BATHROOMS

## Information

<b>Sink and Faucet: Acceptable</b> The sinks were functional.	<b>Trap and Drain: Acceptable</b> The trap and drain are functional. No leaking was noted.	<b>Toilet: Acceptable</b> The toilets were functional, flushes properly and no leaking noted.
<b>Countertop: Acceptable</b> The countertops were functional.	<b>Cabinets: Acceptable</b> The cabinets are functional, and do not have any significant damage.	<b>Exhaust Fan: Acceptable</b> The bathroom exhaust fan is functional and works on demand.
<b>Doors: Acceptable</b> The door(s) are functional.	<b>Walls and Ceiling: Acceptable</b> The walls and ceiling are textured drywall and in acceptable condition.	<b>Windows: Acceptable</b> The windows are functional.
<b>Closet: Acceptable</b> The closet was inspected and appeared to be in acceptable condition.	<b>Closet: Acceptable</b> The door(s) are functional.	<b>Lights, Wall Switches: Acceptable</b> The wall switches are functional.
<b>Lights, Wall Switches: Acceptable</b> The ceiling/wall lights are functional.	<b>Outlets, Electrical Observations: Serviceable</b> All tested outlets were serviceable. Any exceptions will be noted.	<b>HVAC: Acceptable</b> Heating was acceptable.

### Bathroom Photos

These photos are to show the condition of the bathrooms at the time of the inspection.



### Bathrooms In Acceptable Condition

The bathrooms are overall in acceptable and serviceable condition. Any exceptions will be noted in their perspective areas.

**Valves and Connectors: Acceptable**

The valves and connectors below the sink appear functional. Valves were not turned, however no leaking was noted at the time of inspection. Valves are not in daily use and will inevitably become stiff or frozen.

**Tub-Shower: Acceptable**

The tub/shower is functional. Hot and cold water supply temperature was verified and no leaking noted.

**Flooring: Acceptable**

The floor is in satisfactory condition and has no significant visible defects.

## Observations


### 12.6.1 Countertop

**MISSING OR DETERIORATED CAULK/GROUT****HALLWAY BATHROOM**

The caulking or grout for the backsplash is missing, has gaps and/or not installed properly. We advise caulking/grout be installed and/or gaps filled to prevent possible water intrusion.

Recommendation

Recommended DIY Project



### 12.14.1 Lights, Wall Switches

**CEILING LIGHT NOT WORKING****MASTER BATHROOM**

A light fixture did not have light bulbs or the bulbs were burnt out. Recommend replacing bulbs and testing.

Recommendation

Contact a qualified electrical contractor.



# 13: LAUNDRY

## Information

---

### Washer & Dryer: Equipment photos



### Washer & Dryer: Dryer power source

No Access

### Exhaust Fan: Window Only

The laundry room vents only through the window.

### Lights, Wall Switches: Acceptable    Lights, Wall Switches: Acceptable

The ceiling lights are functional.    The wall switches are functional.

### Washer & Dryer: Washer/Dryer Not Inspected

A VISUAL ONLY inspection of the washer/dry was performed. Testing washers and dryers is beyond the scope of a home inspection. We were not able to confirm their functionality which includes the testing of plumbing supply lines or valves, discharge lines, pumps, dryer vents and receptacles. We recommend asking the seller about all appliances and whether there are issues that should be disclosed.

### Dryer Vent: Acceptable

The visible dryer vent connection appears correct. NOTE: Faulty dryer vents have been responsible for thousands of fires, hundreds of injuries, and even deaths. The best vents are a smooth-walled metal type that travels a short distance; all other types should be regarded as suspect, and should be inspected bi-annually to ensure that they do not contain trapped lint or moisture.

### Trap & Drain: Acceptable

The washing machine drain line appears satisfactory but is not visible because it's behind or within the wall.

### Valves & Connectors: Acceptable

The washing machine valves and connectors appear functional but were not tested. No leaking was noted. However, because they are not in daily use they typically become stiff or frozen.

# 14: INTERIORS, WINDOWS & DOORS

## Information

**Doors: Acceptable**

The door(s) are functional.

**Walls and Ceiling: Acceptable**

The walls and ceiling are textured drywall and in acceptable condition.

**Windows: Acceptable**

The windows are functional.

**Closet: Acceptable**

The door(s) are functional.

**Closet: Acceptable**

The closet was inspected and appeared to be in acceptable condition.

**Smoke & CO Detectors Notes:  
Carbon monoxide detectors present**

Carbon monoxide detectors were present where required.



**Fireplace Notes: Type of fireplace & Photo**

Natural Gas

**Lights, Wall Switches: Acceptable**

The wall switches are functional.

**Lights, Wall Switches: Acceptable**

The ceiling lights are functional.

**Outlets, Electrical: Acceptable**

The outlets were functional and grounded. Exceptions will be noted.

**Outlets, Electrical: Light switches acceptable**

The light switches were functional during the inspection.

**Miscellaneous Topics Installed:  
See Not Inspected Tab**

**General Notes: Interior Photos**

These photos are to show the condition of the interiors at the day of the inspection.



## General Notes: Bedrooms Photos

These photos are to show the condition of the bedrooms at the time of the inspection.



## General Notes: Interiors in Acceptable condition

Windows, doors, floor and fixtures were overall in acceptable and serviceable condition. This also includes wall, ceilings and other surfaces. Any exceptions will be noted in their perspective areas.

## General Notes: Furnished Residence

The residence is furnished which limits or restricts a thorough evaluation of all wall floor areas windows electrical outlets etc, and in accordance with industry standards I only inspect those surfaces that are exposed and readily accessible. I do not move furniture, lift carpets, nor remove or rearrange items within closets and cabinets. I suggest that you come back to look over the property when everything is moved out, and all personal items have been removed.

## General Notes: Obsolete two prong ungrounded type

Many outlets throughout the residence are an obsolete, two prong, ungrounded type that are recommended to be evaluated by an electrician, before the close of escrow, and upgraded to have ground-fault protection as a modern safety feature.



## Flooring: Acceptable

The floor is in satisfactory condition and has no significant visible defects.

## Smoke & CO Detectors Notes: Smoke & carbon Monoxide present

Unless noted there was at least the minimally required amount of smoke and CO detectors in the living areas. Our recommendation is that smoke detectors be installed in each bedroom, outside of sleeping areas, and at least one on each floor. Carbon monoxide detectors should be on each floor. It is recommended they should be checked periodically for fire safety and replaced as necessary.

## Environmental Notes: Asbestos

This home may contain asbestos. Common materials that contain asbestos include ceiling texture, old plumbing insulation, ceiling insulation, old tile flooring and old HVAC duct tape. Actual content can only be determined by laboratory testing. Further information on asbestos can be obtained from a licensed asbestos consultant or abatement contractor.

## Environmental Notes: Lead Paint

The Interior and Exterior surfaces may contain lead paint. Actual content can only be determined by laboratory testing. Further information on lead paint can be obtained from a licensed lead paint consultant or abatement contractor.



**GFCI Notes: GFCI OK**

GFCI (Ground Fault Circuit Interrupter) protection was installed for all of the receptacles where this type of protection was required at the time of the dwellings construction. All suggested locations include garages, bathrooms, kitchens, laundry rooms, and all other locations with plumbing fixtures. We recommend testing these devices on a monthly basis.

**GFCI Notes: GFCI Overview**

GFCI (ground fault circuit interrupter) protection is a modern safety device designed to help prevent shock hazards. GFCI breakers and receptacle's function is to de-energize a circuit or a portion of a circuit when a hazardous condition exists. GFCI protection is inexpensive and can provide a substantial increased margin of safety.

Present requirement standards include receptacles near sink and wash basins. In Bathrooms, Kitchen, Garages, Exterior, Crawl Spaces and sump pump equipment.

## Observations

## 14.3.1 Flooring

**SLOPED FLOORS**

## KITCHEN


The floor sloped in one or more areas. This may be due to soil settling and/or age of structure settlement. We advise monitoring for additional sloping or have a structural engineer evaluate for possible corrections.

## Recommendation

Contact a qualified professional.



Low Priority



## 14.4.1 Walls and Ceiling

**TYPICAL SETTLEMENT CRACKING/NAIL POPS**

## HALLWAY

Observed typical settlement type cracking and nail pops on walls and ceilings. Recommend repairs as needed. Home owner to identify all areas for repair.

## Recommendation

Recommend monitoring.



Low Priority



## 14.8.1 Fireplace Notes

**DID NOT WORK**

We could not get the fireplace to work. Further evaluation/repairs or demonstration is recommended.

## Recommendation

Contact a qualified fireplace contractor.



Medium Priority

## 14.8.2 Fireplace Notes

**DOORS/SCREEN MISSING**

## BONUS ROOM



Medium Priority

No doors or screen or installed at the fireplace. We recommend the door or screen be installed.

Recommendation

Contact a qualified professional.



14.10.1 Outlets, Electrical

### **REVERSED POLARITY ON OUTLET**

GARAGE

An outlet has reversed polarity, and should be serviced.  
To learn more why this is dangerous [CLICK HERE](#)

Recommendation

Contact a qualified electrical contractor.

 Medium Priority



# 15: ATTIC

## Information

**Attic Access Location**  
Garage

**Electrical Notes: The attic lights- Acceptable**  
The attic lights work on demand at the attic switch.

**Insulation Notes: Acceptable**  
Insulation is acceptable

**Insulation Notes: Insulation Type**  
Blown, Fiberglass, Cellulose

**Exhaust Ducts: Acceptable**  
The visible portions of the exhaust ducts appear to be functional.

**Plumbing Vents: Acceptable**  
The accessible plumbing vents were in acceptable condition.

## Attic Photos



## General Info

In accordance with our standards, we do not attempt to enter attics that have less than thirty-six inches of headroom, are restricted by ducts, or in which the insulation obscures the joists and thereby makes mobility hazardous, in which case we would inspect them as best we can from the access point. In regard to evaluating the type and amount of insulation on the attic floor, we use only generic terms and approximate measurements, and do not sample or test the material for specific identification. Also, we do not disturb or move any portion of it, and it may well and often does obscure water pipes, electrical conduits, junction boxes, exhaust fans, heating and cooling ducts and other components.

## Method of Evaluation: Entered

The attic was evaluated by direct access to easily accessible areas, and viewed from easy vantage points. Vaulted ceilings have limited access.

## Framing Notes: Rafter type system - Acceptable

The roof framing is in satisfactory condition. The roof framing consists of a wood truss type system, comprised of components called chords, webs, and struts that are connected by metal gussets nailed in place. Each component of the truss is designed for a specific purpose, and cannot be removed or modified without compromising the integrity of the entire truss. The lowest component, which is called the chord and to which the ceiling is attached, can move by thermal expansion and contraction and cause creaking sounds, which are more pronounced in the mornings and evenings along with temperature changes. Such movement has no structural significance, but can result in small cracks or divots in the drywall or plaster.

## Roof Decking Notes: Plywood decking-Acceptable

The visible portions of the plywood roof decking are in acceptable condition and should conform to the standards of the year in which they were installed.

## Electrical Notes: Attic electrical-Acceptable

The attic electrical components that are easily visible and not covered by insulation appear to be in acceptable condition.

## Ventilation: Plumbing Vents-Acceptable

The drainpipe vents that are fully visible appear to be in acceptable condition.

## Ventilation: Ventilation - Acceptable

Ventilation is provided by a combination soffit, gable or roof vents and should be adequate. However, contacting a qualified insulation contractor about having your attic ventilation upgraded could help lower energy costs by cooling down your attic during the warmer summer months.

## Observations

### 15.3.1 Roof Decking Notes

#### DECK STAINING

Discoloration and dark staining was observed on the roof sheathing. This is often caused by poor ventilation and is commonly considered a microbial growth. Recommend improving ventilation and cleaning.



## 15.3.2 Roof Decking Notes

**MOISTURE STAINS ON THE UNDERSIDE DECKING.** Low Priority


There are obvious moisture stains on the underside of some wood decking, which is predictable and would not necessarily confirm an active roof leak. However, the possibility of an active leak could not be ruled out either. Therefore, you are recommended to have a qualified roof specialist evaluate further, before the close of escrow.



## 15.4.1 Electrical Notes

**ATTIC LIGHTS DID NOT WORK** Low Priority


A light fixture did not have light bulbs or the bulbs were burnt out. Recommend replacing bulbs and testing.



## 15.4.2 Electrical Notes

**ELECTRICAL DOES NOT TERMINATE IN BOX** Low Priority


Some live electrical lines should be in an electrical box for safety reasons.



## 15.5.1 Insulation Notes

**DISPLACED OR REMOVED INSULATION** Medium Priority

There is an area of displaced or removed insulation, that should be replaced to conserve energy and prevent heating and cooling loss.



## 15.7.1 Exhaust Ducts

**KITCHEN EXHAUST EXTEND TO EXTERIOR** Medium Priority

The kitchen exhaust duct should be extended to an exterior vent port.



#### 15.8.1 Ventilation

### LIMITED VENTILATION



Ventilation is limited, and could be improved. Therefore, we recommend that you have a second opinion from a licensed contractor. Contacting a qualified insulation contractor about having your attic ventilation upgraded could help lower energy costs by cooling down your attic during the warmer summer months.



# 16: CRAWLSPACE, FOUNDATION, STRUCTURE & BASEMENTS

## Information

**Crawlspace Notes: Crawlspace Access Location**  
Rear

**Foundation: Inspection Method**  
Crawlspace Entered

**Crawlspace Notes: Crawlspace Photos**



**Crawlspace Notes: Inspection Method**  
Crawlspace Traversed

The inspector will enter and inspect all attic and crawlspaces that have no physical or safety limitations, and is limited to the comfort of the inspector.

**Crawlspace Notes: Vapor Barrier**

At the time of the inspection,the vapor barriers were in good condition with only minor visible defects normal to the age of the home.

**Foundation: Material/Type**  
Concrete

Thefoundation showed only the normal signs of weathering and or cracking at the time of the inspection.

**Sub-floor Structure: Serviceable Condition**

The visible Beams, posts and piers and other sub-floor components were in acceptable condition at the time of the inspections. Any exceptions will be noted below.

## Observations

## 16.1.1 Crawlspace Notes



Medium Priority

**NO SUBFLOOR INSULATION**

No subfloor insulation was installed. This is common for the age of the home. We recommend installing as a beneficial efficiency upgrade.

Recommendation

Contact a qualified professional.



## 16.1.2 Crawlspace Notes



Medium Priority

**POSSIBLY ACTIVE PEST ACTIVITY**

There is possibly active pest activity in the crawl space. We recommend pest control company evaluate and treat. Further evaluation by a contractor would also be appropriate.

Recommendation

Contact a qualified professional.



## 16.1.3 Crawlspace Notes



Medium Priority

**VAPOR BARRIER MISSING**

Vapor barrier was missing from one or more sections of the crawl space. We recommend installing black vapor barrier over these areas.

Recommendation

Contact a qualified professional.



## 16.2.1 Foundation



Medium Priority

**SECTION UNDERMINED**

Is section of the foundation footing was undermined. No adverse effects were observed. Recommended monitoring and filling with structural filler for additional support.

Recommendation

Contact a qualified professional.



16.3.1 Sub-floor Structure

**PIERS HAVE SHIFTED OR SETTLED**

 Medium Priority

One or more of the piers have shifted or settled. Recommend evaluation and repair of this condition.

Recommendation

Contact a qualified professional.



16.3.2 Sub-floor Structure

**EXCESSIVE SHIMMING AT POSTS**

 Low Priority

One or more of the posts had excessive shims installed. Recommend that all excessively should posts be replaced with properly cut posts.

Recommendation

Contact a qualified professional.



# 17: GENERAL COMMENTS

## Information

---

### General Info

This report is the exclusive property of Mountains to Sound Home Inspection, LLC and the client whose name appears herewith, and its use by any unauthorized persons is strictly prohibited.

The observations and opinions expressed in this report are those of Mountains to Sound Home Inspection, LLC and supersede any alleged verbal comments. I inspect all of the systems, components, and conditions described in accordance with the standards of the Washington State Home Inspector Standards of Practice and those that I do not inspect are clearly disclaimed in the contract and/or in the aforementioned standards. However, some components that are inspected and found to be functional may not necessarily appear in the report, simply because we do not wish to waste our client's time by having them read an unnecessarily lengthy report about components that do not need to be serviced.

In accordance with the terms of the contract, the service recommendations that I make in this report should be completed well before the close of escrow by licensed specialists, who may well identify additional defects or recommend some upgrades that could affect your evaluation of the property.

This report has been produced in accordance with our signed contract and is subject to the terms and conditions agreed upon therein. All printed comments and the opinions expressed herein are those of the Inspection Company.

## Scope of work

You have contracted with Mountains to Sound Home Inspection, LLC to perform a generalist inspection in accordance with the standards of practice established by the state of Washington and the International Association of Certified Home Inspectors (InterNACHI), a copy of which is available upon request. Generalist inspections are essentially visual, and distinct from those of specialists, inasmuch as they do not include the use of specialized instruments, the dismantling of equipment, or the sampling of air and inert materials. Consequently, a generalist inspection and the subsequent report will not be as comprehensive, nor as technically exhaustive, as that generated by specialists, and it is not intended to be. The purpose of a generalist inspection is to identify significant defects or adverse conditions that would warrant a specialist evaluation. Therefore, you should be aware of the limitations of this type of inspection, which is clearly indicated in the standards. However, the inspection is not intended to document the type of cosmetic deficiencies that would be apparent to the average person, and certainly not intended to identify insignificant deficiencies. Similarly, we do not inspect for vermin infestation, which is the responsibility of a licensed exterminator.

Most homes built after 1978, are generally assumed to be free of asbestos and many other common environmental contaminants. However, as a courtesy to our clients, we are including some well documented, and therefore public, information about several environmental contaminants that could be of concern to you and your family, all of which we do not have the expertise or the authority to evaluate, such as asbestos, radon, methane, formaldehyde, termites and other wood-destroying organisms, pests and rodents, molds, microbes, bacterial organisms, and electromagnetic radiation, to name some of the more commonplace ones. Nevertheless, we will attempt to alert you to any suspicious substances that would warrant evaluation by a specialist. However, health and safety, and environmental hygiene are deeply personal responsibilities, and you should make sure that you are familiar with any contaminant that could affect your home environment. You can learn more about contaminants that can affect your home from a booklet published by The Environmental Protection Agency, which you can read online at [www.epa.gov/iaq/pubs/insidest.htm](http://www.epa.gov/iaq/pubs/insidest.htm).

MOLD is one such contaminant. It is a microorganism that has tiny seeds, or spores, that are spread in the air then land and feed on organic matter. It has been in existence throughout human history and actually contributes to the life process. It takes many different forms, many of them benign, like mildew. Some characterized as allergens are relatively benign but can provoke allergic reactions among sensitive people, and others characterized as pathogens can have adverse health effects on large segments of the population, such as the very young, the elderly, and people with suppressed immune systems. However, there are less common molds that are called toxins that represent a serious health threat. All molds flourish in the presence of moisture, and we make a concerted effort to look for any evidence of it wherever there could be a water source, including that from condensation. Interestingly, the molds that commonly appear on ceramic tiles in bathrooms do not usually constitute a health threat, but they should be removed. However, some visibly similar molds that form on cellulose materials, such as on drywall, plaster, and wood, are potentially toxigenic. If mold is to be found anywhere within a home, it will likely be in the area of tubs, showers, toilets, sinks, water heaters, evaporator coils, inside attics with unvented bathroom exhaust fans, and return-air compartments that draw outside air, all of which are areas that we inspect very conscientiously. Nevertheless, mold can appear as though spontaneously at any time, so you should be prepared to monitor your home, and particularly those areas that we identified. Naturally, it is equally important to maintain clean air-supply ducts and to change filters as soon as they become soiled because contaminated ducts are a common breeding ground for dust mites, rust, and other contaminants. Regardless, although some mold-like substances may be visually identified, the specific identification of molds can only be determined by specialists and laboratory analysis and is absolutely beyond the scope of our inspection. Nonetheless, as a prudent investment in environmental hygiene, we categorically recommend that you have your home tested for the presence of any such contaminants, and particularly if you or any member of your family suffers from allergies or asthma. Also, you can learn more about mold from an Environmental Protection Agency document entitled "A Brief Guide to Mold, Moisture, and Your Home," by visiting their website at: <http://www.epa.gov/iaq/molds/moldguide.html>, from which it can be downloaded.

ASBESTOS is a notorious contaminant that could be present in any home built before 1978. It is a naturally occurring mineral fiber that was first used by the Greek and Romans in the first century, and it has been widely used throughout the modern world in a variety of thermal insulators, including those in the form of paper wraps, bats, blocks, and blankets. However, it can also be found in a wide variety of other products too numerous to mention, including duct insulation and acoustical materials, plasters, siding, floor tiles, heat vents, and roofing products. Although perhaps recognized as being present in some documented forms, asbestos can only be specifically identified by laboratory analysis. The most common asbestos fiber that exists in residential products is chrysotile, which belongs to the serpentine or white-asbestos group, and was used in the clutches and brake shoes of automobiles for many years. However, a single asbestos fiber is said to be able to cause cancer and is, therefore, a potential health threat and a litigious issue. Significantly, asbestos fibers are only dangerous when they are released into the air and inhaled, and for this reason authorities such as the Environmental Protection Agency [EPA] and the Consumer Product Safety Commission [CPSC] distinguish between asbestos that is in good condition, or non-friable, and that which is in poor condition, or friable, which means that its fibers could be easily crumbled and become airborne. However, we are not specialists and, regardless of the condition of any real or suspected asbestos-containing material [ACM], we would not endorse it and recommend having it evaluated by a specialist.

POPCORN CEILING- In early formulations, it often contained white asbestos fibers. When asbestos was banned in ceiling treatments by the Clean Air Act of 1978 in the United States,[1] popcorn ceilings fell out of favor in much of the country. However, in order to minimize economic hardship to suppliers and installers, existing inventories of asbestos-



bearing texturing materials were exempt from the ban, so it is possible to find asbestos in popcorn ceilings that were applied through the 1980s. According to the EPA, the use of asbestos in textured ceiling paint was banned in 1977. Inhaled in large quantities, asbestos fibers can cause lung disease, scarring of the lungs and lung cancer. However, not all popcorn ceilings contain asbestos. Moreover, if left undisturbed or contained, asbestos is not dangerous.

RADON is a gas that results from the natural decay of radioactive materials in the soil and is purported to be the second leading cause of lung cancer in the United States. The gas is able to enter homes through the voids around pipes in concrete floors or through the floorboards of poorly ventilated crawlspaces, and particularly when the ground is wet and the gas cannot easily escape through the soil and be dispersed into the atmosphere. However, it cannot be detected by the senses, and its existence can only be determined by sophisticated instruments and laboratory analysis, which is completely beyond the scope of our service. However, you can learn more about radon and other environmental contaminants and their effects on health, by contacting the Environmental Protection Agency (EPA), at [www.epa.gov/radon/images/hmbuygud.pdf](http://www.epa.gov/radon/images/hmbuygud.pdf), and it would be prudent for you to inquire about any high radon readings that might be prevalent in the general area surrounding your home.

LEAD poses an equally serious health threat. In the 1920's, it was commonly found in many plumbing systems. In fact, the word "plumbing" is derived from the Latin word "plumbum," which means lead. When in use as a component of a waste system, it is not an immediate health threat, but as a component of potable water pipes, it is a definite health hazard. Although rarely found in modern use, the lead could be present in any home build as recently as the nineteen forties. For instance, lead was an active ingredient in many household paints, which can be released in the process of sanding, and even be ingested by small children and animals chewing on painted surfaces. Fortunately, the lead in painted surfaces can be detected by industrial hygienists using sophisticated instruments, but testing for it is not cheap. There are other environmental contaminants, some of which we have already mentioned, and others that may be relatively benign. However, we are not environmental hygienists, and as we stated earlier we disclaim any responsibility for testing or establishing the presence of any environmental contaminant, and recommend that you schedule whatever specialist inspections that may deem prudent within the contingency period.

CRACKS AND WINDOWS Unsealed cracks around windows, doors, and thresholds can permit moisture intrusion, which is the principal cause of the deterioration of any surface. Unfortunately, the evidence of such intrusion may only be obvious when it is raining. We have discovered leaking windows while it was raining that may not have been apparent otherwise. Regardless, there are many styles of windows but only two basic types, single and dual-glazed. Dual-glazed windows are superior because they provide a thermal as well as an acoustical barrier. However, the hermetic seals on these windows can fail at any time, and cause condensation to form between the panes. Many environmental factors come into play when and if hermetic seals have failed and Unfortunately, it is not always apparent, which is why we disclaim an evaluation of hermetic seals or unnoticed fogging glass. Nevertheless, in accordance with industry standards, we test a representative number of unobstructed windows and ensure that at least one window in every bedroom is operable and facilitates an emergency exit.

FURTHERMORE, you are advised to seek two professional opinions and acquire estimates of repair as to any defects, comments, improvements or recommendations mentioned in this report. We recommend that the professional making any repairs inspect the property further in order to discover and repair related problems that were not identified in the report. We recommend that all repairs, corrections, and cost estimates be completed and documented prior to closing or purchasing the property. Feel free to hire other professionals to inspect the property prior to closing. Including HVAC professionals, electricians, engineers, window professionals roofers etc.

All conditions are reported as they existed at the time of the inspection. The information contained in this report may be unreliable beyond the date of the inspection due to changing conditions.

# 18: REASONABLE EXPECTATIONS OF A HOME INSPECTION

## Information

---

---

## Setting Reasonable Expectations

Setting Reasonable Expectations When Things Go Wrong.

There may come a time that you discover something wrong with the house, and you may be upset or disappointed with your home inspection.

### Intermittent Or Concealed Problems

Some problems can only be discovered by living in a house. They cannot be discovered during the few hours of a home inspection. For example, some shower stalls leak when people are in the shower, but do not leak when you simply turn on the tap. Some roofs and basements only leak when specific conditions exist. Some problems will only be discovered when carpets were lifted, furniture is moved or finishes are removed.

### No Clues

These problems may have existed at the time of the inspection but there were no clues as to their existence. Our inspections are based on the past performance of the house. If there are no clues of a past problem, it is unfair to assume we should foresee a future problem.

### We Always Miss Some Minor Things

Some say we are inconsistent because our reports identify some minor problems but not others. The minor problems that are identified were discovered while looking for more significant problems. We note them simply as a courtesy. The intent of the inspection is not to find the \$200 problems; it is to find the \$2,000 problems. These are the things that affect people's decisions to purchase.

### Contractors Advice

The main source of dissatisfaction with home inspectors comes from comments made by contractors. Contractor's opinions often differ from ours. Don't be surprised when three roofers all say the roof needs replacement when we said that, with some minor repairs, the roof will last a few more years.

### Last Man In Theory

While our advice represents the most prudent thing to do, many contractors are reluctant to undertake these repairs. This is because of the Last Man In Theory. The contractor fears that if he is the last person to work on the roof, he will get blamed if the roof leaks, regardless of whether the roof leak is his fault or not. Consequently, he won't want to do a minor repair with high liability when he could re-roof the entire house for more money and reduce the likelihood of a callback. This is understandable.

### Most Recent Advice Is Best

There is more to the Last Man In Theory. It suggests that it is human nature for homeowners to believe the last bit of expert advice they receive, even if it is contrary to previous advice. As home inspectors, we unfortunately find ourselves in the position of First Man In and consequently it is our advice that is often disbelieved.

### Why Didn't We See It

Contractors may say I can't believe you had this house inspected, and they didn't find this problem. There are several reasons for these apparent oversights:

#### 1. Conditions During Inspection

It is difficult for homeowners to remember the circumstances in the house, at the time of the inspection. Homeowners seldom remember that it was snowing, there was storage everywhere in the basement or that the furnace could not be turned on because the air conditioning was operating, et cetera. It's impossible for contractors to know what the circumstances were when the inspection was performed.

#### 2. The Wisdom Of Hindsight

When the problem manifests itself, it is very easy to have 20/20 hindsight. Anybody can say that the basement is wet when there is 2 inches of water on the floor. Predicting the problem is a different story.

#### 3. A Long Look

If we spent 1/2 an hour under the kitchen sink or 45 minutes disassembling the furnace, we would find more problems too. Unfortunately, the inspection would take several days and would cost considerably more.

#### **4. Were Generalists**

We are generalists; we are not specialists. The heating contractor may indeed have more heating expertise than we do.

#### **5. An Invasive Look**

Problems often become apparent when carpets or plaster are removed, when fixtures or cabinets are pulled out, and so on. A home inspection is a visual examination. We don't perform any invasive or destructive tests.

#### **Not Insurance**

In conclusion, a home inspection is designed to better your odds. It is not designed to eliminate all risk. For that reason, a home inspection should not be considered an insurance policy. The premium that an insurance company would have to charge for a policy with no deductible, no limit and an indefinite policy period would be considerably more than the fee we charge. It would also not include the value added by the inspection.

We hope this is food for thought.

# 19: REPORT CONCLUSION

## Information

---

### Conclusion

Congratulations on the purchase of your new home. Since we never know who will be occupying or visiting a property, whether it be children or the elderly, we ask you to consider following these general safety recommendations: install and monitor smoke and carbon monoxide detectors; identify all escape and rescue ports; rehearse an emergency evacuation of the home; upgrade older electrical systems (if present) by at least adding ground-fault outlets; never service any electrical equipment without first disconnecting its power source; safety-film all non-tempered glass; ensure that every elevated window and the railings of stairs, landings, balconies, and decks are child-safe, meaning that barriers are in place or that the distance between the rails is not wider than three inches; regulate the temperature of water heaters to prevent scalding; make sure that goods that contain caustic or poisonous compounds, such as bleach, drain cleaners, and nail polish removers be stored where small children cannot reach them; ensure that all garage doors are well balanced and have a safety device, particularly if they are the heavy wooden type; remove any double-cylinder deadbolts from exterior doors; and consider installing child-safe locks and alarms on the exterior doors of all pool and spa properties.

We are proud of our service and trust that you will be completely satisfied with the quality of our report. We have made every effort to provide you with an accurate assessment of the condition of the property and its components and to alert you to any significant defects or adverse conditions. However, we may not have tested every outlet, and opened every window and door, or identified every minor defect. Also because we are not specialists or because our inspection is essentially visual, latent defects could exist. Therefore, you should not regard our inspection as conferring a guarantee or warranty. It does not. It is simply a report on the general condition of a particular property at a given point in time. Furthermore, as a homeowner, you should expect problems to occur. Roofs will leak, drain lines will become blocked, and components and systems will fail without warning. For these reasons, you should take into consideration the age of the house and its components and keep a comprehensive insurance policy current. If you have been provided with a home protection policy, read it carefully. Such policies usually only cover insignificant costs, such as that of roofer service, and the representatives of some insurance companies can be expected to deny coverage on the grounds that a given condition was preexisting or not covered because of what they claim to be a code violation or manufacturers defect. Therefore, you should read such policies very carefully, and depend upon our company for any consultation that you may need.

FURTHERMORE, you are advised to seek two professional opinions and acquire estimates of repair as to any defects, comments, improvements or recommendations mentioned in this report. We recommend that the professional making any repairs inspect the property further in order to discover and repair related problems that were not identified in the report. We recommend that all repairs, corrections, and cost estimates be completed and documented prior to closing or purchasing the property. Feel free to hire other professionals to inspect the property prior to closing. Including HVAC professionals, electricians, engineers, window professionals roofers etc.

Thank you for taking the time to read this report, and call us if you have any questions or observations whatsoever. I am always attempting to improve the quality of my service and this report, and I will continue to adhere to the highest standards of the real estate industry and to treat everyone with kindness, courtesy, and respect.



# STANDARDS OF PRACTICE

## Exterior

This inspection is not intended to address or include any geological conditions or site stability information. For information concerning these conditions a geologist or soils engineer should be consulted. Any reference to grade is limited to only areas around the exterior of the exposed foundation or exterior walls. This inspection is visual in nature and does not attempt to determine drainage performance of the site or the condition of any underground piping, including municipal water and sewer service piping or septic systems.

When decks and porches are built close to the ground where no viewing or access is possible, we cannot make accurate opinions. These areas as well as others that are too low to enter, or in some other manner not accessible, are excluded from the inspection and are not addressed in this report. We routinely recommend that inquiry be made with the seller about knowledge of conditions, repairs are usually noted in the form seventeen.

Our inspection of the Exterior grounds includes the surface drainage, grading, some fencing, gates, sidewalks, patios, driveways, and retaining walls adjacent to the structure. The inspection of the exterior of the building includes the cladding, trim, eaves, fascias, decks, porches, downspouts, railings, doors, windows and flashings. Areas hidden from view by finished walls or stored items can not be judged and are not a part of this inspection. Minor cracks are typical in many foundations and most do not represent a structural problem. If major cracks are present along with rotation, we routinely recommend further evaluation be made by a qualified professional structural engineer. All exterior grades should allow for surface and roof water to flow away from the foundation. All concrete slabs experience some degree of cracking due to shrinkage in the drying process or minor settlement.

Where deck carpeting, stacked firewood, excessive vegetation, soil and other coverings are installed, the materials or their nature of construction and condition of the underneath cannot be determined. All items listed are inspected for their proper function, poor installation, excessive wear and general state of repair.

## Roof

The inspection of the roof system includes a visual examination of the surface materials, connections, penetrations and roof drainage systems. We examine the roofing material for damage and deterioration. We examine the roof system for possible leaks, damage and conditions that suggest limited remaining service life. We may offer opinions concerning repair and/or replacement if warranted. Opinions stated herein concerning the roofing material are based on the general condition of the roof system as evidence by our visual inspection.

These do not constitute a warranty that the roof is or will remain, free of leaks. All roofing systems require annual maintenance. Failure to perform routine maintenance will usually result in leaks and accelerated deterioration of the roof covering and flashings. When provided, our estimates of the roof's life expectancy are based on the assumption that the roof will be properly maintained during that period.

This report is issued in consideration a foregoing disclaimer in the future. The only way to determine whether a roof is absolutely water tight is to observe it during a prolonged rainfall. Many times, this situation is not present during the inspection and we cannot confirm this condition. We suggest that a annual inspection of the Attic area be performed where accessible to identify if any leaks are evident.

## Garage(s)

The Garage is inspected as best as possible, but can be limited due to parked cars or personal stored items. Due to this area be cluttered or areas being inaccessible, it is common for sections that cannot not be fully inspected or items identified during our limited inspection. We suggest that a walk-through be performed once the home is vacant. If this is a new construction inspection or vacant home this area will be inspected thoroughly. Determining the heat resistance rating of fire walls and doors is beyond the scope of this inspection. Flammable materials should not be stored within the Garage area if possible.

## Main Electrical Panel

Our examination of the electrical system includes a visual examination of the exposed and accessible branch circuits, wiring, service panel, over current protection devices, lighting fixtures, switches, and receptacles. Service equipment, proper grounding, wiring methods and bonding are focal points. We inspect for adverse conditions such as improper installation of aluminum wiring, lack of grounding and bonding, over-fusing, exposed wiring, open-air wire splices, reverse polarity and defective GFCI's. The hidden nature of the electrical wiring prevents inspection of every length of wire or their connections. Telephone, video, cable, audio, security systems and other low voltage systems were not included in this inspection unless specifically noted. We recommend you have the seller or a specialist demonstrate the serviceability or locations of these systems to you if necessary.

Any electrical repairs attempted by anyone other than a licensed electrician should be approached with caution. The power to the entire house should be turned off prior to beginning any repair efforts, no matter how trivial the repair may

seem. Aluminum wiring requires periodic inspection and maintenance by a licensed electrician. Operation of time clock motors is not verified. Inoperative light fixtures often lack bulbs or have dead bulbs installed. Light bulbs are not changed during the inspection, due to time constraints. Smoke Alarms should be installed within 15 feet of all Bedroom doors and in Bedrooms. These units should be tested monthly.

### **Electrical Sub Panel**

I. The inspector shall inspect: A. the service drop; B. the overhead service conductors and attachment point; C. the service head, gooseneck and drip loops; D. the service mast, service conduit and raceway; E. the electric meter and base; F. service-entrance conductors; G. the main service disconnect; H. panelboards and over-current protection devices (circuit breakers and fuses); I. service grounding and bonding; J. a representative number of switches, lighting fixtures and receptacles, including receptacles observed and deemed to be arc-fault circuit interrupter (AFCI)-protected using the AFCI test button, where possible; K. all ground-fault circuit interrupter receptacles and circuit breakers observed and deemed to be GFCIs using a GFCI tester, where possible; and L. smoke and carbon-monoxide detectors. II. The inspector shall describe: A. the main service disconnect's amperage rating, if labeled; and B. the type of wiring observed. III. The inspector shall report as in need of correction: A. deficiencies in the integrity of the service entrance conductors insulation, drip loop, and vertical clearances from grade and roofs; B. any unused circuit-breaker panel opening that was not filled; C. the presence of solid conductor aluminum branch-circuit wiring, if readily visible; D. any tested receptacle in which power was not present, polarity was incorrect, the cover was not in place, the GFCI devices were not properly installed or did not operate properly, evidence of arcing or excessive heat, and where the receptacle was not grounded or was not secured to the wall; and E. the absence of smoke detectors. IV. The inspector is not required to: A. insert any tool, probe or device into the main panelboard, sub-panels, distribution panelboards, or electrical fixtures. B. operate electrical systems that are shut down. C. remove panelboard cabinet covers or dead fronts. D. operate or re-set over-current protection devices or overload devices. E. operate or test smoke or carbon-monoxide detectors or alarms. F. inspect, operate or test any security, fire or alarms systems or components, or other warning or signaling systems. G. measure or determine the amperage or voltage of the main service equipment, if not visibly labeled. H. inspect ancillary wiring or remote-control devices. I. activate any electrical systems or branch circuits that are not energized. J. inspect low-voltage systems, electrical de-icing tapes, swimming pool wiring, or any timecontrolled devices. K. verify the service ground. L. inspect private or emergency electrical supply sources, including, but not limited to: generators, windmills, photovoltaic solar collectors, or battery or electrical storage facility. M. inspect spark or lightning arrestors. N. inspect or test de-icing equipment. O. conduct voltage-drop calculations. P. determine the accuracy of labeling. Q. inspect exterior lighting.

### **Heating System**

Our examination of the heating system includes a visual examination of the exposed and accessible heating equipment, thermostat, safety controls, venting and the means of air distribution. Our inspection of the heating system includes activating the heating system via the thermostat and a visual examination of the accessible components listed below.

These items are examined for proper function, excessive or unusual wear and general state of repair. Heat exchangers are inaccessible by design, and are not part of the Washington standards of practice. They must be completely removed from the furnace to be fully evaluated. Our inspection does not include disassembly of the furnace. The inspector cannot light pilot lights due to the liability. Safety devices are not tested by the inspector. To obtain maximum efficiency and reliability from your heating system, we recommend annual servicing and inspections by a qualified heating specialist.

Determining the condition of oil tanks, whether exposed or buried, is beyond the scope of this inspection. Leaking oil tanks represent an environmental hazard which is sometimes a costly condition to address.

### **Water Heater & Plumbing**

Our inspection of the water heater includes a visual examination of the accessible portions of the tank, gas, electrical and/or water connections, venting and safety valves. These items are examined for proper function, excessive or unusual wear, leakage and general state of repair.

Our Inspection of the plumbing system includes a visual examination of the exposed portions of the domestic water supply, drain waste, vent, gas lines, faucets, fixtures, valves, drains, traps, exposed pipes and fittings. These items are examined for proper function, excessive or unusual wear, leakage and general state of repair. The hidden nature of piping prevents inspection of every pipe and joint connection, especially in walls, floors and ceiling voids. A sewer lateral test is necessary to determine the condition of the underground sewer lines is beyond the scope of this inspection.

Our review of the plumbing system does not include landscape irrigation systems, water wells, on site and/or private water supply systems, off site community water supply systems, or private (septic) waste disposal systems unless specifically noted. Review of these systems could be performed by qualified specialists prior to closing of escrow.

### **Kitchen**

Inspection of the stand alone refrigerators, freezers and built-in ice makers are outside the scope of the inspection. No opinion is offered as to the adequacy of dishwasher operation. Ovens, self or continuous cleaning operations, cooking functions, clocks, timing devices, lights and thermostat accuracy are not tested during this inspection. Appliances are not moved during the inspection to inspect below or behind them. Portable dishwashers are not inspected, as they require connection to facilitate testing and are sometimes not left with the home.

### **Bathrooms**

Our inspection of the bathrooms included a visual examination of the readily accessible portions of the floors, walls, ceilings, cabinets, countertops and plumbing fixtures. Bathrooms are inspected for water drainage, damage, deterioration to floor and walls, proper function of components, active leakage, unusual wear and general state of repair. Bathroom fixtures are run simultaneously to check for adequate water flow and pressure. Fixtures are tested using normal operating controls. Vent fans and their duct work are tested for their proper operation and examined where visible.

Shower pans are visually checked for leakage, but leaks often do not show except when the shower is in actual use. Determining whether shower pans, tub/shower surrounds are water tight is beyond the scope of this inspection. It is very important to maintain all grouting and caulking in the bath areas. Very minor imperfections can allow water to get into the wall or floor areas and cause damage. Proper ongoing maintenance will be required in the future.

### **Interiors, Windows & Doors**

Our inspection of the Interior includes a visual inspection of the readily accessible portions of the walls, ceilings, floors, doors, cabinetry, countertops, steps, stairways, balconies and railings. Please note that a representative sample of the accessible windows and electrical receptacles are inspected. These features are examined for proper function, excessive wear and general state of repair. In some cases, all or portions of these components may not be visible because of furnishings and personal items. In these cases some of the items may not be inspected.

The condition of walls behind wall coverings, paneling and furnishings cannot be judged. Only the general condition of visible portions of floors is included in this inspection. As a general rule, cosmetic deficiencies are considered normal wear and tear and are not reported. Determining the source of odors or like conditions is not a part of this inspection. Floor covering damage or stains may be hidden by furniture. The condition of floors underlying floor coverings is not inspected. Determining the condition of insulated glass windows is not always possible due to temperature, weather and lighting conditions. Check with owners for further information. All fireplaces should be cleaned and inspected on a regular basis to make sure that no cracks have developed. Large fires in the firebox can overheat the firebox and flue liners, sometimes resulting in internal damage.

### **Attic**

Our inspection of the Attic includes a visual examination of the roof framing, plumbing, electrical and mechanical systems. There are often heating ducts, bathroom vent ducts, electrical wiring, chimneys and appliance vents in the Attic. We examined these systems and components for proper function, unusual wear and general state of repair, leakage, venting and unusual or improper improvements. When low clearances and deep insulation prohibits walking in an unfinished Attic, inspection will be from the access opening only. Vaulted ceilings cannot be inspected.

### **Crawlspace, Foundation, Structure & Basements**

Many of the dwellings structural elements and portions of it's mechanical systems are visible inside the Crawl Space. These include the foundation, portions of the structural framing, the distribution systems for electricity, plumbing and heating. Each accessible and visible component and system was examined for proper function, excessive wear or abnormal deterioration and general state of repair. It is not unusual to find occasional moisture and dampness in the Crawl Spaces and we advise annual inspections of this area.

Significant or frequent water accumulation can affect the structures foundation and support system and would indicate the need for further evaluation by professional drainage contractor. We advise to monitor your Crawl Space during the rainy season.