Insured/Applicant Name: Maikel Segui & San	dra Angel	Application	n / Policy #:	
Address Inspected: 7602 Marblehead Ln, Parkland, FL 33067				
	Maria, 1 2 00001	05/	15/0040	
Actual Year Built: 1996		Date Inspected: 05/	15/2019	
Minimum Photo Requirements ☑ Dwelling: Each side ☑ Roof: Each slope ☑ ☑ Main electrical service panel with interior doo ☑ Electrical box with panel off ☑ All hazards or deficiencies noted in this re	or label			
			obtained from the Florida licensed professional of e of the suitability, fitness or longevity of any of the	
Electrical System Separate documentation of any aluminum wiring r	remediation must be provid	ded and certified by a lice	ensed electrician.	
Main Panel Type: ☑ Circuit breaker ☐ Fuse Total Amps: 200 Is amperage sufficient for current usage? ☑ Yes	□ No (explain)	Second Panel Type: ☑ Circuit breake Total Amps: 200 Is amperage sufficient f	r □Fuse or current usage? ☑ Yes □No (explain)	
Indicate presence of any of the following:				
☐ Cloth wiring ☐ Active knob and tube ☐ Branch circuit aluminum wiring (If present, d * If single strand (aluminum branch) wiring, prov ☐ Connections repair via COPALUM crimp ☐ Connections repair via AlumniConn			tion of all work must be provided.	
Hazards Present Blowing fuses Tripping breakers Empty sockets Loose Wiring Improper grounding Corrosion Over fusing		□ Double taps □ Exposed wiring □ Unsafe wiring □ Improper breaker size □ Scoring □ Other (explain)		
General condition of the electrical system: ☑ Satisfactory ☐ Unsatisfactory (explain)				
Supplemental information				
Main Panel	Second Panel		Wiring Type	
Panel age: 1996	Panel age: 23		☑ Copper	
Year last updated: 23	Year last updated: 1996		☐ NM, BX or Conduit	

Brand/Model: Siemens

Brand/Model: Siemens

HVAC System				
Central AC: ☑ Yes ☐ No				
Central heat: ☑ Yes ☐ No				
If not central heat, indicate primary heat source and fuel type:				
Are the heating, ventilation and air conditioning systems in good working order? ☑ Yes ☐ No (explain)				
Date of last HVAC servicing/inspection:				
Hazards Present				
Wood burning stove or central gas fireplace <i>not professionally installed?</i> ☐ Yes ☑ No				
Space heater used as primary heat source? ☐ Yes ☑ No				
Is the source portable? ☐ Yes ☑ No				
Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area?				
Supplemental Information				
Age of system: 8				
Year last updated: 2017 (Places attack the bate(s) of LIV(S any inspect, including dated many featured plate)				
(Please attach photo(s) of HVAC equipment, including dated manufacturer's plate)				
Plumbing System				
Is there a temperature pressure relief valve on the water heater? ☑ Yes ☐ No				
Is there any indication of an active leak?				
Is there any indication of a prior leak? ☐ Yes ☑ No Water heater location:				
General condition of the following plumbing fixtures and connections to applicances:				
Satisfactory Unsatisfactory N/A Dishwasher ✓ □ □	Satisfactory Unsatisfactory N/A Toilets			
Dishwasher ☑ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐	Toilets Sinks □ □ □			
Washing Machine ☑ □	Sump pump □ ☑			
Water Heater □ □	Main shut off valve ☐ ☐			
Showers/Tubs	All other visible			
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).				
Supplemental Information				
Age of Piping System:	Type of pipes (check all that apply)			
Original to home	☑ Copper			
Completely re-piped	☑ PVC/CPVC			
X Partially re-piped				
New water heater in 2018				
	☐ Other (specify)			
	— Other (specify)			

Roof (With photos of each roof slope, this section can take the place of the <i>Roof Inspection Form.</i>)			
Predominant Roof Covering material: Concrete Tile Roof age (years): 23 Remaining useful life (years): 7 Date of last roofing permit: 1996-05-19 Date of last update: 1996-05-19 If updated (check one):	Secondary Roof Covering material: Modified Bitumen Roof age (years): 23 Remaining useful life (years): 7 Date of last roofing permit: 05/19/1996 Date of last update: If updated (check one):		
☐ Full Replacement ☐ Partial Replacement % of replacement	☐ Full Replacement ☐ Partial Replacement % of replacement		
Overall condition:	Overall condition:		
☐ Satisfactory ☑ Unsatisfactory (explain below)	☐ Satisfactory ☑ Unsatisfactory (explain below)		
Any visible signs of damage / deterioration? (check all that apply and explain below) Cracking Cupping/Curling Excessive granule loss Exposed asphalt Exposed felt Missing/loose/cracked tabs or tiles Soft spots in decking Visible hail damage Any visible signs of leaks Yes No Attic/underside of decking Yes No Interior ceilings Yes No Additional Comments/Observations (use additional pages)	Any visible signs of damage / deterioration? (check all that apply and explain below) Cracking Cupping/Curling Excessive granule loss Exposed asphalt Exposed felt Missing/loose/cracked tabs or tiles Soft spots in decking Visible hail damage Any visible signs of leaks Yes Mo Attic/underside of decking Yes No Interior ceilings Yes No		
All 4-Point Inspection Formsmust be completed and signed by a verifiable F			
I certify that the above statements are true and correct.			
ar- -	05/15/2019		
Inspector Signature Title	License Number Date		
Ohana Home Services Company Name License Type	7045796653 Work Phone		

Special Instructions: This sample *4-Point Inspection Form*includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

Photo Requirements

Photos must accompany each 4-Point Inspection Form. The minimum photo requirements include:

- · Dwelling: Each side
- Roof: Each slope
- · Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- · Open main electrical panel and interior door
- · Electrical box with the panel off
- Allhazards or deficiencies

Inspector Requirements

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. Examples include:

- · A general, residential, or building contractor
- · A building code inspector
- A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

Documenting the Condition of Each System

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

Additional Comments or Observations

This section of the 4-Point Inspection Formmust be completed with full details/descriptions if any of the following are noted on the inspection:

- Updates: Identify the types of updates, dates completed and by whom
- · Any visible hazards or deficiencies
- · Any system determined not to be in good working order

Note to All Agents

The writing agent must review each *4-Point Inspection Form* before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.


Photos, Additional Comments or Observations

Exterior Photos



Electrical System

Panel Photos




HVAC System



Plumbing System




Under cabinet plumbing & drains






Exposed Valves



RoofPhotos of Each Slope





Secondary Roof
Overall Condition
Ponding and soft spots