

#### TRUVIEW INSPECTIONS 305-908-3835 info@truviewinspections.com http://truviewinspections.com/



### 4 POINT INSPECTION (ONLY FOR PROPERTIES 25 YEARS OR OLDER)

#### 6210 Leonardo St Coral Gables FL 33146

Christopher Marotta SEPTEMBER 10, 2018



Inspector Luis Perez HI7112/MRSA2947/CRC1330244 305-908-3835 info@truviewinspections.com

# TABLE OF CONTENTS

1: 4 Point Inspection	3
2: Electrical	4
3: HVAC	5
4: Plumbing	6
5: Roof	7
6: Items Needing Repair or Comments	8
7: Inspector Information	9
8: Photos	10

### 1: 4 POINT INSPECTION

#### Information

#### **4 Point Overview**

This 4-Point Insurance Inspection is a direct replica of the most recent 01/18 Florida State Filed Citizens Property Insurance Corporation's 3-page, 4-Point Inspection form. All information contained herein contains the same level of detail to be acceptable to Citizens insurance, and most all other companies underwriting requirements. This form was created inside our inspection report writing software to aid in field data collection and completion, and to aid in any necessary revisions of forms in instances where issues are present and repaired and/or revisions would be necessary without completing an entirely new inspection. The purpose of a 4 point inspection is to verify certain features of a home's four major systems (roofing, plumbing, heating/cooling, and electrical). This 4 Point Inspection is conducted in accordance with the Florida Association of Building Inspectors (FABI) Standards of Practice for 4 Point Inspections, found on our website.

By acceptance and utilization of this report, both the Homeowner and the Insurance Agent, Agency, and Insurance Company agree to hold DG Inspekts harmless for the results of this report or the consequences of the report's findings, both now, and at any time in the future. The ratings, estimates, & life expectancies expressed on the report are professional opinions based upon observed conditions at time of inspection and understood known industry standards of those components. Life expectancies & ratings are not a guarantee or warranty and this report and its lifespans are wholly separate from any full building inspection report and its findings. A 4 Point Inspection is in no way to be utilized as a seller's disclosure or a substitute for a thorough, complete home inspection for purchase of real property. No warranty or guarantee of items inspected, or of insurance coverage or insurability, is expressed or implied by DG Inspekts.

# 2: ELECTRICAL

### Information

<b>Electrical: Electric System General</b> <b>Condition</b> Satisfactory	<b>Electrical: Main Panel Type</b> Circuit Breaker	<b>Electrical: Total Main Panel Amps</b> 200A
Electrical: Main Panel Amperage Sufficient for Current Usage? Yes	Electrical: Second Panel Type Circuit Breaker	Electrical: Second Panel Total Amps 125A
Electrical: Second Panel Amperage Sufficient for Current Usage Yes	Electrical: Indicate Presence Of Any Of The Following: N/A	Electrical: Main Panel Age In Years 2013
Electrical: Main Panel Year Last Updated 2013	Electrical: Main Panel Brand Siemens	Electrical: Second Panel Age In Years 2013
Electrical: Second Panel Year Last Updated 2013	<b>Electrical: Second Panel Brand</b> GE	Electrical: Wiring Type Copper

## 3: HVAC

### Information

No

HVAC: Central AC Yes	<b>HVAC: Central Heat</b> Yes	HVAC: HVAC System in Good Working Order: Yes
HVAC: Date of Last HVAC Servicing 2015	HVAC: Age of System In Years 2015	HVAC: Year Last Updated 2015
Hazards Present: Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area? No	No	Hazards Present: Space Heater Used As Primary Heat Source No
Hazards Present: Wood Burning Stove or Central Gas Fireplace Not Professionally Installed		

# 4: PLUMBING

### Information

Plumbing: Temperature Pressure Relief Valve on the Water Heater? Yes	0	Plumbing: Water Heater Indication of a Prior Leak? No
Plumbing: Water Heater Location Garage	: Plumbing: Water Heater Year of Manufacture: 2004	Plumbing: Types of Plumbing Noted Copper
Plumbing: Age Of Piping System Completely Re-Piped	General Condition of the Following Plumbing Fixtures and Connections to Appliances: Dishwasher Satisfactory	General Condition of the Following Plumbing Fixtures and Connections to Appliances: Refrigerator Satisfactory
General Condition of the Following Plumbing Fixtures and Connections to Appliances: Washing Machine Satisfactory	General Condition of the Following Plumbing Fixtures and Connections to Appliances: Water Heater Satisfactory	
General Condition of the Following Plumbing Fixtures and Connections to Appliances: Toilets Satisfactory	General Condition of the Following Plumbing Fixtures and Connections to Appliances: Sinks Satisfactory	General Condition of the Following Plumbing Fixtures and Connections to Appliances: Sump Pump N/A
General Condition of the Following Plumbing Fixtures and Connections to Appliances: Main Shut Off Valve Satisfactory	General Condition of the Following Plumbing Fixtures and Connections to Appliances: All Other Visible Satisfactory	

### 5: ROOF

### Information

Predominant Roof: Roof Age In Years 2013 Predominant Roof: Date of Last Permit 05/13/2014 Predominant Roof: Date of Last Update 05/13/2014

# 6: ITEMS NEEDING REPAIR OR COMMENTS

## 7: INSPECTOR INFORMATION

### Information

Inspector Information: Date of	Inspector Information: Company	Inspector Information: Office
Inspection	Name	Phone
9/10/2018	Truview Inspections	954-406-0096

#### **Inspector Information: Inspector Luis Perez**

Florida State Certified Residential Contractor License # CRC1330244 Florida Home Inspector License # HI7112

# 8: PHOTOS

### Information

#### Photos: 4 Point Photos



















6210 Leonardo St



